

Multi-Point Inspection Checklist

RO# 6034705

Customer Name INVENTORY: 1289531

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 11/26/2025 10:31 AM

Printed on 12/5/2025

Did your Service Advisor review the results of this multi-point inspection checklist with you?

Checked and OK at this time May Require Future Attention Requires immediate attention

Maintenance Service

- | | | | |
|-------------------------------------|-------------------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cold Engine start-up |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine operation warm-up |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine at normal operating temperature |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Brake and parking operation <u>fb 9mm rb 8mm</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Active seat belt test |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Clutch and transmission operations |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Overdrive operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Transfer case operation (4-wheel drive only) |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Steering operation and off center |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Front end alignment |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tilt steering wheel operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Windshield wiper and washer operation at all speeds, wiper blade condition |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Speedometer and odometer operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cruise Control operation, including resume |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Heater and air condition operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Abnormal noises and vibrations |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Squeaks and rattles |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Frame Check |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Body surface, lower body, and upper body damage requiring body shop repair |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Tire defects and damage, 5/32 <u>ft 5/32 rt 4/32</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive shaft, joints, CV's and boots |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Struts/shock absorbers, leaks and wear |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Exhaust system leaks and damage, including catalytic converter |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Fuel, oil, coolant, or other fluid leaks |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Perform emissions test and/or state inspection if required |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood labels and decals |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Air filter and In -Cabin Air Filter equipped <u>Found the cabin and engine air filter to be dirty</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Battery cables and mount |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Coolant level and test |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood fluid levels, including transmission and transfer case fluids |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive belts and hoses |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Air conditioning levels, check at sight glass |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Warning lights (including air bag) gauges & horn |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Inside and outside rearview mirror operation, adjustment, and condition |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Glass free of cracks, starts and large chips |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Dome , courtesy, map and sun visor lights and lighters and power ports |

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2022	TOYOTA	RAV4 PRIME
Vehicle Identification Number	Color	
JTMEB3FV7ND104277	MAGNETIC G	

INVENTORY: 1289531

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95	169.95	I
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 00279-BLK16-01 : GTMO 0W16 BK SP WTY 5@8.10 40.50 90915-YZZN1 : FILTER, OIL 1@8.66 8.66 Changed the engine oil and filter.	73.70 40.50 8.66	I
#3 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 10.00 87139-OR030 : ELEMENT, AIR REFINER 1@41.20 41.20 Replaced the cabin air filter.	10.00 41.20	I
#4 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 10.00 17801-YZZ16 : ELEMENT SUB-ASSY, AI 1@31.50 31.50 Replaced the engine air filter.	10.00 31.50	I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	263.65				
PARTS	121.86				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	415.50				



This report provided free of charge by:

Deery Brothers
 200 S Gear Ave
 West Burlington, IA 52655
 319-271-8758

★ **4.6 / 5.0**
 144 Verified Reviews

♥ **102**
 Customer Favorites



Vehicle History Report™

US \$44.99

2022 TOYOTA RAV4 PRIME XSE

VIN: JTMEB3FV7ND104277
 4 DOOR WAGON/SPORT
 UTILITY
 2.5L I4 F DOHC 16V
 HYBRID
 ALL WHEEL DRIVE

This CARFAX Report Provided
 by:

Deery Brothers

★ **4.6 / 5.0**
 144 Verified Reviews
 ♥ **102** Customer Favorites

✓ No accidents or damage reported to CARFAX

🔧 **6** Service history records

1 CARFAX 1-Owner vehicle

🏠 Personal vehicle

🌍 Last owned in Iowa

📊 **101,502** Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 11/29/25 at 9:41:10 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	11/28/2025
🛞 Tires	✓ Tires rotated	08/21/2025

This car has been recently serviced. That's a good thing!

 Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX. View Toyota disclosure	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

 Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

 Ownership History The number of owners is estimated	Owner 1
Year purchased	2022
Type of owner	Personal
Estimated length of ownership	3 years
Owned in the following states/provinces	Iowa
Estimated miles driven per year	32,694/yr
Last reported odometer reading	101,502





Detailed History



Owner 1

Purchased: 2022

Personal Vehicle

32,694 mi/yr

Date	Mileage	Source	Comments
09/20/2022		NICB	Vehicle manufactured and shipped to original dealer
10/24/2022	4	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 144 Verified Reviews ❤️ 102 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed - Oil and filter changed
11/01/2022		Iowa Motor Vehicle Dept. Danville, IA	Titled or registered as personal vehicle
11/04/2022	15	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 144 Verified Reviews ❤️ 102 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed - Vehicle washed/detailed
11/28/2022		Iowa Motor Vehicle Dept. Danville, IA	Title or registration issued - First owner reported - Vehicle color noted as Gray
01/10/2023	5,647	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 144 Verified Reviews ❤️ 102 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tires rotated
02/02/2024		Iowa Motor Vehicle Dept. Danville, IA	Registration issued or renewed - Vehicle color noted as Gray
12/23/2024		Iowa Motor Vehicle Dept. Danville, IA	Registration issued or renewed - Vehicle color noted as Gray

05/27/2025 82,450 Deery Brothers
West Burlington, IA
319-752-6000
deerybrothers.com/
★ 4.6 / 5.0
144 Verified Reviews
❤️ 102 Customer Favorites

**Vehicle serviced**

- Maintenance inspection completed
- 5,000 mile service performed
- Air filter replaced
- Oil and filter changed
- Tires rotated

08/21/2025 92,543 Deery Brothers
West Burlington, IA
319-752-6000
deerybrothers.com/
★ 4.6 / 5.0
144 Verified Reviews
❤️ 102 Customer Favorites

**Vehicle serviced**

- Maintenance inspection completed
- 5,000 mile service performed
- Air filter replaced
- Oil and filter changed
- Tires rotated

09/18/2025 Toyota Motor Sales, USA,
Inc.

Manufacturer Service Campaign issued

- Campaign #25TD01 25TD01 REAR TRACTION MOTOR CABLE CORROSION - MULTIPLE MODEL & MODEL YEAR TOYOTA HYBRID (AWD) VEHICLES
- Status: Remedy Available
- Campaign expiration date: 09/11/2028

Locate an authorized Toyota dealer near you to schedule an appointment

🔍 **Learn more about this campaign**

Description: The subject vehicles are equipped with a rear motor unit and an HV Floor Under Wire that provide high voltage to operate the motor. Mud, water, or road salt could potentially enter the HV Floor Underwire connector housing and could cause corrosion over time. Excessive corrosion could cause AM Radio Static during certain driving cycles, or the vehicle may not start.

Remedy: Any authorized Toyota dealer will apply a wire harness protector seal to the HV Floor Under Wire Connector.

11/26/2025 100,411 Deery Brothers
West Burlington, IA
319-752-6000
deerybrothers.com/
★ 4.6 / 5.0
144 Verified Reviews
❤️ 102 Customer Favorites

Vehicle offered for sale

11/28/2025 101,502 Deery Brothers
West Burlington, IA
319-752-6000
deerybrothers.com/
★ 4.6 / 5.0

**Vehicle serviced**

- Maintenance inspection completed
- Air filter replaced
- Cabin air filter replaced/cleaned
- Oil and filter changed