

Multi-Point Inspection Checklist

RO# 6036792

Customer Name INVENTORY: 969000

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 2/6/2026 12:35 PM

Printed on 2/6/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

-  Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-   Cold Engine start-up
-   Engine operation warm-up
-   Engine at normal operating temperature
-   Brake and parking operation **fb 9mm rb 8mm**
-   Active seat belt test
-   Clutch and transmission operations
-   Overdrive operation
-   Transfer case operation (4-wheel drive only)
-   Steering operation and off center
-   Front end alignment
-   Tilt steering wheel operation
-   Windshield wiper and washer operation at all speeds, wiper blade condition
-   Speedometer and odometer operation
-   Cruise Control operation, including resume
-   Heater and air condition operation
-   Abnormal noises and vibrations
-   Squeaks and rattles
-   Frame Check
-   Body surface, lower body, and upper body damage requiring body shop repair
-   Tire defects and damage, 5/32 **ft 6/32 rt 6/32**
-   Drive shaft, joints, CV's and boots


-   Struts/shock absorbers, leaks and wear
-   Exhaust system leaks and damage, including catalytic converter
-   Fuel, oil, coolant, or other fluid leaks
-   Perform emissions test and/or state inspection if required
-   Under hood labels and decals
-    Air filter and In-Cabin Air Filter equipped **Found the engine air filter to be dirty**
-   Battery cables and mount

-   Coolant level and test
-   Under hood fluid levels, including transmission and transfer case fluids
-   Drive belts and hoses
-   Air conditioning levels, check at sight glass
-   Warning lights (including air bag) gauges & horn
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-   Inside and outside rearview mirror operation, adjustment, and condition
-   Glass free of cracks, starts and large chips
-   Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician	Date
Service Manager 	Date 2-6-26
Used Car Manager 	Date 2-6-26
Customer	Date

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
GT AWD	23989	23989
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2025	DODGE	DURANGO
Vehicle Identification Number		Color
1C4RDJDG3SC531512		BLUE

INVENTORY: 969000

#1 - 4: 56 POINT INSPECTION
Corrected by 4: 56 POINT INSPECTION LRATE:169.95
Work performed by Tech 329/9 1.00hrs @ 169.95 169.95
Performed a 56 point inspection.


#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL
ALL FLUID LEVELS
Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE
CHASSIS FILL ALL FLUID LEVELS LRATE:184.25
Work performed by Tech 329/9 0.40hrs @ 184.25 73.70
19420060 : N-OIL (08800-BOPCK) 6@8.10 48.60
R94010 : OIL FILTER 1@10.43 10.43

#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING
CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT
INCLUDE REPLACEMENT OF DAMAGED OR RUSTED
COMPONENTS AND OR PART REPLACEMENT .
Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE .
INCLUDES SETTING CASTER AND CAMBER AND TOE IF
ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF
DAMAGED OR RUSTED COMPONENTS AND OR PART
REPLACEMENT . LRATE:.00
Work performed by Tech 329/9 * 1.50hrs 159.95

#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE
Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE
LRATE:.00
Work performed by Tech 329/9 * 0.90hrs 59.95

#5 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER
REPLACEMENT
Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00
Work performed by Tech 329/9 * 0.10hrs 10.00
PA6116 : AIR FILTER 1@29.95 29.95

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	473.55				
PARTS	88.98				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	592.52				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
151 Verified Reviews

♥ **101**
Customer Favorites



Vehicle History Report™

US \$44.99

2025 DODGE DURANGO GT

VIN: 1C4RDJDG3SC531512
4 DOOR WAGON/SPORT
UTILITY
3.6L V6 F DOHC 24V
GASOLINE
ALL WHEEL DRIVE
Original Window Sticker
This CARFAX Report Provided
by:


Deery Brothers

★ 4.6 / 5.0

151 Verified Reviews

♥ 101 Customer Favorites

Accident reported: minor damage



CARFAX 1-Owner vehicle



Rental vehicle



Last owned in Illinois



23,989 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/10/26 at 5:27:34 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Accident / Damage History


Not all accidents / issues are reported to CARFAX

Event 1

06/17/2025

Accident reported: minor damage

Damage Severity Scale



 Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage Accident reported: 06/17/2025.	Minor Damage
Manufacturer Recall No open recalls reported to CARFAX.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have 25 months or 12,011 miles remaining. Confirm with dealer or vehicle manufacturer.	<input checked="" type="checkbox"/> Warranty Active

 Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
[View Terms](#) | [View Certificate](#)

 Ownership History The number of owners is estimated	Owner 1
Year purchased	2025
Type of owner	Rental
Estimated length of ownership	11 months
Owned in the following states/provinces	Illinois
Estimated miles driven per year	25,905/yr



Last reported odometer reading	23,989
--------------------------------	--------

CARFAX Detailed History

 **Owner 1** Rental Vehicle
 Purchased: 2025 25,905 mi/yr

Date	Mileage	Source	Comments
Not Reported		FCA US LLC	Original Window Sticker 
03/06/2025		Illinois Motor Vehicle Dept.	Vehicle purchase reported - Titled or registered as rental vehicle
03/31/2025	10	Illinois Motor Vehicle Dept. Normal, IL	Title issued or updated - Registration issued or renewed - First owner reported - Loan or lien reported - Vehicle color noted as Blue
05/17/2025		Illinois Motor Vehicle Dept. Normal, IL	Registration issued or renewed
06/17/2025		Damage Report	 Accident reported: minor damage - Damage to right front

Damage Severity Scale



MINOR
MODERATE
SEVERE





Minor damage is usually cosmetic, including dents or scratches to the vehicle body.

02/07/2026	23,989	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/  4.6 / 5.0 151 Verified Reviews	Vehicle offered for sale
------------	--------	---	---------------------------------