

Multi-Point Inspection Checklist

RO# 6034239

Customer Name INVENTORY: 968050

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 11/13/2025 8:29 AM

Printed on 11/13/2025

Did your Service Advisor review the results of this multi-point inspection checklist with you?

- Checked and OK at this time
- May Require Future Attention
- Requires immediate attention

Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation need front rotors and rear rotors fb 9mm rb 8mm ④
- Active seat belt test 499.48 439.28
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 ft 4/32 rt 4/32
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emmisions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In -Cabin Air Filter equipped Found the cabin and engine air filter to be dirty.
- Battery cables and mount
- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips
- Dome , courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician

Date

Service Manager

Date

11-14-25

Used Car Manager

Date

Customer

Date

REPAIR ORDER - AUDIT			Work Phone	R/O Open Date	R/O Number
DEERY BROTHERS 200 S Gear Ave West Burlington, IA 52655				11/13/25	6034239/1
			Home Phone	R/O Close Date	Receipt No
				11/20/25	Original
			Body	Mileage In	Mileage Out
	SEL AWD	25195	25195		
YEAR	MAKE	Model	License Number	Service Advisor	
2022	FORD	ESCAPE		JAKE BACHTTELL 8435	
Vehicle Identification Number		Color	Account No	Delivery Date	In-Service Date
1FMCU9H99NUA69385		WHITE			

INVENTORY: 968050

#1 - MR 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION Work by Tech 329/1329 1.00hrs @ 169.95 Performed a 56 point inspection.		I	169.95	26.00
#2 - MR 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FI ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Work by Tech 329/1329 0.40hrs @ 184.25 19419537 : N-OIL (08800-BOPCKT) 6@7.20 R85348 : FILTER 1@9.68 Changed the engine oil and filter.	LL	I	73.70 43.20 9.68	10.40 40.80 3.99
#3 - MR ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTE COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Work by Tech 329/1329* 1.50hrs Performed a 4 wheel alignment.	D	I	159.95	39.00
#4 - MR GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTAT Work by Tech 329/1329* 0.90hrs Balanced all four wheels and tires.	E	I	59.95	23.40
#5 * MR ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER Work by Tech 329/1329* 0.10hrs PC99542P : CABIN FILTER 1@49.95 Replaced the cabin air filter.		I	10.00 49.95	2.60 19.42

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

			Work Phone	R/O Open Date	R/O Number
				11/13/25	6034239/2
			Home Phone	R/O Close Date	Receipt No
				11/20/25	Original
			Body	Mileage In	Mileage Out
			SEL AWD	25195	25195
YEAR	MAKE	Model	License Number	Service Advisor	
2022	FORD	ESCAPE		JAKE BACHTELL	8435
Vehicle Identification Number		Color	Account No	Delivery Date	In-Service Date
1FMCU9H99NUA69385		WHITE			

INVENTORY: 968050

#6 * MR AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Corrected by AF: REPLACED ENGINE AIR FILTER Work by Tech 329/1329* 0.10hrs PA99541 : AIR FILTER 1@29.95 Replaced the engine air filter.	I	10.00 29.95	2.60 12.59
#7 * MR ROTORS: RESURFACED FRONT OR REAR ROTORS Corrected by ROTORS: RESURFACED FRONT OR REAR ROTORS Work by Tech 329/1329* 1.80hrs BR901800-01 : FRT ROTORS 2@110.74 Replaced the rear brake pads and rotors.	I	82.00 221.48	46.80 105.42
#8 * MR ROTORS: RESURFACED FRONT OR REAR ROTORS Corrected by ROTORS: RESURFACED FRONT OR REAR ROTORS Work by Tech 329/1329* 1.80hrs BR901816 : REAR ROTORS 2@75.64 CMK : BRAKE SERVICE KIT 1@17.95 PS1833B : REAR PADS 1@68.00 Replaced the front brake rotors.	I	82.00 151.28 17.95 68.00	46.80 68.40 10.95 29.97

Account	Description	Control	Re	ference	Amount
46350	SLS-SRV-INTERNAL LABOR - OTHE	6034239		6034239	-647.55
24700	INV-WORK IN PROCESS SERVICE	921329		6034239	-197.60
66350	CST-SRV-INTERNAL LABOR - OTHE	6034239		6034239	197.60
48100	SLS-PTS-INTERNAL RO - GM	6034239		6034239	-17.95
68100	CST-PTS-INTERNAL RO - GM	6034239		6034239	10.95
24200	INVENTORY-PTS/ACC-GM	6034239		6034239	-10.95
48100	SLS-PTS-INTERNAL RO - GM	6034239		6034239	-520.66
68100	CST-PTS-INTERNAL RO - GM	6034239		6034239	235.80
24200	INVENTORY-PTS/ACC-GM	6034239		6034239	-235.80
48100	SLS-PTS-INTERNAL RO - GM	6034239		6034239	-9.68
68100	CST-PTS-INTERNAL RO - GM	6034239		6034239	3.99
24200	INVENTORY-PTS/ACC-GM	6034239		6034239	-3.99
49100	SLS-PTS-GAS OIL & GREASE	6034239		6034239	-43.20
69100	CST-PTS-GAS OIL & GREASE	6034239		6034239	40.80

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT			Work Phone	R/O Open Date	R/O Number
DEERY BROTHERS 200 S Gear Ave West Burlington, IA 52655				11/13/25	6034239/3
			Home Phone	R/O Close Date	Receipt No
				11/20/25	Original
			Body	Mileage In	Mileage Out
			SEL AWD	25195	25195
			License Number	Service Advisor	
				JAKE BACHTELL	8435
YEAR	MAKE	Model	Account No	Delivery Date	In-Service Date
2022	FORD	ESCAPE			
Vehicle Identification Number		Color			
1FMCU9H99NUA69385		WHITE			

INVENTORY: 968050

24200	INVENTORY-PTS/ACC-GM	6034239	6034239	-40.80
66900	CST-SRV-MECH SHOP SUPPLIES	6034239	6034239	-29.99
24100	INVENTORY - USED TRUCKS	968050	6034239	1269.03

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER	COST
LABOR	647.55				197.60
PARTS	591.49				291.54
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	1269.03				489.14



This report provided free of charge by:

Deery Brothers
 200 S Gear Ave
 West Burlington, IA 52655
 319-271-8758

★ **4.6 / 5.0**
 144 Verified Reviews

♥ **102**
 Customer Favorites



Vehicle History Report™

US \$44.99

2022 FORD ESCAPE SEL

VIN: 1FMCU9H99NUA69385
 4 DOOR WAGON/SPORT UTILITY
 2.0L I4 F DOHC 16V GASOLINE
 FRONT WHEEL DRIVE W/ 4X4
 Original Window Sticker
 This CARFAX Report Provided by:

Deery Brothers
 ★ 4.6 / 5.0
 144 Verified Reviews
 ♥ 102 Customer Favorites

✓ No accidents or damage reported to CARFAX

🔧 5 Service history records

📄 At least 1 open recall

👥 3 Previous owners

🌍 Last owned in Ohio

📊 25,195 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 11/20/25 at 6:22:40 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Additional History Not all accidents / issues are reported to CARFAX	Owner 1	Owner 2	Owner 3
Total Loss No total loss reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported
Structural Damage No structural damage reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported
Odometer Check No indication of an odometer rollback.	✓ No Issues Indicated	✓ No Issues Indicated	✓ No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported

Manufacturer Recall	At least 1 manufacturer recall requires service. Locate an authorized Ford or Lincoln Mercury dealer or call 866-436-7332 to obtain more information about this recall.	✔ No Recalls Reported	✔ No Recalls Reported	Recall Reported
Basic Warranty	Original warranty estimated to have expired.	Warranty Expired	Warranty Expired	Warranty Expired

CARFAX Title History	Title History		
CARFAX guarantees the information in this section	Owner 1	Owner 2	Owner 3
Damage Brands	✔ Guaranteed No Problem	✔ Guaranteed No Problem	✔ Guaranteed No Problem
Salvage Junk Rebuilt Fire Flood Hail Lemon			
Odometer Brands	✔ Guaranteed No Problem	✔ Guaranteed No Problem	✔ Guaranteed No Problem
Not Actual Mileage Exceeds Mechanical Limits			



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

CARFAX Ownership History	Ownership History		
The number of owners is estimated	Owner 1	Owner 2	Owner 3
Year purchased	2022	2025	2025
Type of owner	---	---	---
Estimated length of ownership	3 yrs. 1 mo.	1 month	25 days
Owned in the following states/provinces	Quebec	Quebec	Ohio
Estimated miles driven per year	7,737/yr	---	---
Last reported odometer reading	16,322	24,715	25,195

CARFAX Detailed History



Owner 1
Purchased: 2022



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

7,737 mi/yr

Date	Mileage	Source	Comments
------	---------	--------	----------