

Multi-Point Inspection Checklist

RO# 6036210

Customer Name INVENTORY: 968331

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 1/19/2026 3:53 PM

Printed on 1/20/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?



Checked and OK at this time



May Require Future Attention



Requires immediate attention

Maintenance Service

-  Cold Engine start-up Pass
-  Engine operation warm-up Pass
-  Engine at normal operating temperature Pass
-  Brake and parking operation Pass
-  Active seat belt test Pass
-  Clutch and transmission operations Pass
-  Overdrive operation Pass
-  Transfer case operation (4-wheel drive only) Pass
-  Steering operation and off center Pass
-  Front end alignment Pass
-  Tilt steering wheel operation Pass
-  Windshield wiper and washer operation at all speeds, wiper blade condition Pass
-  Speedometer and odometer operation Pass
-  Cruise Control operation, including resume Pass
-  Heater and air condition operation Pass
-  Abnormal noises and vibrations Pass
-  Squeaks and rattles Pass
-  Frame Check Pass
-  Body surface, lower body, and upper body damage requiring body shop repair Pass
-  Tire defects and damage, 5/32 10/32 all
-  Drive shaft, joints, CV's and boots Pass
-  Struts/shock absorbers, leaks and wear Pass
-  Exhaust system leaks and damage, including catalytic converter Pass
-  Fuel, oil, coolant, or other fluid leaks Pass
-  Perform emissions test and/or state inspection if required Pass
-  Under hood labels and decals Pass
-  Air filter and In -Cabin Air Filter equipped Pass
-  Battery cables and mount Pass
-  Coolant level and test Pass
-  Under hood fluid levels, including transmission and transfer case fluids Pass
-  Drive belts and hoses Pass
-  Air conditioning levels, check at sight glass Pass
-  Warning lights (including air bag) gauges & horn Pass
-  Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-  Inside and outside rearview mirror operation, adjustment, and condition Pass
-  Glass free of cracks, starts and large chips Pass
-  Dome , courtesy, map and sun visor lights and lighters and power ports Pass

- Window operation Pass
- Sunroof or convertible top operation Pass
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance Pass
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness Pass
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL Pass
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____



Service Manager *[Signature]* _____ Date 1.19.26

Used Car Manager _____ Date _____

Customer _____ Date _____



Ford : Bronco : 2024 : Badlands : with Sasquatch Package (LT315/70R17 (35") Tire, Beadlock Capable Wheel, Raised Suspension) ExpressAlign Total Alignment



• One or more values are not within specification. Tire wear, handling and safety problems may result.

REPAIR ORDER - AUDIT			Work Phone	R/O Open Date	R/O Number
DEERY BROTHERS 200 S Gear Ave West Burlington, IA 52655			Home Phone	01/19/26	6036210/1
			Body	R/O Close Date	Receipt No
			SUV	01/21/26	Original
			License Number	Mileage In	Mileage Out
				28117	28117
YEAR	MAKE	Model	Service Advisor		
2024	FORD	BRONCO	AMANDA KEPHART 1403		
Vehicle Identification Number		Color	Account No	Delivery Date	In-Service Date
1FMEE9BP5RLA24551					

INVENTORY: 968331

#1 - QL 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FI ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Work by Tech 256/756 0.40hrs @ 184.25 19419537 : N-OIL (08800-BOPCKT) 7@7.25 PO8154 : OIL FILTER 1@11.54 new oil and filter	LL	I	73.70 50.75 11.54	11.20 29.82 5.96
#2 - QL 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION Work by Tech 256/756 1.00hrs @ 169.95 inspection complete		I	169.95	28.00
#3 - QL GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTAT Work by Tech 256/756 * 0.90hrs 4 tires balanced and rotated	E	I	59.95	25.20
#4 - QL ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTE COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Work by Tech 256/756 * 1.50hrs alignment complete	D	I	159.95	42.00
Account Description Control Re ference Amount				
46150 SLS-SRV-QUICKLANE LABOR-OTHER 6036210			6036210	-463.55
24700 INV-WORK IN PROCESS SERVICE 217756			6036210	-106.40
66150 CST-SRV-QUICKLANE-LABOR-OTHER 6036210			6036210	106.40
46750 SLS-PTS-CUSTOMER MECH RO-OTHE 6036210			6036210	-11.54
66750 CST-PTS-CUSTOMER MECH RO-OTHE 6036210			6036210	5.96

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT			Work Phone	R/O Open Date	R/O Number
DEERY BROTHERS 200 S Gear Ave West Burlington, IA 52655				01/19/26	6036210/2
			Home Phone	R/O Close Date	Receipt No
				01/21/26	Original
			Body	Mileage In	Mileage Out
YEAR	MAKE	Model	License Number	Service Advisor	
2024	FORD	BRONCO		AMANDA KEPHART 1403	
Vehicle Identification Number		Color	Account No	Delivery Date	In-Service Date
1FMEE9BP6RLA24551					

INVENTORY: 968331

24230	INVENTORY-PTS/ACCESS-OTHER	6036210	6036210	-5.96
49100	SLS-PTS-GAS OIL & GREASE	6036210	6036210	-50.75
69100	CST-PTS-GAS OIL & GREASE	6036210	6036210	29.82
24200	INVENTORY-PTS/ACC-GM	6036210	6036210	-29.82
66900	CST-SRV-MECH SHOP SUPPLIES	6036210	6036210	-29.99
24100	INVENTORY - USED TRUCKS	968331	6036210	555.83

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER	COST
LABOR	463.55				106.40
PARTS	62.29				35.78
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	555.83				142.18



This report provided free of charge by:

Deery Brothers

200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
149 Verified Reviews

♥ **102**
Customer Favorites



Vehicle History Report™

US \$44.99

**2024 FORD BRONCO
BADLANDS**

VIN: 1FMEE9BP5RLA24551
4 DOOR WAGON/SPORT
UTILITY
2.7L V6
GASOLINE
REAR WHEEL DRIVE W/ 4X4
Original Window Sticker
This CARFAX Report Provided
by:

Deery Brothers

★ **4.6 / 5.0**
149 Verified Reviews
♥ **102** Customer Favorites

✓ No accidents or damage reported to CARFAX

🔧 **4** Service history records

📄 At least 1 open recall

1 CARFAX 1-Owner vehicle

🏠 Personal vehicle

📊 **26,115** Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 1/21/26 at 5:27:05 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	12/12/2025
🌀 Tires	✓ Tires rotated	06/25/2025
 <div style="border: 1px solid blue; padding: 10px; display: inline-block;"> This car has been recently serviced. That's a good thing! </div>		

 Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires service. Locate an authorized Ford or Lincoln Mercury dealer or call 866-436-7332 to obtain more information about this recall.	Recall Reported
Basic Warranty Original warranty estimated to have 15 months or 9,885 miles remaining. Confirm with dealer or vehicle manufacturer.	<input checked="" type="checkbox"/> Warranty Active

 Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

 Ownership History The number of owners is estimated	Owner 1
Year purchased	2024
Type of owner	Personal
Estimated length of ownership	1 yr. 8 mo.
Owned in the following states/provinces	Iowa
Estimated miles driven per year	14,464/yr

