

Multi-Point Inspection Checklist

RO# 6036122

Customer Name INVENTORY: 968930

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 1/15/2026 2:39 PM

Printed on 1/15/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?


 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-   Cold Engine start-up Pass
-   Engine operation warm-up Pass
-   Engine at normal operating temperature Pass
-   Brake and parking operation Pass
-   Active seat belt test Pass
-   Clutch and transmission operations Pass
-   Overdrive operation Pass
-   Transfer case operation (4-wheel drive only) Pass
-   Steering operation and off center Pass
-   Front end alignment Pass
-   Tilt steering wheel operation Pass
-   Windshield wiper and washer operation at all speeds, wiper blade condition Pass
-   Speedometer and odometer operation Pass
-   Cruise Control operation, including resume Pass
-   Heater and air condition operation Pass
-   Abnormal noises and vibrations Pass
-   Squeaks and rattles Pass
-   Frame Check Pass
-   Body surface, lower body, and upper body damage requiring body shop repair Pass
-   Tire defects and damage, 5/32 6/32 all
-   Drive shaft, joints, CV's and boots Pass
-   Struts/shock absorbers, leaks and wear Pass
-   Exhaust system leaks and damage, including catalytic converter Pass
-   Fuel, oil, coolant, or other fluid leaks Pass
-   Perform emmisions test and/or state inspection if required Pass
-   Under hood labels and decals Pass
-    Air filter and In-Cabin Air Filter equipped Fail air and cabin
-   Battery cables and mount Pass
-   Coolant level and test Pass
-   Under hood fluid levels, including transmission and transfer case fluids Pass
-   Drive belts and hoses Pass
-   Air conditioning levels, check at sight glass Pass
-   Warning lights (including air bag) gauges & horn Pass
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-   Inside and outside rearview mirror operation, adjustment, and condition Pass
-   Glass free of cracks, starts and large chips Pass
-   Dome , courtesy, map and sun visor lights and lighters and power ports Pass

- Window operation Pass
- Sunroof or convertible top operation Pass
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance Pass
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness Pass
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL Pass
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager  _____ Date 1-15-26

Used Car Manager _____ Date _____



Customer _____ Date _____



1G1ZD5ST8PF222625

Odometer:64914

Chevrolet : Malibu (Including Classic, Limited) : 2023 : except RPO QQI, LKN ExpressAlign Total Alignment



• One or more values are not within specification. Tire wear, handling and safety problems may result.

REPAIR ORDER - AUDIT COPY			Work Phone	R/O Open Date	R/O Number
DEERY BROTHERS 200 S Gear Ave West Burlington, IA 52655			Home Phone	1/15/26	6036122/1
			Body	R/O Close Date	Receipt No.
			4DR SDN 1LT	1/16/26	Original
			License Number	Mileage In	Mileage Out
				64714	64714
Year	Make	Model	Service Advisor		
2023	CHEVROLET	MALIBU	AMANDA KEPHART		
Vehicle Identification Number		Color	Account No.	Delivery Date	In-Service Date
1G1ZD5ST8PF222625		GRAY			

INVENTORY: 968930

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 256/ 0.40hrs @ 184.25 73.70 19420080 : N-OIL (08800-BOPCK) 4@8.82 35.28 25206966 : SL-N-FILTER (01836-BCKT) 1@10.49 10.49 new oil and filter	I
#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 256/ 1.00hrs @ 169.95 169.95 inspection complete	I
#3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 256/ * 0.90hrs 59.95 balanced and rotated 4 tires psi 36	I
#4 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 256/ * 1.50hrs 159.95	I
#5 * ICF: REPLACED IN CABIN AIR FILTER Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 256/ * 0.10hrs 10.00 23430312 : SL-N-ELEMENT (03410-BC) 1@49.95 49.95	I
#6 * AF: REPLACED ENGINE AIR FILTER	I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
 200 S Gear Ave
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
	1/15/26	6036122/2
Home Phone	R/O Close Date	Receipt No.
	1/16/26	Original
Body	Mileage In	Mileage Out
4DR SDN 1LT	64714	64714
License Number	Service Advisor	
	AMANDA KEPHART	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2023	CHEVROLET	MALIBU
Vehicle Identification Number		Color
1G1ZD5ST8PF222625		GRAY

INVENTORY: 968930

Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00
 Work performed by Tech 256/ * 0.10hrs 10.00
 19338054 : SL-N-FILTER (09786-BOPCKT) 1@29.95 29.95
 filter installed

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	483.55				
PARTS	125.67				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	639.21				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
148 Verified Reviews

♥ **102**
Customer Favorites



Vehicle History Report™

US \$44.99

2023 CHEVROLET MALIBU LT

VIN: 1G1ZD5ST8PF222625
SEDAN 4 DR
1.5L I4
GASOLINE
FRONT WHEEL DRIVE
Original Window Sticker

This CARFAX Report Provided by:

Deery Brothers

★ **4.6 / 5.0**

148 Verified Reviews

♥ **102** Customer Favorites

✓ No accidents or damage reported to CARFAX

✂ 2 Service history records

1 CARFAX 1-Owner vehicle

🚗 Rental vehicle

🌍 Last owned in Idaho

📊 64,714 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 1/17/26 at 10:21:46 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	01/16/2026
 <div style="border: 1px solid #00aaff; padding: 5px; display: inline-block;"> <p>This car has been recently serviced. That's a good thing!</p> </div>		

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

 Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

 Ownership History The number of owners is estimated	Owner 1
Year purchased	2023
Type of owner	Rental
Estimated length of ownership	2 yrs. 6 mo.
Owned in the following states/provinces	Idaho
Estimated miles driven per year	24,479/yr
Last reported odometer reading	64,714

