

Multi-Point Inspection Checklist

RO# 6032666

Customer Name INVENTORY 739241A

Advisor Name Jim Smith

Technician Name JACOB BLAKEMAN

Created on 9/24/2025 2:37 PM

Printed on 9/24/2025

Did your Service Advisor review the results of this multi-point inspection checklist with you?

☐ Checked and OK at this time ☐ May Require Future Attention ☐ Requires immediate attention

Maintenance Service

☐ Cold Engine start-up

☐ Engine operation warm-up

☐ Engine at normal operating temperature

☐ Brake and parking operation db 8mm rb 9mm

☐ Active seat belt test

☐ Clutch and transmission operations

☐ Overdrive operation

☐ Transfer case operation (4-wheel drive only)

☐ Steering operation and off center

☐ Front end alignment

☐ Tilt steering wheel operation

☐ Windshield wiper and washer operation at all speeds, wiper blade condition

☐ Speedometer and odometer operation

☐ Cruise Control operation, including resume

☐ Heater and air condition operation

☐ Abnormal noises and vibrations

☐ Squeaks and rattles

☐ Frame Check

☐ Body surface, lower body, and upper body damage requiring body shop repair

☐ Tire defects and damage, 5/32 ft 6/32 rt 6/32

☐ Drive shaft, joints, CV's and boots

☐ Struts/shock absorbers, leaks and wear

☐ Exhaust system leaks and damage, including catalytic converter

☐ Fuel, oil, coolant, or other fluid leaks

☐ Perform emissions test and/or state inspection if required

☐ Under hood labels and decals

☐ Air filter and In-Cabin Air Filter equipped Found the engine air filter to be dirty

☐ Battery cables and mount

☐ Coolant level and test

☐ Under hood fluid levels, including transmission and transfer case fluids

☐ Drive belts and hoses

☐ Air conditioning levels, check at sight glass

☐ Warning lights (including air bag) gauges & horn

☐ Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light

☐ Inside and outside rearview mirror operation, adjustment, and condition

- ☒ Glass free of cracks, starts and large chips
- ☒ Dome , courtesy, map and sun visor lights and lighters and power ports
- ☒ Window operation
- ☒ Sunroof or convertible top operation
- ☒ Audio system and clock (set if required)
- ☒ Factory -installed alarm system functional
- ☒ Cigarette lighter operation, replace element if used
- ☒ Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- ☒ Truck bed, bed liner, tailgate, rear bumper
- ☒ Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position
- ☒ Seats and seat belt operation for every position
- ☒ Rear defogger, check with test lights
- ☒ Headlight aim
- ☒ Trunk light and trunk trim appearance
- ☒ Hood, trunk, and fuel filler door latch
- ☒ Spare tire pressure, jack and tire wrench match vehicle and work properly
- ☒ Wheel covers and caps
- ☒ Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- ☒ Differential oil level
- ☒ Engine oil and filter changed using genuine replacement parts
- ☒ CHECK AND COMPLETE ALL OPEN RECALL
- ☒ OTHER
- ☒ Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- ☒ With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- ☒ Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- ☒ Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- ☒ Customer Acknowledgement:

Technician

Date

Service Manager

Date

Used Car Manager

Date

Customer

Date

REPAIR ORDER - AUDIT COPY


DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

| | | | | | |
|-------------------------------|-----------|---------------|----------------|-----------------|-----------------|
| Year | Make | Model | Work Phone | R/O Open Date | R/O Number |
| 2018 | CHEVROLET | SILVERADO 250 | Home Phone | 9/24/25 | 6032666/1 |
| Vehicle Identification Number | Color | Account No. | Body | R/O Close Date | Receipt No. |
| 1GC1KVEG3JF159949 | WHITE | | TRUCK | 9/25/25 | Original |
| | | | License Number | Mileage In | Mileage Out |
| | | | | 56900 | 56900 |
| | | | | Service Advisor | |
| | | | | JAKE BACHTELL | |
| | | | | Delivery Date | In-Service Date |
| | | | | 2/23/18 | 2/23/18 |

INVENTORY: 739241A

| | | | |
|---|-------------------------|---|--|
| #1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION Work performed by Tech 329/9 1.00hrs @ 169.95 | 169.95 | I | |
| #2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Work performed by Tech 329/9 0.40hrs @ 184.25 19419537 : N-OIL (08800-BOPCKT) 6@7.10 12735811 : SL-N-FILTER (01836-BOPCKT) 1@13.60 | 73.70 42.60 13.60 | I | |
| #3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Work performed by Tech 329/9 * 1.50hrs | 159.95 | I | |
| #4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Work performed by Tech 329/9 * 0.90hrs | 59.95 | I | |
| #5 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Corrected by AF: REPLACED ENGINE AIR FILTER Work performed by Tech 329/9 * 0.10hrs 23349854 : SL-N-ELEMENT (03410-CT) 1@29.95 | 10.00 29.95 | I | |

| | INTERNAL | SERVICE CONT. | WARRANTY | CUSTOMER PAY | COST |
|-----------------------|----------|---------------|----------|--------------|------|
| LABOR | 473.55 | | | | |
| PARTS | 86.15 | | | | |
| DEDUCTIBLE | | | | | |
| SUBLET | | | | | |
| SHOP SUPPLIES | 29.99 | | | | |
| HAZARDOUS MATERIALS | | | | | |
| SALES TAX OR TAX I.D. | | | | | |
| SPECIAL ORDER DEPOSIT | | | | | |
| DISCOUNTS | | | | | |
| | 589.69 | | | | |




This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
143 Verified Reviews

♥ **102**
Customer Favorites





Vehicle History Report™

US \$44.99

2018 CHEVROLET SILVERADO 2500HD LT
VIN: 1GC1KVEG3JF159949
CREW PICKUP
6.0L V8 F OHV 16V
FLEX FUEL
REAR WHEEL DRIVE W/ 4X4


This CARFAX Report Provided by:
Deery Brothers
★ **4.6 / 5.0**
143 Verified Reviews
♥ **102** Customer Favorites


Damage reported: minor damage




9 Service history records


1 CARFAX 1-Owner vehicle

 Personal vehicle

 **56,900** Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 9/29/25 at 7:00:45 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Accident / Damage History


Not all accidents / issues are reported to CARFAX

Event 1

10/16/2024

Damage reported: minor damage

Damage Severity Scale






MINOR MODERATE SEVERE



Recent Service Highlights

Key services performed in the last 12 months

| Service | Comments | Date |
|--|--------------------------|------------|
|  Oil | ✓ Oil and filter changed | 09/25/2025 |
|  Tires | ✓ Tires rotated | 09/25/2025 |
| <div><div>This car has been recently serviced. That's a good thing!</div></div> | | |



Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss

No total loss reported to CARFAX.



No Issues Reported

Structural Damage

CARFAX recommends that you have this vehicle inspected by a collision repair specialist.



No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.



No Issues Reported

Odometer Check

No indication of an odometer rollback.



No Issues Indicated

Accident / Damage

Damage reported: 10/16/2024.

Minor Damage

Manufacturer Recall

No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.



No Recalls Reported

Basic Warranty

Original warranty estimated to have expired.

Warranty Expired



Title History

CARFAX guarantees the information in this section

Owner 1

Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon



Guaranteed No Problem

Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits



Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
View Terms | View Certificate



Ownership History

The number of owners is estimated

Owner 1

| | |
|---|--------------|
| Year purchased | 2018 |
| Type of owner | Personal |
| Estimated length of ownership | 7 yrs. 7 mo. |
| Owned in the following states/provinces | Iowa |
| Estimated miles driven per year | 7,441/yr |
| Last reported odometer reading | 56,900 |



Detailed History



Owner 1


Purchased: 2018



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
7,441 mi/yr

| Date | Mileage | Source | Comments |
|------------|---------|--|--|
| 11/01/2017 | | Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 143 Verified Reviews ❤️ 102 Customer Favorites | Vehicle offered for sale |
| 01/20/2018 | 21 | Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 143 Verified Reviews ❤️ 102 Customer Favorites | Vehicle serviced - Pre-delivery inspection completed - Oil and filter changed |
| 02/01/2018 | | Iowa Motor Vehicle Dept. Burlington, IA | Titled or registered as personal vehicle |

| | | | |
|------------|--------|--|---|
| 02/23/2018 | | Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 143 Verified Reviews ❤️ 102 Customer Favorites | Vehicle sold |
| 02/28/2018 | 130 | Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 143 Verified Reviews ❤️ 102 Customer Favorites |  Vehicle serviced - Vehicle washed/detailed |
| 03/12/2018 | | Iowa Motor Vehicle Dept. Burlington, IA | Title or registration issued - First owner reported - Vehicle color noted as White |
| 06/07/2018 | | Iowa Motor Vehicle Dept. Burlington, IA | Registration issued or renewed - Vehicle color noted as White |
| 06/27/2019 | | Iowa Motor Vehicle Dept. Burlington, IA | Registration issued or renewed - Vehicle color noted as White |
| 07/13/2020 | | Iowa Motor Vehicle Dept. Burlington, IA | Registration issued or renewed - Vehicle color noted as White |
| 07/29/2020 | 12,600 | Roberts Tire Center Corporation Burlington, IA 319-753-6586 robertstirecenter.com/ ★ 4.9 / 5.0 90 Verified Reviews ❤️ 50 Customer Favorites |  Vehicle serviced - Tire repaired |
| 10/21/2020 | 13,993 | Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com ★ 4.6 / 5.0 143 Verified Reviews ❤️ 102 Customer Favorites |  Vehicle serviced - Maintenance inspection completed - Brakes checked - Oil and filter changed |
| 06/25/2021 | | Iowa Motor Vehicle Dept. Burlington, IA | Registration issued or renewed - Vehicle color noted as White |