

Multi-Point Inspection Checklist

RO# 6036150

Customer Name INVENTORY: 968601

Advisor Name JAKE BACHTTELL

Technician Name JACOB BLAKEMAN

Created on 1/16/2026 1:03 PM

Printed on 1/26/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

-  Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-   Cold Engine start-up
-   Engine operation warm-up
-   Engine at normal operating temperature
-   Brake and parking operation fb 9mm rb 8mm
-   Active seat belt test
-   Clutch and transmission operations
-   Overdrive operation
-   Transfer case operation (4-wheel drive only)
-   Steering operation and off center
-   Front end alignment
-   Tilt steering wheel operation
-   Windshield wiper and washer operation at all speeds, wiper blade condition
-   Speedometer and odometer operation
-   Cruise Control operation, including resume
-   Heater and air condition operation
-   Abnormal noises and vibrations
-   Squeaks and rattles
-   Frame Check
-   Body surface, lower body, and upper body damage requiring body shop repair
-   Tire defects and damage, 5/32 ft 12/32 rt 11/32
-   Drive shaft, joints, CV's and boots
-   Struts/shock absorbers, leaks and wear
-   Exhaust system leaks and damage, including catalytic converter
-   Fuel, oil, coolant, or other fluid leaks
-   Perform emissions test and/or state inspection if required
-   Under hood labels and decals
-    Air filter and In-Cabin Air Filter equipped Found the cabin and engine air filter to be dirty
-   Battery cables and mount
-   Coolant level and test
-   Under hood fluid levels, including transmission and transfer case fluids
-   Drive belts and hoses
-   Air conditioning levels, check at sight glass
-   Warning lights (including air bag) gauges & horn
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-   Inside and outside rearview mirror operation, adjustment, and condition
-   Glass free of cracks, starts and large chips
- Dome , courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Year	Make	Model
2020	CHEVROLET	COLORADO
Vehicle Identification Number		Color
1GCGTDEN2L1185426		RED

Work Phone	R/O Open Date	R/O Number
	1/16/26	6036150/1
Home Phone	R/O Close Date	Receipt No.
	1/20/26	Original
Body	Mileage In	Mileage Out
TRUCK	54648	54648
License Number	Service Advisor	
	JAKE BACHTELL	
Account No.	Delivery Date	In-Service Date
	9/17/24	

INVENTORY: 968601

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 Performed a 56 point inspection.		I					
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 19324430 : SL-N-FILTER KIT (01836-BOPCKT) 1@17.02 17.02 19419537 : N-OIL (08800-BOPCKT) 6@7.25 43.50 Changed the engine oil and filter.		I					
#3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs 59.95 Performed a 4 wheel alignment.		I					
#4 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95 Performed a 4 wheel alignment.		I					
#5 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 10.00 19338059 : SL-N-FILTER (09786-BOPCKT) 1@29.95 29.95		I					

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
 200 S Gear Ave
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
	1/16/26	6036150/2
Home Phone	R/O Close Date	Receipt No.
	1/20/26	Original
Body	Mileage In	Mileage Out
TRUCK	54648	54648
License Number	Service Advisor	
	JAKE BACHTTELL	
Account No.	Delivery Date	In-Service Date
	9/17/24	

Year	Make	Model
2020	CHEVROLET	COLORADO
Vehicle Identification Number		Color
1GCGTDEN2L1185426		RED

INVENTORY: 968601

Replaced the engine air filter.

#6 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER
 REPLACEMENT

Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00

Work performed by Tech 329/9 * 0.10hrs 10.00

94775933 : SL-N-ELEMENT (03410-CT) 1@49.95 49.95

Replaced the engine air filter.

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	483.55				
PARTS	140.42				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	653.96				



This report provided free of charge by:

Deery Brothers
 200 S Gear Ave
 West Burlington, IA 52655
 319-271-8758

★ **4.6 / 5.0**
 149 Verified Reviews

♥ **102**
 Customer Favorites



Vehicle History Report™

US \$44.99

2020 CHEVROLET COLORADO Z71

VIN: 1GCGTDEN2L1185426
 CREW PICKUP
 3.6L V6 F DOHC 24V
 GASOLINE
 REAR WHEEL DRIVE W/ 4X4
 Original Window Sticker

This CARFAX Report Provided by:

Deery Brothers

★ **4.6 / 5.0**

149 Verified Reviews

♥ **102** Customer Favorites

✓ No accidents or damage reported to CARFAX

🔧 **18** Service history records

1 CARFAX 1-Owner vehicle

🏠 Personal vehicle

🌍 Last owned in Iowa

📊 **54,648** Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 1/21/26 at 5:37:15 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	01/20/2026
🛞 Tires	✓ Alignment performed	03/18/2025
	✓ Four tires replaced	
	✓ Four wheel alignment performed	
	✓ Tire(s) replaced	
💧 Flushes ⓘ	✓ Transmission fluid flushed	01/12/2026





This car has been recently serviced. That's a good thing!

 Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

 Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
[View Terms](#) | [View Certificate](#)

 Ownership History The number of owners is estimated	Owner 1
Year purchased	2020
Type of owner	Personal





Estimated length of ownership	5 yrs. 8 mo.
Owned in the following states/provinces	Nevada, Iowa
Estimated miles driven per year	9,516/yr
Last reported odometer reading	54,648

CARFAX Detailed History



Owner 1
Purchased: 2020



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
9,516 mi/yr

Date	Mileage	Source	Comments
Not Reported		General Motors	Original Window Sticker
02/04/2020		Dealer Inventory	Vehicle offered for sale
02/07/2020	5	Team Chevrolet Las Vegas, NV 702-948-8484 teamchevroletlv.com/ ★ 4.2 / 5.0 768 Verified Reviews ❤️ 8,796 Customer Favorites	Vehicle serviced - Pre-delivery inspection completed - Bed liner installed - Door edge guards installed - Pinstripe(s) installed
04/11/2020		Team Chevrolet Las Vegas, NV 702-948-8484 teamchevroletlv.com/ ★ 4.2 / 5.0 768 Verified Reviews ❤️ 8,796 Customer Favorites	Vehicle serviced - Vehicle washed/detailed
04/11/2020	8	Service Plan Co. North Las Vegas, NV	Service contract issued
04/22/2020		Nevada Motor Vehicle Dept. North Las Vegas, NV	Registration issued or renewed - Titled or registered as personal vehicle