

Multi-Point Inspection Checklist

RO# 6034606

Customer Name INVENTORY: 968290

Advisor Name JAKE BACHTELL

Technician Name Moore Alicia

Created on 11/24/2025 12:37 PM

Printed on 12/5/2025

Did your Service Advisor review the results of this multi-point inspection checklist with you?

Checked and OK at this time May Require Future Attention Requires immediate attention

Maintenance Service

- | | | | |
|-------------------------------------|--------------------------|--------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cold Engine start-up |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine operation warm-up |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine at normal operating temperature |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Brake and parking operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Active seat belt test |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Clutch and transmission operations |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Overdrive operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Transfer case operation (4-wheel drive only) |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Steering operation and off center |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Front end alignment |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tilt steering wheel operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Windshield wiper and washer operation at all speeds, wiper blade condition |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Speedometer and odometer operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cruise Control operation, including resume |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Heater and air condition operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Abnormal noises and vibrations |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Squeaks and rattles |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Frame Check |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Body surface, lower body, and upper body damage requiring body shop repair |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tire defects and damage, 5/32 <u>both lh 6/32 both rh 5/32</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive shaft, joints, CV's and boots |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Struts/shock absorbers, leaks and wear |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Exhaust system leaks and damage, including catalytic converter |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Fuel, oil, coolant, or other fluid leaks |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Perform emissions test and/or state inspection if required |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood labels and decals |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Air filter and In-Cabin Air Filter equipped |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Battery cables and mount |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Coolant level and test |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood fluid levels, including transmission and transfer case fluids |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive belts and hoses |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Air conditioning levels, check at sight glass |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Warning lights (including air bag) gauges & horn |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Inside and outside rearview mirror operation, adjustment, and condition |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Glass free of cracks, starts and large chips |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Dome , courtesy, map and sun visor lights and lighters and power ports |

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness front 9mm rear 8mm
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2022	CHEVROLET	SILVERADO 150
Vehicle Identification Number		Color
1GCPDKKXNZ621094		BLACK

11/24/25	6034606/1
11/25/25	Original
36077	36077
JAKE BACHTTELL	

INVENTORY: 968290

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 853/ 1.00hrs @ 169.95	169.95	I
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 853/ 0.40hrs @ 184.25 73.70 19432357 : N-OIL (08800-BOPCK) 6@8.22 49.32 12735608 : SL-N-FILTER (01836-BCKT) 1@8.00 8.00	73.70 49.32 8.00	I
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 853/ * 1.50hrs 159.95	159.95	I
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 853/ * 0.90hrs 59.95	59.95	I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	463.55				
PARTS	57.32				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	550.86				



This report provided free of charge by:

Deery Brothers
 200 S Gear Ave
 West Burlington, IA 52655
 319-271-8758

★ **4.6 / 5.0**
 144 Verified Reviews

♥ **102**
 Customer Favorites




Vehicle History Report™

US \$44.99

2022 CHEVROLET SILVERADO 1500 LT
 VIN: 1GCPDKEKXNZ621094
 CREW PICKUP
 2.7L I4 F DOHC 16V
 GASOLINE
 REAR WHEEL DRIVE W/ 4X4
 Original Window Sticker
 This CARFAX Report Provided by:
Deery Brothers
 ★ 4.6 / 5.0
 144 Verified Reviews
 ♥ 102 Customer Favorites

-  No accidents or damage reported to CARFAX
-  Regular oil changes
-  Good Reliability
-  CARFAX 1-Owner vehicle
-  Personal lease vehicle
-  **36,077** Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 11/26/25 at 5:54:28 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
 Oil	✓ Oil and filter changed	11/25/2025
 Tires	✓ Tires rotated	05/27/2025



This car has been recently serviced. That's a good thing!



Reliability Forecast

https://www.carfax.com/vehiclehistory/ar20/sMOFif11-IQm_PPMHaGeNedCSOj_W9s_rJYvXObJsQOBK7Q_CIDjEbUgp-0J2r7wo2PIZ7HcQZMyX7...
1/7

Based on 2022 Chevrolet Silverado 1500 LT with similar mileage

3-Year Reliability Forecast



Good news! This vehicle is expected to have average risk of repair and average repair costs.



What makes this vehicle have good reliability?

- \$\$\$ **Average Repair Cost**
\$350 avg per year
- Oil Changes** performed regularly
- Average Likelihood of Repair**

Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
View Terms | View Certificate

CARFAX Ownership History		Owner 1
The number of owners is estimated		
Year purchased		2022
Type of owner		Personal lease
Estimated length of ownership		2 yrs. 11 mo.
Owned in the following states/provinces		Michigan
Estimated miles driven per year		11,863/yr
Last reported odometer reading		36,077

CARFAX Detailed History			
	Owner 1 Purchased: 2022		<div style="border: 1px solid blue; padding: 5px;"> <p>Low mileage! This owner drove less than the industry average of 15,000 miles per year.</p> </div> <div style="text-align: right;"> <p>Personal Lease Vehicle 11,863 mi/yr</p> </div>
Date	Mileage	Source	Comments
Not Reported		General Motors	<p>Original Window Sticker</p>
09/12/2022		<p>Cook Chevrolet Buick Vassar, MI 989-299-7901 cookchevybuick.com</p> <p>★ 4.7 / 5.0 516 Verified Reviews ❤️ 5,388 Customer Favorites</p>	Vehicle offered for sale
09/13/2022	6	<p>Cook Chevrolet Buick Vassar, MI 989-299-7901 cookchevybuick.com</p> <p>★ 4.7 / 5.0</p>	<p> Vehicle serviced</p> <ul style="list-style-type: none"> - Pre-delivery inspection completed - Brake fluid flushed/changed - Fluids checked - Transmission fluid changed

516 Verified Reviews
 **5,388** Customer Favorites

11/11/2022	Michigan Motor Vehicle Dept. Columbiaville, MI	Vehicle purchase reported - Registration issued or renewed - Titled or registered as personal lease vehicle - Loan or lien reported
11/11/2022	Michigan Motor Vehicle Dept. Columbiaville, MI	Title issued or updated - First owner reported
12/28/2022	Michigan Motor Vehicle Dept. Columbiaville, MI	Registration issued or renewed
06/27/2023 6,446	Hank Graff Chevrolet - Davison Davison, MI 810-653-4111 hankgraffdavison.com/  4.7 / 5.0 920 Verified Reviews  10,426 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Tire(s) balanced
07/11/2023 7,117	Hank Graff Chevrolet - Davison Davison, MI 810-653-4111 hankgraffdavison.com/  4.7 / 5.0 920 Verified Reviews  10,426 Customer Favorites	 Vehicle serviced - Oil and filter changed - Tires rotated
01/18/2024	Michigan Motor Vehicle Dept. Columbiaville, MI	Registration issued or renewed
03/05/2024 14,414	Hank Graff Chevrolet - Davison Davison, MI 810-653-4111 hankgraffdavison.com/  4.7 / 5.0 920 Verified Reviews  10,426 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Fluids checked - Oil and filter changed - Tire condition and pressure checked
09/26/2024 21,678	Hank Graff Chevrolet - Davison Davison, MI 810-653-4111	 Vehicle serviced - Fluids checked - Oil and filter changed - Tire condition and pressure checked