

# Multi-Point Inspection Checklist

RO# 6037024

Customer Name INVENTORY: 969020

Advisor Name JAKE BACHTELL

Technician Name Dylan Miller

Created on 2/13/2026 4:57 PM

Printed on 3/3/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

- |                                     |                                     |                          |  |
|-------------------------------------|-------------------------------------|--------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Cold Engine start-up   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Engine operation warm-up   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Engine at normal operating temperature   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Brake and parking operation  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Active seat belt test  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Clutch and transmission operations   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Overdrive operation  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Transfer case operation (4-wheel drive only)   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Steering operation and off center  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Front end alignment  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Tilt steering wheel operation  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Windshield wiper and washer operation at all speeds, wiper blade condition   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Speedometer and odometer operation   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Cruise Control operation, including resume   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Heater and air condition operation   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Abnormal noises and vibrations   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Squeaks and rattles  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Frame Check  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Body surface, lower body, and upper body damage requiring body shop repair   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Tire defects and damage, 5/32  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | <del>Drive shaft, joints, CV's and boots</del>   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Struts/shock absorbers, leaks and wear   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Exhaust system leaks and damage, including catalytic converter   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Fuel, oil, coolant, or other fluid leaks   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Perform emissions test and/or state inspection if required   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Under hood labels and decals   |
| <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Air filter and In-Cabin Air Filter equipped <u>engine air filter and cabin filter are dirty</u>  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Battery cables and mount   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Coolant level and test   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Under hood fluid levels, including transmission and transfer case fluids   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Drive belts and hoses  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Air conditioning levels, check at sight glass  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Warning lights (including air bag) gauges & horn   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Inside and outside rearview mirror operation, adjustment, and condition  |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Glass free of cracks, starts and large chips   |
| <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> | Dome, courtesy, map and sun visor lights and lighters and power ports  |

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position
  
- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly missing tire tool kit
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER missing owners manual
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
  
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

\_\_\_\_\_  
 Technician Date

\_\_\_\_\_  
 Service Manager Date

\_\_\_\_\_  
 Used Car Manager Date

\_\_\_\_\_  
 Customer Date

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone			R/O Open Date	R/O Number
Home Phone			2/13/26	6037024/1
Body			R/O Close Date	Receipt No.
4WD CREW CAB			2/27/26	Original
License Number			Mileage In	Mileage Out
			26418	26418
Year	Make	Model	Service Advisor	
2025	CHEVROLET	COLORADO	JAKE BACHTELL	
Vehicle Identification Number		Color	Account No.	Delivery Date
1GCPTBEK1S1123363		WHITE		

INVENTORY: 969020

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 461/4 1.00hrs @ 169.95 169.95 87844382 : N-TOOL KIT (08821-CT) 1@152.78 152.78 performed 56 point inspection	I	
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 461/4 0.40hrs @ 184.25 73.70 19432357 : N-OIL (08800-BOPCK) 6@8.25 49.50 12735608 : SL-N-FILTER (01836-BCKT) 1@8.00 8.00 changed engine oil and filter	I	
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 461/4 * 1.50hrs 159.95 performed alignment. front toe was out of specs. set front toe and test drove. wheel was straight and vehicle drove straight	I	
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 461/4 * 0.90hrs 99.00 balanced and rotated all four wheels	I	
#6 - 0999: MISCELLANEOUS REPAIR - MAINTENANCE ITEMS c/s to order front emblem	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
	2/13/26	6037024/2
Home Phone	R/O Close Date	Receipt No.
	2/27/26	Original
Body	Mileage In	Mileage Out
4WD CREW CAB	26418	26418
License Number	Service Advisor	
	JAKE BACHTELL	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2025	CHEVROLET	COLORADO
Vehicle Identification Number		Color
1GCPTBEK1S1123363		WHITE

INVENTORY: 969020

Corrected by 0999: MISCELLANEOUS REPAIR - MAINTENANCE ITEMS LRATE:191.98 Work performed by Tech 461/4                      0.50hrs @ 191.98                      95.99 84701878 : N-EMBLEM (01303-CT)                      1@76.51                      76.51 installed front chevy emblem				
----- #7 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00 Work performed by Tech 461/4 *    0.10hrs                      12.00 84848112 : SL-N-ELEMENT (03410-CT)                      1@29.95                      29.95 installed new air filter			I	
----- #8 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 461/4 *    0.10hrs                      12.00 19338054 : SL-N-FILTER (09786-BOPCKT)                      1@49.95                      49.95 installed new cabin filter			I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	622.59				
PARTS	366.69				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	1019.27				



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

♥ **101**

Customer Favorites



## Vehicle History Report™

US \$44.99

### 2025 CHEVROLET COLORADO WORK TRUCK

VIN: 1GCPTBEK1S1123363  
CREW PICKUP  
2.7L I4 F DOHC 16V  
GASOLINE  
REAR WHEEL DRIVE W/ 4X4  
Original Window Sticker

This CARFAX Report Provided by:  
**Deery Brothers**  
♥ 101 Customer Favorites

✓ No accidents or damage reported to CARFAX

✂ 2 Service history records

1 CARFAX 1-Owner vehicle

🚚 Commercial vehicle

🌍 Last owned in Texas

📊 26,418 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/28/26 at 12:08:15 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



### Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	02/27/2026
 <div style="border: 1px solid #00a0e3; padding: 5px; display: inline-block;"> <p>This car has been recently serviced. That's a good thing!</p> </div>		



### Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

<b>Total Loss</b> No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Structural Damage</b> No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Manufacturer Recall</b> No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have 25 months or 9,582 miles remaining. Confirm with dealer or vehicle manufacturer.	<input checked="" type="checkbox"/> Warranty Active

 <b>Title History</b> CARFAX guarantees the information in this section	<b>Owner 1</b>
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
 <b>GUARANTEED</b> - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. <a href="#">View Terms</a>   <a href="#">View Certificate</a>	

 <b>Ownership History</b> The number of owners is estimated	<b>Owner 1</b>
Year purchased	2025
Type of owner	Commercial
Estimated length of ownership	10 months
Owned in the following states/provinces	Texas
Estimated miles driven per year	29,212/yr
Last reported odometer reading	26,418

