

Multi-Point Inspection Checklist

RO# 6039964

Did your Service Advisor review the results of this multi-point inspection checklist with you?

Customer Name INVENTORY: 969191

Advisor Name TERRY STOTTS

Technician Name Dalton Berry

Created on 5/19/2026 7:43 AM

Printed on 6/2/2026

Checked and OK at this time May Require Future Attention Requires immediate attention

Maintenance Service

- | | | | |
|-------------------------------------|--------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cold Engine start-up <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine operation warm-up <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine at normal operating temperature <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Brake and parking operation <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Active seat belt test <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Clutch and transmission operations <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Overdrive operation <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Transfer case operation (4-wheel drive only) <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Steering operation and off center <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Front end alignment <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tilt steering wheel operation <u>Pass</u> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Windshield wiper and washer operation at all speeds, wiper blade condition <u>Fail wipers</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Speedometer and odometer operation <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cruise Control operation, including resume <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Heater and air condition operation <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Abnormal noises and vibrations <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Squeaks and rattles <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Frame Check <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Body surface, lower body, and upper body damage requiring body shop repair <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tire defects and damage, 5/32 <u>6/32 all</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive shaft, joints, CV's and boots <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Struts/shock absorbers, leaks and wear <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Exhaust system leaks and damage, including catalytic converter <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Fuel, oil, coolant, or other fluid leaks <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Perform emissions test and/or state inspection if required <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood labels and decals <u>Pass</u> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Air filter and In -Cabin Air Filter equipped <u>Fail air filter</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Battery cables and mount <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Coolant level and test <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood fluid levels, including transmission and transfer case fluids <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive belts and hoses <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Air conditioning levels, check at sight glass <u>Pass</u> |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Warning lights (including air bag) gauges & horn <u>Fail tpms light</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Inside and outside rearview mirror operation, adjustment, and condition <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Glass free of cracks, starts and large chips <u>Pass</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Dome , courtesy, map and sun visor lights and lighters and power ports <u>Pass</u> |

- Window operation Pass
- Sunroof or convertible top operation Pass
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance Pass
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 6mm front 8mm rear
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL Pass
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
SUV	143271	143271
License Number	Service Advisor	
	AMANDA KEPHART	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2017	GMC	YUKON
Vehicle Identification Number		Color
1GKS2BKC0HR157688		RED

INVENTORY: 969191

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:195.58 Work performed by Tech 256/ 0.40hrs @ 195.57 78.23 19432337 : N-OIL (08800-BOPCK) 3@9.60 28.80 19432337 : N-OIL (08800-BOPCK) 5@9.60 48.00 19363567 : SL-N-FILTER (01836-BOPCKT) 1@6.95 6.95 new oil and filter installed	I	
#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:178.95 Work performed by Tech 256/ 1.00hrs @ 178.95 178.95 inspection complete	I	
#3 - BATTERY: CHARGE OR REPLACE BATTERY Corrected by BATTERY: CHARGE OR REPLACE BATTERY LRATE:.00 Work performed by Tech 256/ * 0.60hrs 39.95 battery tested good	I	
#4 * TPMS3: REPLACE 3 TPMS SENSORS Corrected by TPMS3: REPLACE 3 TPMS SENSORS LRATE:.00 Work performed by Tech 256/ * 1.50hrs 90.00 13540601 : SL-N-SENSOR (05890-BCKT) 3@100.64 301.92 3 tpms sensors replaced light is off	I	
#5 * BLADE: REPLACED WIPER BLADES Corrected by BLADE: REPLACED WIPER BLADES LRATE:.00 Work performed by Tech 256/ * 0.10hrs 10.00 19388171 : SL-N-BLADE (10146-BOPCKT) 2@22.95 45.90 wipers installed	I	
#6 * AF: REPLACED ENGINE AIR FILTER Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00 Work performed by Tech 256/ * 0.10hrs 12.00 23349854 : SL-N-ELEMENT (03410-CT) 1@49.95 49.95	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

2025 TOP-RATED DEALER

★ **4.6 / 5.0**
177 Verified Reviews

♥ **1,545**
Customer Favorites



Report

US \$44.99

2017 GMC Yukon SLT

143,271 mi | VIN: 1GKS2BKC0HR157688 |

4 Door Wagon/Sport Utility | 5.3L V8 F OHV 16V | Gasoline | Rear wheel drive w/ 4X4

CARFAX HAS THE MOST
ACCIDENT & DAMAGE
INFORMATION



🔧 42 Service History Records

👤 3 Previous Owners

🏠 Personal Vehicle

🌍 Last Owned in Illinois

📁 64 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/30/26 at 9:04:43 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Accident / Damage History

Not all accidents / issues are reported to CARFAX


Event 1

09/15/2019

Accident reported: minor damage

- Involving left rear impact with another motor vehicle
- It hit a parked motor vehicle

Damage Severity Scale



CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	05/28/2026
🛞 Tires	✓ One tire replaced	05/28/2026

This car has been recently serviced. That's a good thing!

CARFAX Additional History Not all accidents / issues are reported to CARFAX	Owner 1	Owner 2	Owner 3
Total Loss No total loss reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported
Odometer Check No indication of an odometer rollback.	✓ No Issues Indicated	✓ No Issues Indicated	✓ No Issues Indicated
Accident / Damage Accident reported: 09/15/2019.	✓ No Issues Reported	Minor Damage	No New Issues Reported
Manufacturer Recall No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	✓ No Recalls Reported	✓ No Recalls Reported	✓ No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired	Warranty Expired

CARFAX Title History CARFAX guarantees the information in this section	Owner 1	Owner 2	Owner 3
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	✓ Guaranteed No Problem	✓ Guaranteed No Problem	✓ Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	✓ Guaranteed No Problem	✓ Guaranteed No Problem	✓ Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

CARFAX Ownership History The number of owners is estimated	Owner 1	Owner 2	Owner 3
Year purchased	2018	2018	2022
Type of owner	Personal	Personal	Personal
Estimated length of ownership	24 days	4 yrs. 2 mo.	3 yrs. 11 mo.
Owned in the following states/provinces	Illinois	Illinois	Illinois
Estimated miles driven per year	--	15,222/yr	18,968/yr
Last reported odometer reading	3,028	66,317	143,271

CARFAX Detailed History			
Owner 1 Purchased: 2018			Personal Vehicle
Date	Mileage	Source	Comments
12/20/2017	1,856	Ray Dennison Buick GMC Cadillac	Vehicle offered for sale

Pekin, IL
 309-321-0093
 raydennisonbuickgmc.com/
 ★ 4.7 / 5.0 163 Verified Reviews
 ♥ 2,312 Customer Favorites

12/20/2017 
 Ray Dennison Buick GMC Cadillac
 Pekin, IL
 309-321-0093
 raydennisonbuickgmc.com/
 ★ 4.7 / 5.0 163 Verified Reviews
 ♥ 2,312 Customer Favorites

Vehicle serviced
 - Fluids checked
 - Oil and filter changed

01/30/2018 3,028
 Ray Dennison Buick GMC Cadillac
 Pekin, IL
 309-321-0093
 raydennisonbuickgmc.com/
 ★ 4.7 / 5.0 163 Verified Reviews
 ♥ 2,312 Customer Favorites


Vehicle sold

01/30/2018
 Illinois
 Motor Vehicle Dept.
 Pekin, IL

Vehicle purchase reported
 - First owner reported
 - Titled or registered as personal vehicle

01/31/2018
 Certified Pre-Owned Dealer
 Pekin, IL





Sold as a GMC Certified Pre-owned Vehicle



02/21/2018
 Illinois
 Motor Vehicle Dept.
 Pekin, IL

Registration issued or renewed

 **Owner 2** Personal Vehicle
 Purchased: 2018 15,222 mi/yr

Date	Mileage	Source	Comments
02/23/2018		Illinois Motor Vehicle Dept. Pekin, IL Title #180546917430	Title issued or updated - New owner reported - Loan or lien reported - Vehicle color noted as Red
03/05/2018	5,469	Crown Buick GMC Saint Petersburg, FL 727-527-7151 crownmgmbuick.com ★ 4.6 / 5.0 299 Verified Reviews ♥ 126 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Blend/diverter door actuator replaced
04/18/2018	7,869	Ray Dennison Buick GMC Cadillac Pekin, IL 309-321-0093 raydennisonbuickgmc.com/ ★ 4.7 / 5.0 163 Verified Reviews ♥ 2,312 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Oil and filter changed - Tires rotated
06/15/2018	10,921	Ray Dennison Buick GMC Cadillac Pekin, IL 309-321-0093 raydennisonbuickgmc.com/ ★ 4.7 / 5.0 163 Verified Reviews ♥ 2,312 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Battery/charging system checked
08/11/2018	13,935	Ray Dennison Buick GMC Cadillac Pekin, IL 309-321-0093 raydennisonbuickgmc.com/ ★ 4.7 / 5.0 163 Verified Reviews	 Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Oil and filter changed - Tires rotated

♥ 2,312 Customer Favorites

11/30/2018 20,043

Ray Dennison Buick GMC Cadillac
Pekin, IL
309-321-0093
raydennisonbuickgmc.com/
★ 4.7 / 5.0 163 Verified Reviews
♥ 2,312 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Battery/charging system checked
- Fluids checked
- Oil and filter changed
- Tire repaired
- Tires rotated

02/13/2019

Illinois
Motor Vehicle Dept.
Pekin, IL

Registration issued or renewed

- Correction to record

05/10/2019 26,249

Ray Dennison Buick GMC Cadillac
Pekin, IL
309-321-0093
raydennisonbuickgmc.com/
★ 4.7 / 5.0 163 Verified Reviews
♥ 2,312 Customer Favorites



Vehicle serviced


- Maintenance inspection completed
- Recommended maintenance performed
- Battery/charging system checked
- Fluids checked
- Oil and filter changed
- Tires rotated

09/15/2019

Damage Report

Accident reported: minor damage

- Involving left rear impact with another motor vehicle
- It hit a parked motor vehicle
- Damage to rear



Minor damage is usually cosmetic, including dents or scratches to the vehicle body.

CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION

09/18/2019 32,020

Ray Dennison Buick GMC Cadillac
Pekin, IL
309-321-0093
raydennisonbuickgmc.com/
★ 4.7 / 5.0 163 Verified Reviews
♥ 2,312 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Recommended maintenance performed
- Battery/charging system checked
- Fluids checked
- Oil and filter changed
- Tire condition and pressure checked

11/05/2019 33,917

Ray Dennison Buick GMC Cadillac
Pekin, IL
309-321-0093
raydennisonbuickgmc.com/
★ 4.7 / 5.0 163 Verified Reviews
♥ 2,312 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Recommended maintenance performed
- Battery/charging system checked
- Drivability/performance checked
- Four tires balanced
- Four tires mounted
- Four wheel alignment performed
- Tire condition and pressure checked

02/11/2020

Illinois

Registration issued or renewed