

Multi-Point Inspection Checklist

RO# 6036882

Customer Name INVENTORY: 968651

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 2/10/2026 7:35 AM

Printed on 2/19/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

- Checked and OK at this time
 May Require Future Attention
 Requires immediate attention

Maintenance Service

- | | | | |
|-------------------------------------|--------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cold Engine start-up |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine operation warm-up |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine at normal operating temperature |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Brake and parking operation <u>fb 9mm rb 8mm</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Active seat belt test |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Clutch and transmission operations |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Overdrive operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Transfer case operation (4-wheel drive only) |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Steering operation and off center |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Front end alignment |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tilt steering wheel operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Windshield wiper and washer operation at all speeds, wiper blade condition |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Speedometer and odometer operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cruise Control operation, including resume |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Heater and air condition operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Abnormal noises and vibrations |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Squeaks and rattles |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Frame Check |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Body surface, lower body, and upper body damage requiring body shop repair |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tire defects and damage, 5/32 <u>ft 6/32 rt 7/32</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive shaft, joints, CV's and boots |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Struts/shock absorbers, leaks and wear |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Exhaust system leaks and damage, including catalytic converter |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Fuel, oil, coolant, or other fluid leaks |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Perform emissions test and/or state inspection if required |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood labels and decals |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Air filter and In-Cabin Air Filter equipped <u>Found the cabin and engine air filter to be dirty</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Battery cables and mount |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Coolant level and test |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood fluid levels, including transmission and transfer case fluids |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive belts and hoses |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Air conditioning levels, check at sight glass |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Warning lights (including air bag) gauges & horn |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Inside and outside rearview mirror operation, adjustment, and condition <u>Found passenger side mirror to be broken</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Glass free of cracks, starts and large chips |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Dome, courtesy, map and sun visor lights and lighters and power ports |

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

 Technician Date

 Service Manager Date

 Used Car Manager Date

 Customer Date

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
SUV	64208	64208
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date
	11/17/22	11/17/22

Year	Make	Model
2023	CHEVROLET	TRAVERSE
Vehicle Identification Number		Color
1GNEVNKW1PJ129740		PURPLE

INVENTORY: **968651**

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 Performed a 56 point inspection.	I	169.95
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 19432357 : N-OIL (08800-BOPCK) 6@8.25 49.50 12735811 : SL-N-FILTER (01836-BOPCKT) 1@13.60 13.60 Changed the engine oil and filter.	I	73.70 49.50 13.60
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs Performed a 4 wheel alignments.	I	159.95
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs Balanced all four wheels and tires.	I	59.95
#5 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 19338054 : SL-N-FILTER (09786-BOPCKT) 1@29.95 29.95	I	10.00 29.95

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
 200 S Gear Ave
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
SUV	64208	64208
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date
	11/17/22	11/17/22


Year	Make	Model
2023	CHEVROLET	TRAVERSE
Vehicle Identification Number		Color
1GNEVNKW1PJ129740		PURPLE

INVENTORY: 968651

Replaced the cabin air filter.

#6 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT
 Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00
 Work performed by Tech 329/9 * 0.10hrs 10.00
 23321606 : SL-N-ELEMENT (03410-BCKT) 1@49.95 49.95
 Replaced the engine air filter.

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	483.55				
PARTS	143.00				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	656.54				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
153 Verified Reviews

♥ **101**
Customer Favorites



Vehicle History Report™

US \$44.99

2023 CHEVROLET TRAVERSE HIGH COUNTRY

VIN: 1GNEVNKW1PJ129740
4 DOOR WAGON/SPORT UTILITY
3.6L V6 F DOHC 24V GASOLINE
ALL WHEEL DRIVE
Original Window Sticker
This CARFAX Report Provided by:
Deery Brothers
★ 4.6 / 5.0
153 Verified Reviews
♥ 101 Customer Favorites

✓ No accidents or damage reported to CARFAX


🔧 15 Service history records

👍 Good Reliability

1 CARFAX 1-Owner vehicle

🏠 Personal vehicle

📊 64,208 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/18/26 at 6:51:22 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	02/12/2026
🛞 Tires	✓ Tires rotated	02/12/2026





This car has been recently serviced. That's a good thing!

CARFAX Reliability Forecast

Based on 2023 Chevrolet Traverse High Country with similar mileage

3-Year Reliability Forecast



Fair Reliability **Good Reliability** Great Reliability

Good news! This vehicle is expected to have average risk of repair and average repair costs.



What makes this vehicle have good reliability?

- Top 50%** compared to similar vehicles
- Average Repair Cost**
\$330 avg per year
- Oil Changes** performed regularly
- Average Likelihood of Repair**

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss

No total loss reported to CARFAX.

No Issues Reported

Structural Damage

No structural damage reported to CARFAX.

No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.

No Issues Reported

Odometer Check

No indication of an odometer rollback.

No Issues Indicated

Accident / Damage

No accidents or damage reported to CARFAX.

No Issues Reported

Manufacturer Recall

No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.

No Recalls Reported

Basic Warranty

Original warranty estimated to have expired.

Warranty Expired

CARFAX Title History

CARFAX guarantees the information in this section

Owner 1