

Multi-Point Inspection Checklist

RO# 6040145

Customer Name INVENTORY: 969791

Advisor Name JAKE BACHTELL

Technician Name Dylan Miller









































































































Created on 5/22/2026 2:55 PM

Printed on 6/2/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

- | | | | |
|--|---|---|--|
|  |  |  | Cold Engine start-up |
|  |  |  | Engine operation warm-up |
|  |  |  | Engine at normal operating temperature |
|  |  |  | Brake and parking operation |
|  |  |  | Active seat belt test |
|  |  |  | Clutch and transmission operations <u>has shudder between 45 and 55 mph</u> |
|  |  |  | Overdrive operation |
|  |  |  | Transfer case operation (4-wheel drive only) |
|  |  |  | Steering operation and off center |
|  |  |  | Front end alignment |
|  |  |  | Tilt steering wheel operation |
|  |  |  | Windshield wiper and washer operation at all speeds, wiper blade condition |
|  |  |  | Speedometer and odometer operation |
|  |  |  | Cruise Control operation, including resume |
|  |  |  | Heater and air condition operation |
|  |  |  | Abnormal noises and vibrations <u>has growl in front end when turning</u> |
|  |  |  | Squeaks and rattles |
|  |  |  | Frame Check |
|  |  |  | Body surface, lower body, and upper body damage requiring body shop repair |
|  |  |  | Tire defects and damage, 5/32 <u>front tires are at 12/32nds, rear tires are at 12/32nds</u> |
|  |  |  | Drive shaft, joints, CV's and boots |
|  |  |  | Struts/shock absorbers, leaks and wear |
|  |  |  | Exhaust system leaks and damage, including catalytic converter |
|  |  |  | Fuel, oil, coolant, or other fluid leaks |
|  |  |  | Perform emissions test and/or state inspection if required |
|  |  |  | Under hood labels and decals |
|  |  |  | Air filter and In-Cabin Air Filter equipped <u>both air filters are dirty</u> |
|  |  |  | Battery cables and mount |
|  |  |  | Coolant level and test |
|  |  |  | Under hood fluid levels, including transmission and transfer case fluids |
|  |  |  | Drive belts and hoses |
|  |  |  | Air conditioning levels, check at sight glass |
|  |  |  | Warning lights (including air bag) gauges & horn |
|  |  |  | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light |
|  |  |  | Inside and outside rearview mirror operation, adjustment, and condition |
|  |  |  | Glass free of cracks, starts and large chips |
|  |  |  | Dome, courtesy, map and sun visor lights and lighters and power ports |

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness front pads are at 11mm, rear pads are at 11mm
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2021	CHEVROLET	SUBURBAN
Vehicle Identification Number		Color
1GNSKCKD8MR423759		WHITE

5/22/26	6040145/1
5/23/26	Original
96503	96503
JAKE BACHTELL	

INVENTORY: 969791

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:178.95 Work performed by Tech 461/4 1.00hrs @ 178.95 178.95 19432337 : N-OIL (08800-BOPCK) 8@9.60 76.80 19363567 : SL-N-FILTER (01836-BOPCKT) 1@6.95 6.95 performed 56 point inspection	I
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:195.58 Work performed by Tech 461/4 0.40hrs @ 195.57 78.23 changed engine oil and filter, reset maintenance and installed sticker	I
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 461/4 * 1.50hrs 159.95 performed alignment. front toe was out of specs set front toe and test drove wheel was straight and vehicle drove straight.	I
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 461/4 * 0.90hrs 99.00 balanced and rotated all four wheels	I
#5 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT	I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
Vehicle Identification Number	Color	

INVENTORY: 969791

Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00
 Work performed by Tech 461/4 * 0.10hrs 12.00
 19338054 : SL-N-FILTER (09786-BOPCKT) 1@29.95 29.95
 replaced air filter

#6 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT
 Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00
 Work performed by Tech 461/4 * 0.10hrs 12.00
 84121217 : SL-N-ELEMENT (03410-CT) 1@49.95 49.95
 replaced air filter

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	540.13				
PARTS	163.65				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	733.77				

This report provided free of charge by:

Deery Brothers
 200 S Gear Ave
 West Burlington, IA 52655
 319-271-8758

2025 TOP-RATED DEALER

★ **4.6 / 5.0**
 175 Verified Reviews

♥ **1,514**

Customer Favorites



Report

US \$44.99

2021 Chevrolet Suburban LT

96,503 mi | VIN: 1GNSKCKD8MR423759 |

4 Door Wagon/Sport Utility | 5.3L V8 F OHV 16V | Gasoline | Rear wheel drive w/ 4X4



NO ACCIDENTS REPORTED

✓ No Accidents or Damage Reported to CARFAX

🛢️ Regular Oil Changes

1 CARFAX 1-Owner Vehicle

🏠 Personal Vehicle

🌍 Last Owned in Illinois

📄 37 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/27/26 at 5:54:10 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	05/23/2026
🛞 Tires	✓ Tires rotated	05/23/2026
🛑 Brakes	✓ Front brake pads replaced ✓ Rear brake pads replaced	12/12/2025

This car has been recently serviced. That's a good thing!

CARFAX Additional History

Not all accidents / issues are reported to CARFAX


👤 Owner 1

Total Loss




No total loss reported to CARFAX.









✓ No Issues Reported

Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

CARFAX Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

CARFAX Ownership History The number of owners is estimated	Owner 1
Year purchased	2021
Type of owner	Personal
Estimated length of ownership	4 yrs. 9 mo.
Owned in the following states/provinces	Illinois
Estimated miles driven per year	20,197/yr
Last reported odometer reading	96,503

CARFAX Detailed History			
 Owner 1 Purchased: 2021		Personal Vehicle 20,197 mi/yr	
Date	Mileage	Source	Comments
Not Reported		General Motors	Original Window Sticker 
08/05/2021	3	Bommarito Mazda Chevrolet Saint Louis, MO 314-487-9800 bommarito.com ★ 4.7 / 5.0 833 Verified Reviews ❤️ 8,304 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed

08/13/2021		Illinois Motor Vehicle Dept.		Vehicle purchase reported - Titled or registered as personal vehicle
10/13/2021	10	Illinois Motor Vehicle Dept. Carthage, IL Title #212866960750		Title issued or updated - Registration issued or renewed - First owner reported - Loan or lien reported
11/16/2021	5,632	Carson Motors Carthage, IL 217-357-2925 carsongm.com/ ★ 4.8 / 5.0 42 Verified Reviews ❤️ 31 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Brakes checked - Oil and filter changed - Tire condition and pressure checked - Tires rotated
02/10/2022	11,834	Carson Motors Carthage, IL 217-357-2925 carsongm.com/ ★ 4.8 / 5.0 42 Verified Reviews ❤️ 31 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed
04/27/2022	17,094	Shottenkirk Chevrolet Quincy Quincy, IL 217-228-6500 shottenkirkchevy.com ★ 4.8 / 5.0 799 Verified Reviews ❤️ 7,549 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Fuel pump module replaced
05/03/2022	17,830	Carson Motors Carthage, IL 217-357-2925 carsongm.com/ ★ 4.8 / 5.0 42 Verified Reviews ❤️ 31 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed
06/30/2022		Illinois Motor Vehicle Dept. Carthage, IL		Registration issued or renewed
07/05/2022	23,285	Carson Motors Carthage, IL 217-357-2925 carsongm.com/ ★ 4.8 / 5.0 42 Verified Reviews ❤️ 31 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed
10/13/2022	29,768	Carson Motors Carthage, IL 217-357-2925 carsongm.com/ ★ 4.8 / 5.0 42 Verified Reviews ❤️ 31 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed
01/26/2023	35,720	Carson Motors Carthage, IL 217-357-2925 carsongm.com/ ★ 4.8 / 5.0 42 Verified Reviews ❤️ 31 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed
02/24/2023		Carson Motors Carthage, IL 217-357-2925 carsongm.com/ ★ 4.8 / 5.0 42 Verified Reviews ❤️ 31 Customer Favorites		Vehicle serviced