

Multi-Point Inspection Checklist

RO# 6036136

Customer Name INVENTORY: 968581

Advisor Name JAKE BACHTELL

Technician Name Justen Shelman

Created on 1/16/2026 9:13 AM

Printed on 2/4/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

-  Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-    Cold Engine start-up Pass
-    Engine operation warm-up Pass
-    Engine at normal operating temperature Pass
-    Brake and parking operation Pass
-    Active seat belt test Pass
-    Clutch and transmission operations Pass
-    Overdrive operation Pass
-    Transfer case operation (4-wheel drive only) Pass
-    Steering operation and off center Pass
-    Front end alignment Pass
-    Tilt steering wheel operation Pass
-    Windshield wiper and washer operation at all speeds, wiper blade condition Pass
-    Speedometer and odometer operation Pass
-    Cruise Control operation, including resume Pass
-    Heater and air condition operation Pass
-    Abnormal noises and vibrations Pass
-    Squeaks and rattles Pass
-    Frame Check Pass
-    Body surface, lower body, and upper body damage requiring body shop repair Pass
-    Tire defects and damage, 5/32 SERVICE TIRE LIGHT IS ON, ALL AT 10/32
-    Drive shaft, joints, CV's and boots Pass
-    Struts/shock absorbers, leaks and wear Pass
-    Exhaust system leaks and damage, including catalytic converter Pass
-    Fuel, oil, coolant, or other fluid leaks Pass
-    Perform emissions test and/or state inspection if required Pass
-    Under hood labels and decals Pass
-    Air filter and In-Cabin Air Filter equipped Pass
-    Battery cables and mount Pass

-    Coolant level and test Pass
-    Under hood fluid levels, including transmission and transfer case fluids Pass
-    Drive belts and hoses Pass
-    Air conditioning levels, check at sight glass Pass
-    Warning lights (including air bag) gauges & horn Pass
-    Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-    Inside and outside rearview mirror operation, adjustment, and condition Pass
-    Glass free of cracks, starts and large chips Pass
-    Dome, courtesy, map and sun visor lights and lighters and power ports Pass

- Window operation Pass
- Sunroof or convertible top operation Pass
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used N/A
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets MISSING FLOOR MATS
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance Pass
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness F 7MM, R 8MM
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL Pass
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle. Pass
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time. pass
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists. Pass
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase. Pass
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Year	Make	Model
2022	GMC	SIERRA 1500 L
Vehicle Identification Number		Color
1GTU9FEL3NZ169963		BLACK

Work Phone	R/O Open Date	R/O Number
	1/16/26	6036136/1
Home Phone	R/O Close Date	Receipt No.
	1/28/26	Original
Body	Mileage In	Mileage Out
TRUCK	57781	57781
License Number	Service Advisor	
	JAKE BACHTELL	
Account No.	Delivery Date	In-Service Date
	2/01/22	1/31/22

INVENTORY: 968581

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 490/ 1.00hrs @ 169.95 PERFORMED SERVICE			I	
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 490/ 0.40hrs @ 184.25 73.70 12735811 : SL-N-FILTER (01836-BOPCKT) 1@13.60 13.60 19432867 : N-OIL (08800-BOPCK) 8@16.65 133.20 PERFORMED SERVICE			I	
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 490/ * 1.50hrs 159.95 PERFORMED ALIGNMENT			I	
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 490/ * 0.90hrs 59.95 ROTATED AND BALANCED TIRES			I	
#5 * TPMS3: REPLACE 3 TPMS SENSORS Corrected by SOP: PARTS TO REPAIR YOUR VEHICLE HAD TO BE SPECIAL ORDERED. WE WILL CONTACT YOU AS SOON AS WE RECEIVE THE REQUIRED PARTS TO REPAIR YOUR VEHICLE. IF YOU HAVE ANY FURTHER QUESTIONS PLEASE			I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
 200 S Gear Ave
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2022	GMC	SIERRA 1500 L
Vehicle Identification Number		Color
1GTU9FEL3NZ169963		BLACK

TRUCK	57781	57781
JAKE BACHTELL		
	2/01/22	1/31/22

INVENTORY: 968581

CONTACT THE SERVIC LRATE:180.14
 VEHICLE. IF YOU HA VE ANY FURTHER QUESTIONS PLEASE
 CONTACT THE SERVIC LRATE:180.14
 Work performed by Tech 490/ 0.00hrs @
 13540603 : SL-N-SENSOR (05890-BCKT) 3@92.42 Ordered

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	463.55				
PARTS	146.80				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	640.34				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
151 Verified Reviews

♥ **101**
Customer Favorites



Vehicle History Report™

US \$44.99

2022 GMC SIERRA 1500 LIMITED DENALI

VIN: 1GTU9FEL3NZ169963
CREW PICKUP


6.2L V8
GASOLINE
REAR WHEEL DRIVE W/ 4X4
Original Window Sticker

This CARFAX Report Provided by:

Deery Brothers

★ **4.6 / 5.0**
151 Verified Reviews
♥ **101** Customer Favorites

Damage reported: minor damage



13 Service history records

Good Reliability

CARFAX 1-Owner vehicle

57,790 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 1/31/26 at 12:00:34 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.


CARFAX Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1

04/11/2023

Damage reported: minor damage



CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
Oil	✓ Oil and filter changed	01/21/2026
Tires	✓ One tire replaced ✓ Tires rotated	01/21/2026



This car has been recently serviced. That's a good thing!

CARFAX Reliability Forecast

Based on 2022 GMC Sierra 1500 Limited Denali with similar mileage

3-Year Reliability Forecast



Good news! This vehicle is expected to have average risk of repair and average repair costs.



What makes this vehicle have **good** reliability?

- Top 50%** compared to similar vehicles
- Average Repair Cost**
\$420 avg per year
- Average Likelihood of Repair**

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss

No total loss reported to CARFAX.

✓ No Issues Reported

Structural Damage

CARFAX recommends that you have this vehicle inspected by a collision repair specialist.

✓ No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.

✓ No Issues Reported

Odometer Check

No indication of an odometer rollback.

✓ No Issues Indicated

Accident / Damage

Damage reported: 04/11/2023.

Minor Damage

<p>Manufacturer Recall No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.</p>	<p><input checked="" type="checkbox"/> No Recalls Reported</p>
<p>Basic Warranty Original warranty estimated to have expired.</p>	<p>Warranty Expired</p>

<p>CARFAX Title History CARFAX guarantees the information in this section</p>	<p>Owner 1</p>
<p>Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon</p>	<p><input checked="" type="checkbox"/> Guaranteed No Problem</p>
<p>Odometer Brands Not Actual Mileage Exceeds Mechanical Limits</p>	<p><input checked="" type="checkbox"/> Guaranteed No Problem</p>
<p> GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate</p>	

<p>CARFAX Ownership History The number of owners is estimated</p>	<p>Owner 1</p>
<p>Year purchased</p>	<p>2022</p>
<p>Type of owner</p>	<p>Personal</p>
<p>Estimated length of ownership</p>	<p>3 yrs. 11 mo.</p>
<p>Owned in the following states/provinces</p>	<p>Illinois</p>
<p>Estimated miles driven per year</p>	<p>14,585/yr</p>
<p>Last reported odometer reading</p>	<p>57,790</p>

<p>CARFAX Detailed History</p>			
<p> Owner 1 Purchased: 2022</p>		<p>Low mileage! This owner drove less than the industry average of 15,000 miles per year.</p>	<p>Personal Vehicle 14,585 mi/yr</p>
<p>Date</p>	<p>Mileage</p>	<p>Source</p>	<p>Comments</p>