

# Multi-Point Inspection Form

RO# 6035847  
 INVENTORY: 968770  
 VIN 2C4RC1BG1RR142424  
 Advisor JAKE BACHTTELL  
 Technician Moore Alicia  
 Created On 1/26/2026

Checked and OK at this time

May Require Future Attention

Requires immediate attention

## Interior / Exterior

- Bulbs and Lights
- Windshield Washer Spray / Wiper Operation / Wiper Blades / Including Rear (if applicable)
- Windshield / Window Condition
- Upholstery / Carpet / Floor Mats / Mirrors / Trim
- Horn Operation
- Clutch Operation (if equipped)
- Cabin/HEPA Filter (if equipped)

## Battery Performance

- Battery Terminals / Cables / Mountings
- Check Condition of Battery (Storage Capacity Test if Applicable)

## Under Hood

- Fluids: Oil / Coolant / Power Steering / Brake Fluid / Washer
- Engine Air Filter
- Belts / Tensioners (condition and adjustment)
- Cooling System Hoses / Heater Hoses / Air Conditioning Hoses and Connections
- Radiator Core / Air Conditioning Condenser (if equipped)

## Under Vehicle

- Shock Absorbers / Suspension
- Steering Gear Box / Linkage and Boots / Ball Joints / Dust Covers
- Muffler / Exhaust Pipes / Mountings
- Engine Oil and/or Fluid Leaks
- Drive Shaft Boots / Constant Velocity Boots / U-joints / Transmission Linkage (if equipped)
- Transmission / Differential / Transfer Case (Check Fluid Level, Fluid Condition and Fluid Leaks)
- Fuel Lines and Connections / Fuel Tank Band / Fuel Tank Vapor Vent System Hoses
- Inspect Nuts and Bolts on Body Chassis

## Tread Depth (measured in 1/32")



- LF g
- RF g
- LR g
- RR g
- Spare Tire (if applicable)
- LF/RF Tire Pressure 36
- LR/RR Tire Pressure 36

## Abnormal Wear Pattern of Tires

- LF
- RF
- LR
- RR

## Check Brake Linings (measured in millimeters)

- LF g
- RF g
- LR g
- RR g

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
TOURING L FWD	37271	37271
License Number	Service Advisor	
	JAKE BACHTELL	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2024	CHRYSLER	PACIFICA
Vehicle Identification Number		Color
2C4RC1BG1RR142424		BLACK

INVENTORY: 968770

<p>#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 853/ 1.00hrs @ 169.95 technician completed 56-point inspection on used vehicle.</p>	169.95	I	
<p>#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 853/ 0.40hrs @ 184.25 73.70 19420060 : N-OIL (08800-BOPCK) 5@8.10 40.50 PO6296EX : OIL FILTER 1@21.70 21.70 technician completed engine oil drain and refilling with new. as well as replacement of engine oil filter with new.</p>	73.70 40.50 21.70	I	
<p>#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 853/ * 1.50hrs 159.95 technician completed HUNTER 4-wheel alignment on used vehicle.</p>	159.95	I	
<p>#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 853/ * 0.90hrs 59.95 technician completed rotate and wheel rotation on used vehicle/</p>	59.95	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
	1/06/26	6035847/2
Home Phone	R/O Close Date	Receipt No.
	1/07/26	Original
Body	Mileage In	Mileage Out
TOURING L FWD	37271	37271
License Number	Service Advisor	
	JAKE BACHTELL	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2024	CHRYSLER	PACIFICA
Vehicle Identification Number		Color
2C4RC1BG1RR142424		BLACK

INVENTORY: 968770

#5 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 853/ * 0.10hrs PC99238C : CABIN AIR FILTER 1@49.95 technician completed replacement of cabin air filter with new	10.00 49.95	I
#6 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00 Work performed by Tech 853/ * 0.10hrs PA99209 : AIR FILTER 1@29.95 technician completed replacement of engine air filter with new on used vehicle.	10.00 29.95	I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	483.55				
PARTS	142.10				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	655.64				



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
148 Verified Reviews

♥ **102**  
Customer Favorites



## Vehicle History Report™

US \$44.99

### 2024 CHRYSLER PACIFICA TOURING L

VIN: 2C4RC1BG1RR142424  
VAN  
3.6L V6  
GASOLINE  
FRONT WHEEL DRIVE  
Original Window Sticker  
This CARFAX Report Provided by:

**Deery Brothers**  
★ 4.6 / 5.0  
148 Verified Reviews  
♥ 102 Customer Favorites

✓ No accidents or damage reported to CARFAX

✂ 1 Service history record

1 CARFAX 1-Owner vehicle

🚗 Rental vehicle

🌍 Last owned in Florida

📊 37,271 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 1/12/26 at 6:30:10 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	01/07/2026
🛞 Tires	✓ Tires rotated	01/07/2026



This car has been recently serviced. That's a good thing!

 <b>Additional History</b> Not all accidents / issues are reported to CARFAX	Owner 1
<b>Total Loss</b> No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Structural Damage</b> No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Manufacturer Recall</b> No open recalls reported to CARFAX.	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	Warranty Expired

 <b>Title History</b> CARFAX guarantees the information in this section	Owner 1
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
 <b>GUARANTEED</b> - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. <a href="#">View Terms</a>   <a href="#">View Certificate</a>	

 <b>Ownership History</b> The number of owners is estimated	Owner 1
Year purchased	2024
Type of owner	Rental
Estimated length of ownership	1 yr. 7 mo.
Owned in the following states/provinces	Florida
Estimated miles driven per year	22,373/yr
Last reported odometer reading	37,271





## Detailed History



**Owner 1**

Purchased: 2024

Rental Vehicle  
22,373 mi/yr

Date	Mileage	Source	Comments
Not Reported		FCA US LLC	<b>Original Window Sticker</b> 
05/08/2024		Florida Motor Vehicle Dept. Orlando, FL	<b>Vehicle purchase reported</b> - First owner reported - Titled or registered as rental vehicle
06/14/2024	5	Florida Motor Vehicle Dept. Orlando, FL	<b>Registration issued or renewed</b> - Loan or lien reported - Vehicle color noted as Black
06/06/2025		Florida Motor Vehicle Dept. Orlando, FL	<b>Registration issued or renewed</b> - Loan or lien reported - Vehicle color noted as Black
12/13/2025		Online Listing	<b>Vehicle offered for sale</b>
01/06/2026	37,269	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 148 Verified Reviews ❤️ 102 Customer Favorites	<b>Vehicle offered for sale</b>
01/07/2026	37,271	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 148 Verified Reviews ❤️ 102 Customer Favorites	 <b>Vehicle serviced</b> - Maintenance inspection completed - Air filter replaced - Cabin air filter replaced/cleaned - Oil and filter changed - Tires rotated
			<div style="border: 1px solid blue; padding: 5px;">                         Looks like this dealer serviced the car in order to prepare it for sale. That's a good thing!                     </div>
01/12/2026		CARFAX Car Care	<b>Manufacturer Recommended</b>