

# Multi-Point Inspection Checklist

RO# 6039796

Customer Name INVENTORY: 500490

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 5/13/2026 2:35 PM

Printed on 5/13/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?


 Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

-   Cold Engine start-up Pass
-   Engine operation warm-up Pass
-   Engine at normal operating temperature Pass
-   Brake and parking operation Pass
-   Active seat belt test Pass
-   Clutch and transmission operations Pass
-   Overdrive operation Pass
-   Transfer case operation (4-wheel drive only) Pass
-   Steering operation and off center Pass
-   Front end alignment Pass
-   Tilt steering wheel operation Pass
-   Windshield wiper and washer operation at all speeds, wiper blade condition Pass
-   Speedometer and odometer operation Pass
-   Cruise Control operation, including resume Pass
-   Heater and air condition operation Pass
-   Abnormal noises and vibrations Pass
-   Squeaks and rattles Pass
-   Frame Check Pass
-   Body surface, lower body, and upper body damage requiring body shop repair Pass
-   Tire defects and damage, 5/32 7/32
-   Drive shaft, joints, CV's and boots Pass
-   Struts/shock absorbers, leaks and wear Pass
-   Exhaust system leaks and damage, including catalytic converter Pass
-   Fuel, oil, coolant, or other fluid leaks Pass
-   Perform emissions test and/or state inspection if required Pass
-   Under hood labels and decals Pass
-    Air filter and In-Cabin Air Filter ~~equipped~~ air filter
-   Battery cables and mount Pass
-   Coolant level and test Pass
-   Under hood fluid levels, including transmission and transfer case fluids Pass
-   Drive belts and hoses Pass
-   Air conditioning levels, check at sight glass Pass
-   Warning lights (including air bag) gauges & horn Pass
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-   Inside and outside rearview mirror operation, adjustment, and condition Pass
-   Glass free of cracks, starts and large chips Pass
-   Dome, courtesy, map and sun visor lights and lighters and power ports Pass

- Window operation Pass
- Sunroof or convertible top operation Pass
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance Pass
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 7mm front 6mm rear
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL Pass
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician \_\_\_\_\_ Date \_\_\_\_\_

Service Manager  \_\_\_\_\_ Date 5.13.26

Used Car Manager \_\_\_\_\_ Date \_\_\_\_\_

Customer \_\_\_\_\_ Date \_\_\_\_\_

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

|                |                 |                 |
|----------------|-----------------|-----------------|
| Work Phone     | R/O Open Date   | R/O Number      |
| Home Phone     | R/O Close Date  | Receipt No.     |
| Body           | Mileage In      | Mileage Out     |
| SUV            | 116562          | 116562          |
| License Number | Service Advisor |                 |
| Account No.    | Delivery Date   | In-Service Date |

|                               |           |         |
|-------------------------------|-----------|---------|
| Year                          | Make      | Model   |
| 2020                          | CHEVROLET | EQUINOX |
| Vehicle Identification Number |           | Color   |
| 2GNAXUEV7L6154915             |           | SILVER  |

AMANDA KEPHART

INVENTORY: 500490

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL  
ALL FLUID LEVELS  
Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE  
CHASSIS FILL ALL FLUID LEVELS LRATE:195.58  
Work performed by Tech 256/ 0.40hrs @ 195.57 78.23  
19432337 : N-OIL (08800-BOPCK) 6@9.60 57.60  
19533697 : SL-N-FILTER (01836-BOPCKT) 1@6.95 6.95  
new oil and filter installed

I

#2 - 4: 56 POINT INSPECTION  
Corrected by 4: 56 POINT INSPECTION LRATE:178.95  
Work performed by Tech 256/ 1.00hrs @ 178.95 178.95  
inspection complete

I

#3 - RECALL: CHECK FOR OPEN RECALLS  
Corrected by NRF: NO RECALLS FOUND FOR VEHICLE AT THIS  
TIME. LRATE:184.59  
Work performed by Tech 256/ 0.00hrs @

I

#4 \* AF: REPLACED ENGINE AIR FILTER  
Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00  
Work performed by Tech 256/ \* 0.10hrs 12.00  
84390002 : SL-N-ELEMENT (03410-CT) 1@29.95 29.95  
new air filter installed

I

|                       | INTERNAL | SERVICE CONT. | WARRANTY | CUSTOMER PAY | COST |
|-----------------------|----------|---------------|----------|--------------|------|
| LABOR                 | 269.18   |               |          |              |      |
| PARTS                 | 94.50    |               |          |              |      |
| DEDUCTIBLE            |          |               |          |              |      |
| SUBLET                |          |               |          |              |      |
| SHOP SUPPLIES         | 29.99    |               |          |              |      |
| HAZARDOUS MATERIALS   |          |               |          |              |      |
| SALES TAX OR TAX I.D. |          |               |          |              |      |
| SPECIAL ORDER DEPOSIT |          |               |          |              |      |
| DISCOUNTS             |          |               |          |              |      |
|                       | 393.67   |               |          |              |      |

This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

2025 TOP-RATED DEALER

★ **4.6 / 5.0**  
169 Verified Reviews

♥ **1,182**  
Customer Favorites

# CARFAX Report

US \$44.99

## 2020 Chevrolet Equinox LT

116,562 mi | VIN: 2GNAXUEV7L6154915 |  
4 Door Wagon/Sport Utility | 1.5L I4 F DOHC 16V | Gasoline | All wheel drive



**NO ACCIDENTS REPORTED**

✓ No Accidents or Damage Reported to CARFAX

**CARFAX VALUE \$14,680**

🔧 7 Service History Records

👤 2 Previous Owners

🚗 Types of Owners: Rental, Personal

🌍 Last Owned in Montana

📄 26 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/16/26 at 9:12:11 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### CARFAX Recent Service Highlights

Key services performed in the last 12 months

| Service | Comments                 | Date       |
|---------|--------------------------|------------|
| 🛢 Oil   | ✓ Oil and filter changed | 05/14/2026 |
| 🛞 Tires | ✓ Tire(s) replaced       | 03/21/2026 |

This car has been recently serviced. That's a good thing!




### CARFAX History-Based Value Report

**\$14,680**  
CARFAX Retail Value

#### History events affecting this vehicle's value

- ↑ ✓ No Accidents Reported
- ↑ ✂ Service History

  Non-Personal Vehicle



|  <b>Additional History</b><br>Not all accidents / issues are reported to CARFAX |  Owner 1 |  Owner 2 |
|---|---|---|
| <b>Total Loss</b><br>No total loss reported to CARFAX.  | <input checked="" type="checkbox"/> No Issues Reported                                      | <input checked="" type="checkbox"/> No Issues Reported                                      |
| <b>Structural Damage</b><br>No structural damage reported to CARFAX.  | <input checked="" type="checkbox"/> No Issues Reported                                      | <input checked="" type="checkbox"/> No Issues Reported                                      |
| <b>Airbag Deployment</b><br>No airbag deployment reported to CARFAX.  | <input checked="" type="checkbox"/> No Issues Reported                                      | <input checked="" type="checkbox"/> No Issues Reported                                      |
| <b>Odometer Check</b><br>No indication of an odometer rollback.   | <input checked="" type="checkbox"/> No Issues Indicated                                     | <input checked="" type="checkbox"/> No Issues Indicated                                     |
| <b>Accident / Damage</b><br>No accidents or damage reported to CARFAX.  | <input checked="" type="checkbox"/> No Issues Reported                                      | <input checked="" type="checkbox"/> No Issues Reported                                      |
| <b>Manufacturer Recall</b><br>No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.                                      | <input checked="" type="checkbox"/> No Recalls Reported                                     | <input checked="" type="checkbox"/> No Recalls Reported                                     |
| <b>Basic Warranty</b><br>Original warranty estimated to have expired.   | Warranty Expired  | Warranty Expired  |





|  <b>Title History</b><br>CARFAX guarantees the information in this section |  Owner 1 |  Owner 2 |
|--|---|---|
| <b>Damage Brands</b><br>Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon   | <input checked="" type="checkbox"/> <b>Guaranteed</b><br>No Problem                         | <input checked="" type="checkbox"/> <b>Guaranteed</b><br>No Problem                         |
| <b>Odometer Brands</b><br>Not Actual Mileage   Exceeds Mechanical Limits   | <input checked="" type="checkbox"/> <b>Guaranteed</b><br>No Problem                         | <input checked="" type="checkbox"/> <b>Guaranteed</b><br>No Problem                         |




**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)


|  <b>Ownership History</b><br>The number of owners is estimated |  Owner 1 |  Owner 2 |
|--|---|---|
| Year purchased   | 2019  | 2022  |
| Type of owner  | Rental  | Personal  |
| Estimated length of ownership  | 2 yrs. 3 mo.  | 3 yrs. 8 mo.  |
| Owned in the following states/provinces  | Illinois  | Iowa, Montana   |
| Estimated miles driven per year  | 22,109/yr   | 17,781/yr   |
| Last reported odometer reading   | 50,308  | 116,562   |

|  <b>Detailed History</b>            |         |                                |          |
|---|---------|--------------------------------|----------|
|  <b>Owner 1</b><br>Purchased: 2019 |         | Rental Vehicle<br>22,109 mi/yr |          |
| Date  | Mileage | Source                         | Comments |

|              |        |   |   |   |
|--------------|--------|---|---|---|
| Not Reported |        | General Motors  |   | <b>Original Window Sticker</b>  |
|              |        |   |   |   |
| 10/10/2019   |        | Illinois<br>Motor Vehicle Dept.   |   | <b>Vehicle purchase reported</b>  |
| 10/18/2019   | 5      | Illinois<br>Motor Vehicle Dept.<br>Chicago, IL<br>Title #192916953980   |   | <b>Title issued or updated</b><br>- Registration issued or renewed<br>- First owner reported<br>- Loan or lien reported<br>- Titled or registered as rental vehicle<br>- Vehicle color noted as Silver  |
| 10/28/2020   |        | Illinois<br>Motor Vehicle Dept.<br>Chicago, IL  |   | <b>Registration issued or renewed</b>   |
| 11/17/2021   |        | Illinois<br>Motor Vehicle Dept.<br>Chicago, IL  |   | <b>Registration issued or renewed</b>   |
| 11/22/2021   | 49,272 | Moore Cadillac Chantilly<br>Chantilly, VA<br>703-674-5900<br>moorecadillac.com<br>★ 4.6 / 5.0 640 Verified Reviews<br>❤️ 294 Customer Favorites             |    | <b>Vehicle serviced</b><br>- Maintenance inspection completed<br>- Camshaft(s) replaced/repared<br>- Computer(s) checked<br>- Cooling system bled<br>- Exhaust system checked<br>- No-start/hard start condition checked<br>- Oil and filter changed<br>- Vacuum pump replaced  |
| 01/17/2022   | 50,276 | Auto Auction  |   | <b>Vehicle sold</b><br><div style="border: 1px solid black; padding: 5px; margin-top: 5px;">Millions of used vehicles are bought and sold at auction every year.</div>  |
| 01/21/2022   |        | Buerkle Acura<br>Minneapolis, MN<br>★ 4.8 / 5.0 194 Verified Reviews<br>❤️ 135 Customer Favorites   |   | <b>Vehicle offered for sale</b>   |
| 02/08/2022   | 50,280 | Buerkle Acura<br>Minneapolis, MN<br>763-424-4545<br>buerkleacura.com<br>★ 4.8 / 5.0 194 Verified Reviews<br>❤️ 135 Customer Favorites                       |  | <b>Vehicle serviced</b><br>- Pre-delivery inspection completed<br>- Brakes checked<br>- Four tires replaced<br>- Oil and filter changed<br>- Tire(s) replaced<br><div style="border: 1px solid black; padding: 5px; margin-top: 5px;">Looks like this dealer serviced the car in order to prepare it for sale. That's a good thing!</div> |
| 02/17/2022   | 50,305 | Luther Brookdale Chevrolet<br>Minneapolis, MN<br>763-561-9220<br>brookdalechevrolet.com/<br>★ 4.5 / 5.0 757 Verified Reviews<br>❤️ 8,384 Customer Favorites |  | <b>Vehicle serviced</b><br>- Maintenance inspection completed<br>- Engine checked<br>- Vacuum pump replaced   |
| 04/27/2022   | 50,308 | Online Listing  |   | <b>Vehicle offered for sale</b>   |
| 05/23/2022   |        | Auto Auction  |   | <b>Listed as a dealer vehicle</b><br>- Vehicle sold   |

 **Owner 2**  
Purchased: 2022

Personal Vehicle  
17,781 mi/yr

| Date       | Mileage | Source  |   | Comments   |
|------------|---------|---|---|--|
| 08/05/2022 | 50,532  | Iowa<br>Motor Vehicle Dept.<br>Lake Park, IA<br>Title #30AB20517  |   | <b>Registration issued or renewed</b><br>- Title or registration issued<br>- New owner reported<br>- Correction to record<br>- Vehicle color noted as Silver             |
| 09/26/2022 |         | Iowa<br>Motor Vehicle Dept.<br>Terril, IA<br>Title #30AB20517   |   | <b>Registration issued or renewed</b><br>- Registration updated when owner moved the vehicle to a new location<br>- Vehicle color noted as Silver                        |
| 09/14/2023 |         | Iowa<br>Motor Vehicle Dept.<br>Terril, IA<br>Title #30AB20517   |   | <b>Registration issued or renewed</b><br>- Vehicle color noted as Silver   |
| 03/22/2024 | 86,231  | Okoboji Motor Company<br>Spirit Lake, IA<br>712-336-1500<br>okobojigmtoyota.com<br>★ 4.5 / 5.0 268 Verified Reviews<br>❤️ 3,139 Customer Favorites  |    | <b>Vehicle serviced</b><br>- Engine/powertrain computer/module reprogrammed<br>- Fuel system cleaned/serviced<br>- Induction system serviced<br>- Throttle body replaced |
| 10/01/2024 |         | Iowa<br>Motor Vehicle Dept.<br>Terril, IA<br>Title #30AB20517   |   | <b>Registration issued or renewed</b><br>- Vehicle color noted as Silver   |
| 09/17/2025 |         | Iowa<br>Motor Vehicle Dept.<br>Terril, IA<br>Title #30AB20517   |   | <b>Registration issued or renewed</b><br>- Vehicle color noted as Silver   |
| 02/24/2026 | 114,216 | Walmart Auto Care Center<br>Spirit Lake, IA<br>712-336-0966<br>https://www.walmart.com<br>★ 4.9 / 5.0 28 Verified Reviews<br>❤️ 1 Customer Favorite |  | <b>Vehicle serviced</b><br>- Tire pressure monitoring system checked<br>- Tire(s) replaced   |
| 03/21/2026 | 115,034 | Walmart Auto Care Center<br>Spirit Lake, IA<br>712-336-0966<br>https://www.walmart.com<br>★ 4.9 / 5.0 28 Verified Reviews<br>❤️ 1 Customer Favorite |  | <b>Vehicle serviced</b><br>- Tire(s) replaced  |
| 04/06/2026 |         | Montana<br>Motor Vehicle Dept.  |   | <b>Vehicle purchase reported</b>   |
| 04/30/2026 |         | Online Listing  |   | <b>Vehicle offered for sale</b>  |
| 05/01/2026 | 115,531 | Montana<br>Motor Vehicle Dept.<br>Helena, MT<br>Title #AB1991770  |   | <b>Dealer took title of this vehicle while it was in inventory</b><br>- Title or registration issued<br>- Vehicle color noted as Silver                                  |
| 05/13/2026 | 116,555 | Deery Brothers<br>West Burlington, IA<br>319-752-6000<br>deerybrothers.com/<br>★ 4.6 / 5.0 169 Verified Reviews<br>❤️ 1,182 Customer Favorites      |   | <b>Vehicle offered for sale</b>  |
| 05/14/2026 | 116,562 | Deery Brothers<br>West Burlington, IA<br>319-752-6000<br>deerybrothers.com/<br>★ 4.6 / 5.0 169 Verified Reviews                                     |  | <b>Vehicle serviced</b><br>- Maintenance inspection completed<br>- Air filter replaced<br>- Oil and filter changed   |