

Multi-Point Inspection Checklist

RO# 6035682

Customer Name INVENTORY: 968690

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 12/30/2025 2:35 PM

Printed on 1/21/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation fb 9mm rb 8mm
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 ft 7/32 rt 6/32
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emissions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In -Cabin Air Filter equipped Found the cabin and engine air filter to be dirty
- Battery cables and mount
- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips
- Dome , courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2024	CHEVROLET	SILVERADO 150
Vehicle Identification Number		Color
3GCPDKEK2RG264869		BLUE

6035682/1	Original	21336	21336
4WD CREW CAB	21336	JAKE BACHTTELL	

INVENTORY: 968690

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 Performed a 56 point inspection.	I	169.95
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 19419537 : N-OIL (08800-BOPCKT) 6@7.25 43.50 12735608 : SL-N-FILTER (01836-BCKT) 1@8.00 8.00 Changed the engine oil and filter.	I	
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95 Performed a 4 wheel alignment.	I	
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs 59.95 Balanced all four wheels and tires.	I	
#5 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 10.00 19338055 : SL-N-FILTER (09786-BOPCKT) 1@49.95 49.95	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone

R/O Open Date

R/O Number

12/30/25

6035682/2

Home Phone

R/O Close Date

Receipt No.

12/31/25

Original

Body

Mileage In

Mileage Out

4WD CREW CAB

21336

21336

License Number

Service Advisor

JAKE BACHTELL

Year

Make

Model

2024

CHEVROLET

SILVERADO 150

Vehicle Identification Number

Color

Account No.

Delivery Date

In-Service Date

3GCPDKK2RG264869

BLUE

INVENTORY: 968690

Replaced the cabin air filter.

#6 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER
REPLACEMENT

Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00

Work performed by Tech 329/9 * 0.10hrs 10.00

84121217 : SL-N-ELEMENT (03410-CT) 1@29.95 29.95

Replaced the engine air filter.

I

INTERNAL

SERVICE CONT.

WARRANTY

CUSTOMER PAY

COST

LABOR

483.55

PARTS

131.40

DEDUCTIBLE

SUBLET

SHOP SUPPLIES

29.99

HAZARDOUS MATERIALS

SALES TAX OR TAX I.D.

SPECIAL ORDER DEPOSIT

DISCOUNTS

644.94



This report provided free of charge by:

Deery Brothers

200 S Gear Ave
West Burlington, IA 52655

319-271-8758

★ **4.6 / 5.0**
147 Verified Reviews

♥ **102**
Customer Favorites



Vehicle History Report™

US \$44.99

2024 CHEVROLET SILVERADO 1500 LT

VIN: 3GCPDKEK2RG264869
CREW PICKUP
2.7L I4
GASOLINE
REAR WHEEL DRIVE W/ 4X4
Original Window Sticker

This CARFAX Report Provided by:

Deery Brothers

★ **4.6 / 5.0**
147 Verified Reviews
♥ **102** Customer Favorites

✓ No accidents or damage reported to CARFAX

✂ 4 Service history records

👤 2 Previous owners

🚗 Types of owners: Personal lease, Lease

🌍 Last owned in Michigan

📊 21,336 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 1/3/26 at 10:14:05 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	12/31/2025
 <div style="border: 1px solid #00aaff; padding: 5px; display: inline-block;"> <p>This car has been recently serviced. That's a good thing!</p> </div>		



Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Owner 2

Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have 18 months or 14,664 miles remaining. Confirm with dealer or vehicle manufacturer.	<input checked="" type="checkbox"/> Warranty Active	<input checked="" type="checkbox"/> Warranty Active

 Title History CARFAX guarantees the information in this section	Owner 1	Owner 2
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate		

 Ownership History The number of owners is estimated	Owner 1	Owner 2
Year purchased	2024	2025
Type of owner	Personal lease	Lease
Estimated length of ownership	1 yr. 6 mo.	2 days
Owned in the following states/provinces	Michigan	Michigan
Estimated miles driven per year	---	---
Last reported odometer reading	6,725	21,336



Detailed History



Owner 1
Purchased: 2024

Personal Lease
Vehicle

Date	Mileage	Source	Comments
Not Reported		General Motors	Original Window Sticker 
03/02/2024	11	Berger Chevrolet Grand Rapids, MI 616-949-5200 bergerchevy.com/ ★ 4.6 / 5.0 2,185 Verified Reviews ❤️ 22,453 Customer Favorites	Vehicle offered for sale
03/14/2024		Berger Chevrolet Grand Rapids, MI 616-949-5200 bergerchevy.com ★ 4.6 / 5.0 2,185 Verified Reviews ❤️ 22,453 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed - Vehicle washed/detailed
06/06/2024	61	Berger Chevrolet Grand Rapids, MI 616-949-5200 bergerchevy.com ★ 4.6 / 5.0 2,185 Verified Reviews ❤️ 22,453 Customer Favorites	Vehicle sold
06/06/2024		Berger Chevrolet Grand Rapids, MI 616-949-5200 bergerchevy.com ★ 4.6 / 5.0 2,185 Verified Reviews ❤️ 22,453 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Tonneau cover installed - Vehicle washed/detailed
06/06/2024		Michigan Motor Vehicle Dept. Jenison, MI	Vehicle purchase reported - Registration issued or renewed