

Multi-Point Inspection Checklist

RO# 6035468

Customer Name INVENTORY: 684571

Advisor Name JAKE BACHTTELL

Technician Name Dylan Miller

Created on 12/22/2025 1:35 PM

Printed on 1/2/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

Checked and OK at this time May Require Future Attention Requires immediate attention

Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation **fb 9mm rb 8mm**
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 **ft 5/32 rt 5/32**
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emmisions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In -Cabin Air Filter equipped **Found the cabin and engine air filter to be dity.**
- Battery cables and mount
- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips
- Dome , courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DERRY BROTHERS
 200 S Gear Ave
 West Burlington, IA 52655

| | | |
|----------------|-----------------|-----------------|
| Work Phone | R/O Open Date | R/O Number |
| Home Phone | R/O Close Date | Receipt No. |
| Body | Mileage In | Mileage Out |
| License Number | Service Advisor | |
| Account No. | Delivery Date | In-Service Date |

| | | |
|-------------------------------|------|---------|
| Year | Make | Model |
| 2020 | GMC | TERRAIN |
| Vehicle Identification Number | | Color |
| 3GKALVEV9LL345469 | | WHITE |

| | | |
|----------------|---------|---------|
| SUV | 92868 | 92868 |
| JAKE BACHTTELL | 2/01/21 | 2/01/21 |

INVENTORY: 684571

| | | |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---|--|
| #1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 25206966 : SL-N-FILTER (01836-BCKT) 1@12.71 12.71 19432337 : N-OIL (08800-BOPCK) 6@8.92 53.52 | I | |
| #2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 169.95 | I | |
| #3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs 59.95 | I | |
| #4 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95 | I | |
| #5 - RECALL: CHECK FOR OPEN RECALLS Corrected by NRF: NO RECALLS FOUND FOR VEHICLE AT THIS TIME. LRATE:180.14 Work performed by Tech 329/9 0.00hrs @ | I | |
| #6 * RECALL: CHECK FOR OPEN RECALLS perform recall N232403240 Caused by performed recall Corrected by 9106808: CHECK FOR OPEN RECALLS performed recall LRATE:165.53 | W | |

| | INTERNAL | SERVICE CONT. | WARRANTY | CUSTOMER PAY | COST |
|-----------------------|----------|---------------|----------|--------------|------|
| LABOR | | | | | |
| PARTS | | | | | |
| DEDUCTIBLE | | | | | |
| SUBLET | | | | | |
| SHOP SUPPLIES | | | | | |
| HAZARDOUS MATERIALS | | | | | |
| SALES TAX OR TAX I.D. | | | | | |
| SPECIAL ORDER DEPOSIT | | | | | |
| DISCOUNTS | | | | | |

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
 200 S Gear Ave
 West Burlington, IA 52655

| | | | | | |
|-------------------------------|------|---------|----------------|-----------------|-------------|
| Year | Make | Model | Work Phone | R/O Open Date | R/O Number |
| 2020 | GMC | TERRAIN | Home Phone | 12/22/25 | 6035468/2 |
| Vehicle Identification Number | | Color | Body | R/O Close Date | Receipt No. |
| 3GKALVEV9LL345469 | | WHITE | SUV | 12/27/25 | Original |
| INVENTORY: 684571 | | | License Number | Mileage In | Mileage Out |
| | | | | 92868 | 92868 |
| | | | Account No. | Service Advisor | |
| | | | | JAKE BACHTELL | |
| | | | Delivery Date | In-Service Date | |
| | | | 2/01/21 | 2/01/21 | |

Work performed by Tech 461/4 0.20hrs @ 165.55
 performed recall as per bulletin# N232403240-02
 Inspect Only No Further Action Required
 labor code# 9106808
 lt 0.2hrs

33.11

#7 * ICF: REPLACED IN CABIN AIR FILTER
 Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00
 Work performed by Tech 329/9 * 0.10hrs
 19338054 : SL-N-FILTER (09786-BOPCKT) 1@29.95

I

10.00
 29.95

#8 * AF: REPLACED ENGINE AIR FILTER
 Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00
 Work performed by Tech 329/9 * 0.10hrs
 84390002 : SL-N-ELEMENT (03410-CT) 1@49.95

I

10.00
 49.95

| | INTERNAL | SERVICE CONT. | WARRANTY | CUSTOMER PAY | COST |
|-----------------------|----------|---------------|----------|--------------|------|
| LABOR | 483.55 | | 33.11 | | |
| PARTS | 146.13 | | | | |
| DEDUCTIBLE | | | | | |
| SUBLET | | | | | |
| SHOP SUPPLIES | 29.99 | | | | |
| HAZARDOUS MATERIALS | | | | | |
| SALES TAX OR TAX I.D. | | | | | |
| SPECIAL ORDER DEPOSIT | | | | | |
| DISCOUNTS | | | | | |
| | 659.67 | | 33.11 | | |

Display CARFAX in online listings:



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
147 Verified Reviews

♥ **102**
Customer Favorites



Vehicle History Report™

US \$44.99

2020 GMC TERRAIN SLT

VIN: 3GKALVEV9LL345469
4 DOOR WAGON/SPORT
UTILITY
1.5L I4 F DOHC 16V
GASOLINE
ALL WHEEL DRIVE
Original Window Sticker
This CARFAX Report Provided
by:

Deery Brothers

★ **4.6 / 5.0**

147 Verified Reviews

♥ **102** Customer Favorites



No accidents or damage reported to CARFAX



Regular oil changes



Great Reliability



CARFAX 1-Owner vehicle



Personal vehicle



92,868 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 1/2/26 at 3:15:18 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Recent Service Highlights

Key services performed in the last 12 months

| Service | Comments | Date |
|---------|--------------------------|------------|
| Oil | ✓ Oil and filter changed | 12/27/2025 |
| Tires | ✓ Tires rotated | 12/27/2025 |





This car has been recently serviced. That's a good thing!

CARFAX Reliability Forecast

Based on 2020 GMC Terrain SLT with similar mileage

3-Year Reliability Forecast



Fair Reliability Good Reliability **Great Reliability**

Good news! This vehicle is expected to have low risk of repair and average repair costs.



What makes this vehicle have great reliability?

- Top 25%** compared to similar vehicles
- Average Repair Cost**
\$360 avg per year
- Oil Changes** performed regularly
- Low Likelihood of Repair**

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss

No total loss reported to CARFAX.

No Issues Reported

Structural Damage

No structural damage reported to CARFAX.

No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.

No Issues Reported

Odometer Check

No indication of an odometer rollback.

No Issues Indicated

Accident / Damage

No accidents or damage reported to CARFAX.

No Issues Reported

Manufacturer Recall

No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.

No Recalls Reported

Basic Warranty

Original warranty estimated to have expired.

Warranty Expired

CARFAX Title History

CARFAX guarantees the information in this section

Owner 1

Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

Guaranteed
No Problem**Odometer Brands**

Not Actual Mileage | Exceeds Mechanical Limits

Guaranteed
No Problem**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)**Ownership History**

The number of owners is estimated

Owner 1

Year purchased

2021

Type of owner

Personal

Estimated length of ownership

4 yrs. 10 mo.

Owned in the following states/provinces

Iowa

Estimated miles driven per year

18,951/yr

Last reported odometer reading

92,868

**Detailed History** **Owner 1**

Purchased: 2021

Personal Vehicle

18,951 mi/yr

Date**Mileage****Source****Comments**

Not Reported

General Motors

Original Window Sticker

10/06/2020 4

Deery Brothers
West Burlington, IA
319-752-6000
deerybrothers.com**Vehicle serviced**- Pre-delivery inspection completed
- Oil and filter changed **4.6 / 5.0**

147 Verified Reviews

102 Customer Favorites