

Multi-Point Inspection Checklist

RO# 6035141

Customer Name INVENTORY: 968480

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 12/11/2025 8:25 AM

Printed on 12/17/2025

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

- | | | | |
|--|---|---|--|
|  |  |  | Cold Engine start-up |
|  |  |  | Engine operation warm-up |
|  |  |  | Engine at normal operating temperature |
|  |  |  | Brake and parking operation <u>fb 9mm rb 8mm</u> |
|  |  |  | Active seat belt test |
|  |  |  | Clutch and transmission operations |
|  |  |  | Overdrive operation |
|  |  |  | Transfer case operation (4-wheel drive only) |
|  |  |  | Steering operation and off center |
|  |  |  | Front end alignment |
|  |  |  | Tilt steering wheel operation |
|  |  |  | Windshield wiper and washer operation at all speeds, wiper blade condition |
|  |  |  | Speedometer and odometer operation |
|  |  |  | Cruise Control operation, including resume |
|  |  |  | Heater and air condition operation |
|  |  |  | Abnormal noises and vibrations |
|  |  |  | Squeaks and rattles |
|  |  |  | Frame Check |
|  |  |  | Body surface, lower body, and upper body damage requiring body shop repair |
|  |  |  | Tire defects and damage, 5/32 <u>ft 5/32 rt 6/32</u> |
|  |  |  | Drive shaft, joints, CV's and boots |
|  |  |  | Struts/shock absorbers, leaks and wear |
|  |  |  | Exhaust system leaks and damage, including catalytic converter |
|  |  |  | Fuel, oil, coolant, or other fluid leaks |
|  |  |  | Perform emissions test and/or state inspection if required |
|  |  |  | Under hood labels and decals |
|  |  |  | Air filter and In-Cabin Air Filter equipped <u>Found the cabin and engine air filter to be dirty</u> |
|  |  |  | Battery cables and mount |
|  |  |  | Coolant level and test |
|  |  |  | Under hood fluid levels, including transmission and transfer case fluids |
|  |  |  | Drive belts and hoses |
|  |  |  | Air conditioning levels, check at sight glass |
|  |  |  | Warning lights (including air bag) gauges & horn |
|  |  |  | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light |
|  |  |  | Inside and outside rearview mirror operation, adjustment, and condition |
|  |  |  | Glass free of cracks, starts and large chips |
|  |  |  | Dome , courtesy, map and sun visor lights and lighters and power ports |

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone			R/O Open Date	R/O Number
Home Phone			12/11/25	6035141/1
Body			R/O Close Date	Receipt No.
AWD 4DR LT W/			12/12/25	Original
License Number			Mileage In	Mileage Out
			25979	25979
Year	Make	Model	Service Advisor	
2025	CHEVROLET	EQUINOX	JAKE BACHTELL	
Vehicle Identification Number		Color	Account No.	Delivery Date
3GNAXPEG5SL277870		GRAY		In-Service Date

INVENTORY: 968480

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 Performed a 56 point inspection.	I	169.95
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 19432337 : N-OIL (08800-BOPCK) 5@8.92 44.60 25206966 : SL-N-FILTER (01836-BCKT) 1@12.71 12.71 Changed the engine oil and filter.	I	73.70 44.60 12.71
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95 Performed a 4 wheel alignment.	I	159.95
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs 59.95 Balanced all four wheels and tires.	I	59.95
#5 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 10.00 19338054 : SL-N-FILTER (09786-BOPCKT) 1@29.95 29.95	I	10.00 29.95

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
 200 S Gear Ave
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2025	CHEVROLET	EQUINOX
Vehicle Identification Number	Color	
3GNAXPEG5SL277870	GRAY	

12/11/25	6035141/2
12/12/25	Original
25979	25979
JAKE BACHTELL	

INVENTORY: 968480

Replaced the cabin air filter.

#6 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER
 REPLACEMENT
 Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00
 Work performed by Tech 329/9 * 0.10hrs 10.00
 84390002 : SL-N-ELEMENT (03410-CT) 1@49.95 49.95
 Replaced the engine air filter.

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	483.55				
PARTS	137.21				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	650.75				



This report provided free of charge by:

Deery Brothers
 200 S Gear Ave
 West Burlington, IA 52655
 319-271-8758

★ **4.6 / 5.0**
 147 Verified Reviews

♥ **102**
 Customer Favorites



Vehicle History Report™

US \$44.99

2025 CHEVROLET EQUINOX LT
 VIN: 3GNAXPEG5SL277870
 4 DOOR WAGON/SPORT UTILITY
 1.5L I4 GASOLINE
 ALL WHEEL DRIVE
 Original Window Sticker
 This CARFAX Report Provided by:
Deery Brothers
 ★ 4.6 / 5.0
 147 Verified Reviews
 ♥ 102 Customer Favorites

-  No accidents or damage reported to CARFAX
-  **3** Service history records
-  CARFAX 1-Owner vehicle
-  Rental vehicle
-  Last owned in Montana
-  **25,979** Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 12/15/25 at 5:42:58 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
 Oil	 Oil and filter changed	12/12/2025
 Tires	 Tires rotated	12/12/2025



This car has been recently serviced. That's a good thing!

 Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have 27 months or 10,021 miles remaining. Confirm with dealer or vehicle manufacturer.	<input checked="" type="checkbox"/> Warranty Active

 Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

 Ownership History The number of owners is estimated	Owner 1
Year purchased	2025
Type of owner	Rental
Estimated length of ownership	9 months
Owned in the following states/provinces	California, Montana
Estimated miles driven per year	---



Last reported odometer reading

25,979



Detailed History



Owner 1

Purchased: 2025

Rental Vehicle

Date	Mileage	Source	Comments
Not Reported		General Motors	Original Window Sticker 
02/24/2025	10	California Motor Vehicle Dept. South San Francisco, CA	Title issued or updated - First owner reported - Loan or lien reported - Titled or registered as rental vehicle
05/20/2025	10,645	Take 5 Oil Change Antioch, TN 615-649-6351 take5oilchange.com ★ 4.7 / 5.0 75 Verified Reviews	 Vehicle serviced - Oil and filter changed
09/29/2025	20,652	Take 5 Oil Change Donelson, TN 615-953-7009 take5oilchange.com ★ 4.4 / 5.0 101 Verified Reviews	 Vehicle serviced - Oil and filter changed
12/02/2025		Online Listing	Vehicle offered for sale
12/05/2025	25,971	Montana Motor Vehicle Dept. Helena, MT	Vehicle purchase reported - Dealer took title of this vehicle while it was in inventory - Title or registration issued - Vehicle color noted as Gray
12/11/2025		Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 147 Verified Reviews	Vehicle offered for sale