

# Multi-Point Inspection Checklist

RO# 6038250

Customer Name INVENTORY: 969280

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 3/26/2026 1:19 PM

Printed on 4/3/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

- Checked and OK at this time    
  May Require Future Attention    
  Requires immediate attention

## Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation fb 8mm rb 7mm
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 ft 5/32 rt 4/32
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emissions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In-Cabin Air Filter equipped Found the cabin and engine air filter to be dirty.
- Battery cables and mount
- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips
- Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician \_\_\_\_\_ Date \_\_\_\_\_

Service Manager \_\_\_\_\_ Date \_\_\_\_\_

Used Car Manager \_\_\_\_\_ Date \_\_\_\_\_

Customer \_\_\_\_\_ Date \_\_\_\_\_

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2025	GMC	SIERRA 1500
Vehicle Identification Number		Color
3GTUUED2SG199382		BLACK

3/26/26	6038250/1
3/27/26	Original
29585	29585
JAKE BACHTELL	

INVENTORY: 969280

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 169.95 Performed a 56 point inspection.	I
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 19432337 : N-OIL (08800-BOPCK) 8@9.60 76.80 12735811 : SL-N-FILTER (01836-BOPCKT) 1@6.95 6.95 Changed the engine oil and filter.	I
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95 Performed a 4 wheel alignment.	I
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs 99.00 Balanced all four wheels and tires.	I
#5 - RECALL: CHECK FOR OPEN RECALLS PERFORM RECALL N252494770 Caused by Recall. Corrected by 9107856: CHECK FOR OPEN RECALLS Recall. LRATE:165.53 Work performed by Tech 329/9 0.10hrs @ 165.50 16.55	W

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
 200 S Gear Ave  
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2025	GMC	SIERRA 1500
Vehicle Identification Number		Color
3GTUDED2SG199382		BLACK

3/26/26	6038250/2
3/27/26	Original
29585	29585
JAKE BACHTTELL	

INVENTORY: 969280

Installed paper work in owners manual.

#6 \* ICF: REPLACED IN CABIN AIR FILTER \*CABIN AIR FILTER REPLACEMENT  
 Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00  
 Work performed by Tech 329/9 \* 0.10hrs 12.00  
 19338055 : SL-N-FILTER (09786-BOPCKT) 1@29.95 29.95  
 Replaced the cabin air filter.

#7 \* AF: REPLACED ENGINE AIR FILTER \*ENGINE AIR FILTER REPLACEMENT  
 Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00  
 Work performed by Tech 329/9 \* 0.10hrs 12.00  
 84121217 : SL-N-ELEMENT (03410-CT) 1@49.95 49.95  
 Replaced the engine air filter.

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	526.60		16.55		
PARTS	163.65				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	720.24		16.55		



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
159 Verified Reviews

♥ **101**  
Customer Favorites



## Report

US \$44.99

### 2025 GMC Sierra 1500 SLT

29,585 mi | VIN: 3GTUUED2SG199382 |

Crew Pickup | 5.3L V8 F OHV 16V | Gasoline | Rear wheel drive w/ 4X4

CARFAX HAS THE MOST  
ACCIDENT & DAMAGE  
INFORMATION



✂ 3 Service history records

1 CARFAX 1-Owner vehicle

🚗 Rental vehicle

🌍 Last owned in Idaho

📄 10 Detailed records available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/31/26 at 6:12:33 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### CARFAX Accident / Damage History


Not all accidents / issues are reported to CARFAX

Event 1

04/16/2025

**Damage reported: minor damage**


Damage Severity Scale




### CARFAX Recent Service Highlights


Key services performed in the last 12 months

Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	03/27/2026

 **Tires**


 **Tires rotated**

03/27/2026











This car has been recently serviced. That's a good thing!

<b>CARFAX Additional History</b> Not all accidents / issues are reported to CARFAX	Owner 1
<b>Total Loss</b> No total loss reported to CARFAX.	✔ No Issues Reported
<b>Structural Damage</b> CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	✔ No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	✔ No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	✔ No Issues Indicated
<b>Accident / Damage</b> Damage reported: 04/16/2025.	Minor Damage
<b>Manufacturer Recall</b> No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	✔ No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have 21 months or 6,415 miles remaining. Confirm with dealer or vehicle manufacturer.	✔ Warranty Active

<b>CARFAX Title History</b> CARFAX guarantees the information in this section	Owner 1
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	✔ Guaranteed No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	✔ Guaranteed No Problem
 <b>GUARANTEED</b> - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. <a href="#">View Terms</a>   <a href="#">View Certificate</a>	

<b>CARFAX Ownership History</b> The number of owners is estimated	Owner 1
Year purchased	2024
Type of owner	Rental
Estimated length of ownership	1 yr. 1 mo.
Owned in the following states/provinces	Idaho
Estimated miles driven per year	--
Last reported odometer reading	29,585

<b>CARFAX Detailed History</b>			
	Owner 1		Rental Vehicle
	Purchased: 2024		
Date	Mileage	Source	Comments

Not Reported		General Motors	<b>Original Window Sticker</b> 
12/09/2024	10	Idaho Motor Vehicle Dept.	<b>Vehicle purchase reported</b> - Titled or registered as rental vehicle
12/14/2024		Idaho Motor Vehicle Dept. Meridian, ID Title #240782414	<b>Title issued or updated</b> - First owner reported - Vehicle color noted as Black
04/16/2025		Damage Report	<b>Damage reported: minor damage</b> - Damage to front
<p><b>CARFAX HAS THE MOST ACCIDENT &amp; DAMAGE INFORMATION</b></p> 		<p><b>Damage Severity Scale</b></p> 	
		<p><b>Damage Location</b></p> 	
		 <p>Minor damage is usually cosmetic, including dents or scratches to the vehicle body.</p>	
10/10/2025	19,740	Dennis Dillon Auto Park Boise, ID 208-388-4444 dennisdillon.com ★ 4.4 / 5.0 292 Verified Reviews ❤️ 412 Customer Favorites	 <b>Vehicle serviced</b> - Accessories installed
12/08/2025		Idaho Motor Vehicle Dept. Meridian, ID Title #240782414	<b>Registration issued or renewed</b> - Vehicle color noted as Black
01/09/2026		Online Listing	<b>Vehicle offered for sale</b>
02/26/2026		AutoGlassNow 888-434-9452 autoglassnow.com/ ★ 4.8 / 5.0 1,575 Verified Reviews	 <b>Vehicle serviced</b> - Glass repaired
03/06/2026	27,867	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 159 Verified Reviews	<b>Vehicle offered for sale</b>