

Multi-Point Inspection Checklist

RO# 6035483

Customer Name INVENTORY: 739371

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 12/23/2025 7:33 AM

Printed on 2/4/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

Checked and OK at this time May Require Future Attention Requires immediate attention

Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation fb 9mm rb 8mm
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 ft 4/32 rt 3/32
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks Found the oil pan to be leaking
- Perform emissions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In -Cabin Air Filter equipped Found the cabin and engine air filter to be dirty
- Battery cables and mount

- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips
- Dome , courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Year		Make	Model	License Number	Service Advisor
2022		GMC	SIERRA 1500		JAKE BACHTELL
Vehicle Identification Number			Color	Account No.	Delivery Date
3GTUUEET2NG538840					

Work Phone	R/O Open Date	R/O Number
	12/23/25	6035483/1
Home Phone	R/O Close Date	Receipt No.
	1/23/26	Original
Body	Mileage In	Mileage Out
TRUCK	55896	55896

INVENTORY: 739371

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95	169.95	I
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 19370138 : N-OIL (08800-BOPCKT) 7@9.33 12735608 : SL-N-FILTER (01836-BCKT) 1@8.00	73.70 65.31 8.00	I
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs	159.95	I
#5 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 19338054 : SL-N-FILTER (09786-BOPCKT) 1@29.95	10.00 29.95	I
#6 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 84121219 : SL-N-ELEMENT (03410-CT) 1@49.95	10.00 49.95	I
#7 * 0999: MISCELLANEOUS REPAIR - MAINTENANCE ITEMS c/s they have an oil leak check and advise		W

	INTERNAL	SERVICE CONT	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Year	Make	Model	License Number	Service Advisor
2022	GMC	SIERRA 1500		JAKE BÄCHTELL
Vehicle Identification Number		Color	Account No.	Delivery Date
3GTUUEET2NG538840				

Work Phone	R/O Open Date	R/O Number
	12/23/25	6035483/2
Home Phone	R/O Close Date	Receipt No.
	1/23/26	Original
Body	Mileage In	Mileage Out
TRUCK	55896	55896

INVENTORY: 739371

Caused by Found the lower oil pan to be leaking.
Corrected by 4065910: (6061) LOWER OIL PAN REPLACEMENT
Found the lower oil pan to be leaking. LRATE:165.5
3 improperly sealed LRATE:165.53
Work performed by Tech 329/9 6.20hrs @ 165.53 1026.29
Caused by improperly sealed
Work performed by Tech 329/9 0.00hrs @
19369831 : N-SEALANT (08800-BOPCKT) 1@50.73 50.73
55506665 : SL-N-PAN (01426-CT) 1@87.32 87.32
Drained the oil and removed the front differential. Once the front differential was removed I removed the lower oil pan and installed a new one with engine sealant on the new oil pan. After installing the new oil pan i reinstalled the front differential and engine covers.

#8 * 4T: REPLACE 4 TIRES MOUNT & BALANCE . INCLUDES WITH PURCHASE OF THESE TIRES - ORIGINAL OWNER WILL RECEIVE TIRE ROTATIONS FOR LIFE OF TIRE AND ONE YEAR DEERY ROAD HAZARD
Corrected by 4T: REPLACE 4 TIRES MOUNT & BALANCE . INCLUDES WITH PURCHASE OF THESE TIRES - ORIGINAL OWNER WILL RECEIVE TIRE ROTATIONS FOR LIFE OF TIRE AND ONE YEAR DEERY ROAD HAZARD LRATE:.00
Work performed by Tech 329/9 * 1.20hrs 100.00
19472113 : N-GY2656020 (05880-BOPCKT) 4@682.27 2729.08
Mounted and balanced 4 new tires.

#9 * 0999: MISCELLANEOUS REPAIR - MAINTENANCE ITEMS verified vehicle has a second oil leak as well after oil pan replacement started
Caused by Front crank seal leaking.
Corrected by 4063430: (4061) CRANKSHAFT FRONT OIL SEAL REPLACEMENT Front crank seal leaking. LRATE:165.53
Corrected by 4063430: CRANKSHAFT FRONT OIL SEAL REPLACEMENT Front crank seal leaking. LRATE:165.53
Work performed by Tech 329/9 7.00hrs @ 165.53 1158.71

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
 200 S Gear Ave
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2022	GMC	SIERRA 1500
Vehicle Identification Number		Color
3GTUUEET2NG538840		

12/23/25	6035483/3
1/23/26	Original
55896	55896
JAKE BACHTELL	

INVENTORY: 739371

55509254 : SL-N-SEAL (00213-CT)	1@15.97	15.97	
Found the front crank seal to be leaking. Removed the front clip and coolant pack. Once I removed the front clip and coolant pack I removed the serpentine belt and front crank cover. One I removed the front crank cover i installed a new one with engine sealant and re installed all components. Vehicle is not leaking any oil at this time.			
Total Fee Amounts		34.00	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	523.60		2185.00		
PARTS	2882.29		154.02		
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	3469.88		2339.02		

Display CARFAX in online listings:

This report provided free of charge by:



Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
149 Verified Reviews

♥ **101**
Customer Favorites



Vehicle History Report™

US \$44.99

2022 GMC SIERRA 1500 AT4
VIN: 3GTUUEET2NG538840
CREW PICKUP
3.0L I6
DIESEL
REAR WHEEL DRIVE W/ 4X4
Original Window Sticker
This CARFAX Report Provided by:
Deery Brothers
★ 4.6 / 5.0
149 Verified Reviews
♥ 101 Customer Favorites

- No accidents or damage reported to CARFAX
-  Regular oil changes
-  CARFAX 1-Owner vehicle
-  Personal vehicle
-  Last owned in Minnesota
-  **55,909** Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 1/26/26 at 10:07:50 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
 Oil	<input checked="" type="checkbox"/> Oil and filter changed	01/20/2026
 Tires	<input checked="" type="checkbox"/> Four tires replaced	01/20/2026

