

Multi-Point Inspection Checklist

RO# 6036553

Customer Name INVENTORY: 968731

Advisor Name JAKE BACHTTELL

Technician Name JACOB BLAKEMAN

Created on 1/29/2026 5:17 PM

Printed on 2/4/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation **fb 8mm rb 7m**
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 **ft 10/32 rt 9/32**
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emissions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In-Cabin Air Filter equipped **Found the engine air filter to be dirty.**
- Battery cables and mount

- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips
- Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER **Found front license plate bracket to be missing**
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DE. RY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone			R/O Open Date	R/O Number
Home Phone			1/29/26	6036553/1
Body			R/O Close Date	Receipt No.
SEDAN			1/31/26	Original
License Number			Mileage In	Mileage Out
			57876	57876
Year	Make	Model	Service Advisor	
2021	HYUNDAI	ACCENT	JAKE BACHTTELL	
Vehicle Identification Number		Color	Account No.	Delivery Date
3KPC24A69ME137842		WHITE		In-Service Date

INVENTORY: 968731

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 Performed a 56 point inspection.		I	169.95
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 19432337 : N-OIL (08800-BOPCK) 5@8.92 44.60 PO99518EX : OIL FILTER 1@19.11 19.11 Changed the engine oil and filter.		I	
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95 Performed a 4 wheel alignment.		I	
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs 59.95 Balanced all four wheels and tires.		I	
#5 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 10.00 PA99485 : AIR FILTER 1@29.95 29.95		I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEJRY BROTHERS
 200 S Gear Ave
 West Burlington, IA 52655

Year	Make	Model	License Number	Service Advisor
2021	HYUNDAI	ACCENT		JAKE BACHTELL
Vehicle Identification Number		Color	Account No.	Delivery Date
3KPC24A69ME137842		WHITE		

Work Phone	R/O Open Date	R/O Number
	1/29/26	6036553/2
Home Phone	R/O Close Date	Receipt No.
	1/31/26	Original
Body	Mileage In	Mileage Out
SEDAN	57876	57876

INVENTORY: 968731

Replaced the engine air filter.

#6 * BRACKET: INSTALL LICENSE PLATE BRACKET

Corrected by SOP: PARTS TO REPAIR YOUR VEHICLE HAD TO BE SPECIAL ORDERED. WE WILL CONTACT YOU AS SOON AS WE RECEIVE THE REQUIRED PARTS TO REPAIR YOUR VEHICLE. IF YOU HAVE ANY FURTHER QUESTIONS PLEASE CONTACT THE SERVICE RATE:180.14

Work performed by Tech 329/9 0.00hrs @
 86519-J0000 : PLATE BRACKET 1@70.37 Ordered

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	473.55				
PARTS	93.66				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	597.20				



This report provided free of charge by:

Deery Brothers
 200 S Gear Ave
 West Burlington, IA 52655
 319-271-8758

★ **4.6 / 5.0**
 151 Verified Reviews

♥ **101**
 Customer Favorites



Vehicle History Report™

US \$44.99

2021 HYUNDAI ACCENT SE

VIN: 3KPC24A69ME137842
 SEDAN 4 DR
 1.6L I4 F DOHC 16V
 GASOLINE
 FRONT WHEEL DRIVE
 Original Window Sticker

This CARFAX Report Provided by:

Deery Brothers

★ **4.6 / 5.0**
 151 Verified Reviews
 ♥ **101** Customer Favorites

✓ No accidents or damage reported to CARFAX

🔧 **4** Service history records

📁 At least 1 open recall

👥 **3** Previous owners

🚗 Types of owners: Corporate fleet, Personal

📊 **54,369** Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 1/31/26 at 11:57:58 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

	Additional History		
Not all accidents / issues are reported to CARFAX	Owner 1	Owner 2	Owner 3
Total Loss No total loss reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported
Structural Damage No structural damage reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported
Odometer Check No indication of an odometer rollback.	✓ No Issues Indicated	✓ No Issues Indicated	✓ No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	✓ No Issues Reported	✓ No Issues Reported	✓ No Issues Reported

Manufacturer Recall At least 1 manufacturer recall requires repair. Most recalls can be repaired free of charge.	Recall Reported	No New Recalls Reported	No New Recalls Reported
Basic Warranty Original warranty estimated to have 3 months or 5,631 miles remaining. Confirm with dealer or vehicle manufacturer.	<input checked="" type="checkbox"/> Warranty Active	<input checked="" type="checkbox"/> Warranty Active	<input checked="" type="checkbox"/> Warranty Active

 Title History CARFAX guarantees the information in this section	Owner 1	Owner 2	Owner 3
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

 Ownership History The number of owners is estimated	Owner 1	Owner 2	Owner 3
Year purchased	2021	2023	2025
Type of owner	Corporate fleet	Personal	Personal
Estimated length of ownership	2 yrs. 2 mo.	2 years	5 months
Owned in the following states/provinces	Kansas, Alabama	Alabama	Iowa
Estimated miles driven per year	12,927/yr	---	---
Last reported odometer reading	28,986	37,556	54,369

 Detailed History			
 Owner 1 Purchased: 2021		<div style="border: 1px solid #00aaff; padding: 5px;"> Low mileage! This owner drove less than the industry average of 15,000 miles per year. </div>	Corporate Fleet Vehicle 12,927 mi/yr
Date	Mileage	Source	Comments