

# Multi-Point Inspection Checklist

RO# 6036202

Customer Name INVENTORY: 1289651

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 1/19/2026 1:35 PM

Printed on 1/26/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

-    Cold Engine start-up Pass
-    Engine operation warm-up Pass
-    Engine at normal operating temperature Pass
-    Brake and parking operation Pass
-    Active seat belt test Pass
-    Clutch and transmission operations Pass
-    Overdrive operation Pass
-    Transfer case operation (4-wheel drive only) Pass
-    Steering operation and off center Pass
-    Front end alignment Pass
-    Tilt steering wheel operation Pass
-    Windshield wiper and washer operation at all speeds, wiper blade condition Pass
-    Speedometer and odometer operation Pass
-    Cruise Control operation, including resume Pass
-    Heater and air condition operation Pass
-    Abnormal noises and vibrations Pass
-    Squeaks and rattles Pass
-    Frame Check Pass
-    Body surface, lower body, and upper body damage requiring body shop repair Pass
-    Tire defects and damage, 5/32 Fail 3/32 all
-    Drive shaft, joints, CV's and boots Pass
-    Struts/shock absorbers, leaks and wear Pass
-    Exhaust system leaks and damage, including catalytic converter Pass
-    Fuel, oil, coolant, or other fluid leaks Pass
-    Perform emissions test and/or state inspection if required Pass
-    Under hood labels and decals Pass
-    Air filter and In-Cabin Air Filter equipped Pass
-    Battery cables and mount Pass
-    Coolant level and test Pass
-    Under hood fluid levels, including transmission and transfer case fluids Pass
-    Drive belts and hoses Pass
-    Air conditioning levels, check at sight glass Pass
-    Warning lights (including air bag) gauges & horn Pass
-    Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-    Inside and outside rearview mirror operation, adjustment, and condition Pass
-    Glass free of cracks, starts and large chips Pass
-    Dome, courtesy, map and sun visor lights and lighters and power ports Pass

- Window operation Pass
- Sunroof or convertible top operation Pass
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance Pass
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 7mm all
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL Pass
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician \_\_\_\_\_ Date \_\_\_\_\_

Service Manager \_\_\_\_\_ Date \_\_\_\_\_

Used Car Manager \_\_\_\_\_ Date \_\_\_\_\_

Customer \_\_\_\_\_ Date \_\_\_\_\_

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
	1/19/26	6036202/1
Home Phone	R/O Close Date	Receipt No.
	1/21/26	Original
Body	Mileage In	Mileage Out
SEDAN	48882	48882

Year	Make	Model	License Number	Service Advisor
2017	LINCOLN	MKZ		AMANDA KEPHART
Vehicle Identification Number		Color	Account No.	Delivery Date
3LN6L5D90HR659646				

INVENTORY: 1289651

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 256/ 0.40hrs @ 184.25 73.70 19419537 : N-OIL (08800-BOPCKT) 6@7.25 43.50 R85348 : FILTER 1@6.14 6.14	I
#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 256/ 1.00hrs @ 169.95 169.95 inspection complete	I
#3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 256/ * 0.90hrs 59.95 rotated 4 tires	I
#4 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 256/ * 1.50hrs 159.95 alignment complete	I
#5 - NRF: NO RECALLS FOUND FOR VEHICLE AT THIS TIME.	C
#6 * 4T: REPLACE 4 TIRES MOUNT & BALANCE . INCLUDES WITH PURCHASE OF THESE TIRES - ORIGINAL OWNER WILL RECEIVE TIRE ROTATIONS FOR LIFE OF TIRE AND ONE YEAR DEERY ROAD HAZARD 19427350 UNIROYAL TIGER PAT	I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
SEDAN	48882	48882
License Number	Service Advisor	
Account No.	AMANDA KEPHART	Delivery Date
Vehicle Identification Number	3LN6L5D90HR659646	In-Service Date

INVENTORY: 1289651

TOURING 245/45R18  
YEAR DEERY ROAD HAZARD 19427350 UNIROYAL TIGER PAT  
TOURING 245/45R18  
Corrected by 4T: REPLACE 4 TIRES MOUNT & BALANCE .  
INCLUDES WITH PURCHASE OF THESE TIRES - ORIGINAL  
OWNER WILL RECEIVE TIRE ROTATIONS FOR LIFE OF TIRE  
AND ONE YEAR DEERY ROAD HAZARD LRATE:.00  
Work performed by Tech 256/ \* 1.20hrs 100.00  
19427350 : N-U24545180 (05880-BOPCKT) 4@192.00 768.00  
mounted and balanced 4 tires psi 36 all

Total Fee Amounts 34.00

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	563.55				
PARTS	817.64				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	1445.18				



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
149 Verified Reviews

♥ **102**  
Customer Favorites



## Vehicle History Report™

US \$44.99

### 2017 LINCOLN MKZ SELECT

VIN: 3LN6L5D90HR659646  
SEDAN 4 DR  
2.0L I4 F DOHC 16V  
GASOLINE  
ALL WHEEL DRIVE  
Original Window Sticker  
This CARFAX Report Provided  
by:

**Deery Brothers**

★ 4.6 / 5.0

149 Verified Reviews

♥ 102 Customer Favorites

⚠ Accident reported

🔧 10 Service history records

👍 Great Reliability

👤 2 Previous owners

🏠 Types of owners: Personal lease, Personal

📊 48,882 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 1/22/26 at 5:45:34 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### CARFAX Accident / Damage History


Not all accidents / issues are reported to CARFAX

#### Event 1

08/17/2017

**Accident reported with another motor vehicle**



- Functional damage reported



#### Event 2

01/16/2018

**Damage reported: minor damage**



**CARFAX** Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
Oil	Oil and filter changed	01/21/2026

This car has been recently serviced. That's a good thing!

**CARFAX** Reliability Forecast

Based on 2017 Lincoln MKZ Select with similar mileage

**3-Year Reliability Forecast**



Good news! This vehicle is expected to have low risk of repair and average repair costs.



**What makes this vehicle have great reliability?**

- Top 50%** compared to similar vehicles
- Average Repair Cost**  
\$430 avg per year
- Oil Changes** performed regularly
- Low Likelihood of Repair**

**CARFAX** Additional History

Not all accidents / issues are reported to CARFAX

	Owner 1	Owner 2
<b>Total Loss</b> No total loss reported to CARFAX.	No Issues Reported	No Issues Reported
<b>Structural Damage</b>	No Issues Reported	No Issues Reported

CARFAX recommends that you have this vehicle inspected by a collision repair specialist.		
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
<b>Accident / Damage</b> Accident reported: 08/17/2017. Damage reported: 01/16/2018.	Accident Reported	No New Issues Reported
<b>Manufacturer Recall</b> No open recalls reported to CARFAX. A current list of recalls is available at Ford Motor Company.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	Warranty Expired	Warranty Expired

 <b>Title History</b> CARFAX guarantees the information in this section	Owner 1	Owner 2
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
 <b>GUARANTEED</b> - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. <a href="#">View Terms</a>   <a href="#">View Certificate</a>		

 <b>Ownership History</b> The number of owners is estimated	Owner 1	Owner 2
Year purchased	2017	2019
Type of owner	Personal lease	Personal
Estimated length of ownership	2 years	6 yrs. 3 mo.
Owned in the following states/provinces	Michigan, Illinois	Illinois, Iowa
Estimated miles driven per year	4,325/yr	6,383/yr
Last reported odometer reading	8,699	48,882

 <b>Detailed History</b>