

Multi-Point Inspection Checklist

RO# 6036219

Customer Name INVENTORY: 1289151

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 1/20/2026 8:21 AM

Printed on 1/26/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

- Checked and OK at this time
 May Require Future Attention
 Requires immediate attention

Maintenance Service

- | | | | |
|-------------------------------------|--------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cold Engine start-up |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine operation warm-up |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Engine at normal operating temperature |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Brake and parking operation <u>fb 9m rb 8mm</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Active seat belt test |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Clutch and transmission operations |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Overdrive operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Transfer case operation (4-wheel drive only) |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Steering operation and off center |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Front end alignment |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tilt steering wheel operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Windshield wiper and washer operation at all speeds, wiper blade condition |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Speedometer and odometer operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Cruise Control operation, including resume |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Heater and air condition operation |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Abnormal noises and vibrations |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Squeaks and rattles |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Frame Check |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Body surface, lower body, and upper body damage requiring body shop repair |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Tire defects and damage, 5/32 <u>ft 11/32 rt 10/32</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive shaft, joints, CV's and boots |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Struts/shock absorbers, leaks and wear |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Exhaust system leaks and damage, including catalytic converter |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Fuel, oil, coolant, or other fluid leaks |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Perform emissions test and/or state inspection if required |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood labels and decals |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Air filter and In-Cabin Air Filter equipped <u>Found the cabin and engine air filter to be dirty</u> |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Battery cables and mount |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Coolant level and test |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Under hood fluid levels, including transmission and transfer case fluids |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Drive belts and hoses |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Air conditioning levels, check at sight glass |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Warning lights (including air bag) gauges & horn |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Inside and outside rearview mirror operation, adjustment, and condition |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Glass free of cracks, starts and large chips |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Dome , courtesy, map and sun visor lights and lighters and power ports |

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2023	TOYOTA	TACOMA
Vehicle Identification Number	Color	
3TMCZ5AN8PM550533	BLACK	

TRUCK	34722	34722
JAKE BACHTTELL		
	2/13/23	2/13/23

INVENTORY: 1289151

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 Performed a 56 point inspection.	I	169.95
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 19432337 : N-OIL (08800-BOPCK) 6@8.92 53.52 04152-YZZA1 : REPLACEABLE ELEMENT 1@6.90 6.90	I	73.70 53.52 6.90
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95	I	159.95
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs 59.95	I	59.95
#5 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 10.00 87139-YZZ09 : ELEMENT, AIR REFINER 1@49.95 49.95	I	10.00 49.95
#6 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
 200 S Gear Ave
 West Burlington, IA 52655

Work Phone

R/O Open Date

R/O Number

1/20/26

6036219/2

Home Phone

R/O Close Date

Receipt No.

1/20/26

Original

Body

Mileage In

Mileage Out

TRUCK

34722

34722

License Number

Service Advisor

JAKE BACHTELL

Account No.

Delivery Date

In-Service Date

2/13/23

2/13/23

Year	Make	Model
2023	TOYOTA	TACOMA
Vehicle Identification Number		Color
3TMCZ5AN8PM550533		BLACK

INVENTORY: 1289151

Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00
 Work performed by Tech 329/9 * 0.10hrs
 17801-YZZ15 : ELEMENT SUB-ASSY, AI 1@29.95

10.00
 29.95

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	483.55				
PARTS	140.32				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	653.86				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
149 Verified Reviews

♥ **102**
Customer Favorites



Vehicle History Report™

US \$44.99

2023 TOYOTA TACOMA TRD OFF-ROAD

VIN: 3TMCZ5AN8PM550533
CREW PICKUP
3.5L V6
GASOLINE
REAR WHEEL DRIVE W/ 4X4

This CARFAX Report Provided by:

Deery Brothers

★ **4.6 / 5.0**
149 Verified Reviews
♥ **102** Customer Favorites

Damage reported: minor damage

MINOR MODERATE SEVERE

4 Service history records

Great Reliability

CARFAX 1-Owner vehicle

34,722 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 1/21/26 at 5:34:21 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.


CARFAX Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1

06/07/2024

Damage reported: minor damage



CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
 Oil	 Oil and filter changed	01/20/2026
 <div style="border: 1px solid blue; padding: 5px; display: inline-block;"> This car has been recently serviced. That's a good thing! </div>		

CARFAX Reliability Forecast

Based on 2023 Toyota Tacoma TRD Off-Road with similar mileage

3-Year Reliability Forecast



Good news! This vehicle is expected to have low risk of repair and average repair costs.



What makes this vehicle have great reliability?

 **Top 25%** compared to similar vehicles

 **Average Repair Cost**
\$330 avg per year

 **Low Likelihood of Repair**

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage Damage reported: 06/07/2024.	Minor Damage
Manufacturer Recall No open recalls reported to CARFAX. View Toyota disclosure	<input checked="" type="checkbox"/> No Recalls Reported

<p>Basic Warranty Original warranty estimated to have 1 month or 1,278 miles remaining. Confirm with dealer or vehicle manufacturer.</p>	<p><input checked="" type="checkbox"/> Warranty Active</p>
---	--

<p>CARFAX Title History CARFAX guarantees the information in this section</p>	<p>Owner 1</p>
<p>Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon</p>	<p><input checked="" type="checkbox"/> Guaranteed No Problem</p>
<p>Odometer Brands Not Actual Mileage Exceeds Mechanical Limits</p>	<p><input checked="" type="checkbox"/> Guaranteed No Problem</p>
<p> GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate</p>	

<p>CARFAX Ownership History The number of owners is estimated</p>	<p>Owner 1</p>
<p>Year purchased</p>	<p>2023</p>
<p>Type of owner</p>	<p>Personal</p>
<p>Estimated length of ownership</p>	<p>2 yrs. 11 mo.</p>
<p>Owned in the following states/provinces</p>	<p>Iowa</p>
<p>Estimated miles driven per year</p>	<p>11,689/yr</p>
<p>Last reported odometer reading</p>	<p>34,722</p>



<p>CARFAX Detailed History</p>			
<p> Owner 1 Purchased: 2023</p>		<p>Low mileage! This owner drove less than the industry average of 15,000 miles per year.</p>	<p>Personal Vehicle 11,689 mi/yr</p>
Date	Mileage	Source	Comments
11/21/2022		NICB	Vehicle manufactured and shipped to original dealer
12/23/2022	3	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com	 Vehicle serviced - Pre-delivery inspection completed - Oil and filter changed