

Multi-Point Inspection Checklist

RO# 6039530

Customer Name INVENTORY: 1289721

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 5/5/2026 3:57 PM

Printed on 5/20/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-    Cold Engine start-up
-    Engine operation warm-up
-    Engine at normal operating temperature
-    Brake and parking operation FB 8/32 RB 7/32
-    Active seat belt test
-    Clutch and transmission operations
-    Overdrive operation
-    Transfer case operation (4-wheel drive only)
-    Steering operation and off center
-    Front end alignment
-    Tilt steering wheel operation
-    Windshield wiper and washer operation at all speeds, wiper blade condition
-    Speedometer and odometer operation
-    Cruise Control operation, including resume
-    Heater and air condition operation
-    Abnormal noises and vibrations
-    Squeaks and rattles
-    Frame Check
-    Body surface, lower body, and upper body damage requiring body shop repair
-    Tire defects and damage, 5/32 FT 4/32 RT 4/32
-    Drive shaft, joints, CV's and boots
-    Struts/shock absorbers, leaks and wear
-    Exhaust system leaks and damage, including catalytic converter
-    Fuel, oil, coolant, or other fluid leaks
-    Perform emissions test and/or state inspection if required
-    Under hood labels and decals
-    Air filter and In-Cabin Air Filter equipped FOUND THE SLOW DROP ON THE GLOVE BOX TO BE BROKEN
-    Battery cables and mount
-    Coolant level and test
-    Under hood fluid levels, including transmission and transfer case fluids
-    Drive belts and hoses
-    Air conditioning levels, check at sight glass
-    Warning lights (including air bag) gauges & horn
-    Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-    Inside and outside rearview mirror operation, adjustment, and condition
-    Glass free of cracks, starts and large chips
-    Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone			R/O Open Date	R/O Number
Home Phone			5/05/26	6039530/1
Body			R/O Close Date	Receipt No.
SUV			5/08/26	Original
License Number			Mileage In	Mileage Out
			24273	24273
Year	Make	Model	Service Advisor	
2024	SUBARU	CROSSTREK	JAKE BACHTTELL	
Vehicle Identification Number		Color	Account No.	In-Service Date
4S4GUHM60R3824362		GRAY		

INVENTORY: 1289721

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:178.95 Work performed by Tech 329/9 1.00hrs @ 178.95 Performed a 56 point inspection.				I	
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:195.58 Work performed by Tech 329/9 0.40hrs @ 195.57 78.23 00279-BLK16-01 : GTMO OW16 BK SP WTY 5@9.60 48.00 R85358MP : FILTER 1@9.65 9.65 Changed the engine oil and filter.				I	
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95 Performed a 4 wheel alignment.				I	
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs 99.00 Balanced all four tires.				I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	516.13				
PARTS	57.65				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	603.77				

This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

2025 TOP-RATED DEALER

★ **4.6 / 5.0**
165 Verified Reviews

♥ **1,102**
Customer Favorites

CARFAX Report

US \$44.99

2024 Subaru Crosstrek Limited


24,273 mi | VIN: 4S4GUHM60R3824362 |
4 Door Wagon/Sport Utility | 2.5L H4 F DOHC 16V | Gasoline | All wheel drive



NO ACCIDENTS REPORTED

✓ No Accidents or Damage Reported to CARFAX

FAIR VALUE



🛢️ Regular Oil Changes

1 CARFAX 1-Owner Vehicle

🏠 Personal Vehicle

🌍 Last Owned in Iowa

📄 15 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/12/26 at 6:14:17 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	05/08/2026
🛞 Tires	✓ Tires rotated	05/08/2026

This car has been recently serviced. That's a good thing!

CARFAX History-Based Value Report

\$29,180

CARFAX Value

FAIR VALUE



What makes this vehicle a fair value?

↑ ✓ No Accidents Reported

↑ 1 1-Owner Vehicle







Fair Value	Good Value	Great Value	Regular Oil Changes Personal Vehicle
------------	------------	-------------	---

CARFAX Additional History	Owner 1
Not all accidents / issues are reported to CARFAX	
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have 17 months or 11,727 miles remaining. Confirm with dealer or vehicle manufacturer.	<input checked="" type="checkbox"/> Warranty Active

CARFAX Title History	Owner 1
CARFAX guarantees the information in this section	
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

CARFAX Ownership History	Owner 1
The number of owners is estimated	
Year purchased	2024
Type of owner	Personal
Estimated length of ownership	1 yr. 7 mo.
Owned in the following states/provinces	Illinois, Iowa
Estimated miles driven per year	14,936/yr
Last reported odometer reading	24,273

CARFAX Detailed History								
<div style="display: flex; justify-content: space-between; align-items: flex-start;"> <div style="text-align: left;"> Owner 1 Purchased: 2024 </div> <div style="border: 1px solid blue; padding: 5px; text-align: center;"> Low mileage! This owner drove less than the industry average of 15,000 miles per year. </div> <div style="text-align: right;"> Personal Vehicle 14,936 mi/yr </div> </div>								
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 15%;">Date</th> <th style="width: 15%;">Mileage</th> <th style="width: 30%;">Source</th> <th style="width: 40%;">Comments</th> </tr> </thead> <tbody> <tr> <td>08/30/2024</td> <td></td> <td>McLaughlin Motors Volvo</td> <td>Vehicle offered for sale</td> </tr> </tbody> </table>	Date	Mileage	Source	Comments	08/30/2024		McLaughlin Motors Volvo	Vehicle offered for sale
Date	Mileage	Source	Comments					
08/30/2024		McLaughlin Motors Volvo	Vehicle offered for sale					

		Moline, IL 309-797-5654 mcmotors.com/ ★ 4.7 / 5.0 33 Verified Reviews ♥ 24 Customer Favorites		
08/31/2024	4	McLaughlin Motors Subaru Moline, IL 309-797-5654 mcmotors.com/ ★ 4.8 / 5.0 134 Verified Reviews ♥ 51 Customer Favorites		Vehicle serviced - Pre-delivery inspection completed
09/19/2024	11	McLaughlin Motors Subaru Moline, IL 309-797-5654 mcmotors.com/ ★ 4.8 / 5.0 134 Verified Reviews ♥ 51 Customer Favorites		Vehicle sold
09/19/2024		Illinois Motor Vehicle Dept.		Vehicle purchase reported
11/01/2024		Illinois Motor Vehicle Dept. Milan, IL Title #243056924100		Title issued or updated - Registration issued or renewed - First owner reported - Titled or registered as personal vehicle - Loan or lien reported - Vehicle color noted as Gray
12/27/2024	6,402	McLaughlin Motors Subaru Moline, IL 309-797-5654 mcmotors.com/ ★ 4.8 / 5.0 134 Verified Reviews ♥ 51 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Cabin air filter replaced/cleaned - Fluids checked - Oil and filter changed - Tire condition and pressure checked - Tires rotated
03/13/2025		Iowa Motor Vehicle Dept. Fruitland, IA		Registration issued or renewed - Registration updated when owner moved the vehicle to a new location - Vehicle color noted as Gray
05/15/2025	12,178	McLaughlin Motors Subaru Moline, IL 309-797-5654 mcmotors.com/ ★ 4.8 / 5.0 134 Verified Reviews ♥ 51 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Cabin air filter replaced/cleaned - Oil and filter changed - Oil line/hose replaced - Tire condition and pressure checked - Tires rotated - Two tires mounted
09/07/2025	17,775	Walmart Auto Care Center Muscatine, IA 563-262-5447 https://www.walmart.com ★ 4.4 / 5.0 54 Verified Reviews ♥ 1 Customer Favorite		Vehicle serviced - Tire repaired
09/11/2025	17,933	McLaughlin Motors Subaru Moline, IL 309-797-5654 mcmotors.com/ ★ 4.8 / 5.0 134 Verified Reviews ♥ 51 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Recommended maintenance performed - Air filter replaced - Fluids checked - Oil and filter changed - Tire condition and pressure checked - Tires rotated
09/18/2025	18,261	Walmart Auto Care Center Coralville, IA 319-545-6417		Vehicle serviced - Tire repaired