

Multi-Point Inspection Checklist

RO# 6035619

Customer Name INVENTORY: 1139171

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 12/29/2025 10:10 AM

Printed on 12/30/2025

Did your Service Advisor review the results of this multi-point inspection checklist with you?

- Checked and OK at this time May Require Future Attention Requires immediate attention

Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation fb 9mm rb 8mm
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 ft 4/32 rt /32
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emissions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In-Cabin Air Filter equipped Found the cabin and engine air filter to be dirty
- Battery cables and mount
- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips
- Dome, courtesy, map and sun visor lights and lighters and power ports

Window operation
Sunroof or convertible top operation
Audio system and clock (set if required)
Factory -installed alarm system functional
Cigarette lighter operation, replace element if used
Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
Truck bed, bed liner, tailgate, rear bumper
Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

Seats and seat belt operation for every position

Rear defogger, check with test lights

Headlight aim

Trunk light and trunk trim appearance

Hood, trunk, and fuel filler door latch

Spare tire pressure, jack and tire wrench match vehicle and work properly

Wheel covers and caps

Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness

Differential oil level

Engine oil and filter changed using genuine replacement parts

CHECK AND COMPLETE ALL OPEN RECALL

OTHER

Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

With the complexity of the modern automobile, no one can foresee what may happen to it at any time.

Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.

Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.

Customer Acknowledgement:

Technician

Date

Service Manager

Date 12-29-25

Used Car Manager

Date

Customer

Date

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Year	Make	Model
2018	TOYOTA	CAMRY
Vehicle Identification Number		Color
4T1B61HK4JU125611		WHITE

Work Phone	R/O Open Date	R/O Number
	12/29/25	6035619/1
Home Phone	R/O Close Date	Receipt No.
	12/31/25	Original
Body	Mileage In	Mileage Out
SEDAN	113013	113013
License Number	Service Advisor	
	JAKE BACHTELL	
Account No.	Delivery Date	In-Service Date
	11/09/18	11/09/18

INVENTORY: 1139171

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 Performed a 56 point inspection.	169.95	I
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 19420060 : N-OIL (08800-BOPCK) 5@8.10 40.50 90915-YZZN1 : FILTER, OIL 1@8.66 8.66 Changed the engine oil and filter.	73.70 40.50 8.66	I
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs Performed a 4 wheel alignment.	159.95	I
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs Balanced all four wheels and tires.	59.95	I
#5 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 10.00 87139-YZZ93 : ELEMENT, AIR REFINER 1@49.95 49.95	10.00 49.95	I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone

R/O Open Date

R/O Number

12/29/25

6035619/2

Home Phone

R/O Close Date

Receipt No.

12/31/25

Original

Body

Mileage In

Mileage Out

SEDAN

113013

113013

Year

Make

Model

License Number

Service Advisor

2018

TOYOTA

CAMRY

JAKE BACHTELL

Vehicle Identification Number

Color

Account No.

Delivery Date

In-Service Date

4T1B61HK4JU125611

WHITE

11/09/18

11/09/18

INVENTORY: 1139171

Replaced the cabin air filter.

#6 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER
REPLACEMENT

Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00

Work performed by Tech 329/9 * 0.10hrs

17801-F0050 : ELEMENT SUB-ASSY, AI 1@29.95

Replaced the engine air filter.

10.00

29.95

I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	483.55				
PARTS	129.06				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	642.60				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
147 Verified Reviews

♥ **102**
Customer Favorites



Vehicle History Report™

US \$44.99

2018 TOYOTA CAMRY XSE

VIN: 4T1B61HK4JU125611
SEDAN 4 DR
2.5L I4 F DOHC 16V
GASOLINE
FRONT WHEEL DRIVE

This CARFAX Report Provided by:


Deery Brothers

★ **4.6 / 5.0**

147 Verified Reviews

♥ **102** Customer Favorites

Accident reported: minor damage




🔧 **19** Service history records

👍 **Great Reliability**

1 CARFAX 1-Owner vehicle

📊 **113,009** Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 12/30/25 at 6:09:56 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Accident / Damage History



Not all accidents / issues are reported to CARFAX

Event 1

06/06/2024

Accident reported: minor damage

- It hit an object
- Damage to undercarriage
- Airbags did not deploy





Event 2

03/10/2025

Accident reported: minor damage

- Vehicle involved in a sideswipe collision with another motor vehicle
- Airbags did not deploy



CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
Oil	✓ Oil and filter changed	10/28/2025
Tires	✓ Tires rotated	10/17/2025



This car has been recently serviced. That's a good thing!

CARFAX Reliability Forecast

Based on 2018 Toyota Camry XSE with similar mileage

3-Year Reliability Forecast



Good news! This vehicle is expected to have low risk of repair and average repair costs.



What makes this vehicle have great reliability?

- Top 25%** compared to similar vehicles
- Average Repair Cost**
\$290 avg per year
- Oil Changes** performed regularly
- Low Likelihood of Repair**

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss

No Issues Reported

No total loss reported to CARFAX.	
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage Accidents reported: 06/06/2024 and 03/10/2025.	Minor Damage
Manufacturer Recall No open recalls reported to CARFAX. View Toyota disclosure	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

 Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

 Ownership History The number of owners is estimated	Owner 1
Year purchased	2018
Type of owner	Personal
Estimated length of ownership	7 yrs. 1 mo.
Owned in the following states/provinces	Iowa
Estimated miles driven per year	15,779/yr
Last reported odometer reading	113,009

 Detailed History
--

