

# Multi-Point Inspection Checklist

RO# 6036166

Customer Name INVENTORY: 1289831

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 1/16/2026 4:27 PM

Printed on 1/26/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time     May Require Future Attention     Requires immediate attention

## Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation fb 9mm rb 8mm
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 ft 9/32 rt 8/32
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emissions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In-Cabin Air Filter equipped Found the cabin and engine air filter to be dirty
- Battery cables and mount
- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips
- Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician \_\_\_\_\_ Date \_\_\_\_\_

Service Manager \_\_\_\_\_ Date \_\_\_\_\_

Used Car Manager \_\_\_\_\_ Date \_\_\_\_\_

Customer \_\_\_\_\_ Date \_\_\_\_\_

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
	1/16/26	6036166/1
Home Phone	R/O Close Date	Receipt No.
	1/21/26	Original
Body	Mileage In	Mileage Out
SEDAN	54478	54478
License Number	Service Advisor	
	JAKE BACHTTELL	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2024	LEXUS	ES 300H
Vehicle Identification Number		Color
58ABA1C19RU038319		WHITE

INVENTORY: 1289831

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 Performed a 56 point inspection.			I
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70 19432337 : N-OIL (08800-BOPCK) 5@8.92 44.60 19427700 : SL-N-FILTER (01836-BOPCKT) 1@13.53 13.53 Changed the engine oil and filter.			I
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95 Performed a 4 wheel alignment.			I
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs 59.95 Balanced all four wheels and tires.			I
#5 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 10.00 87139-YZZ93 : ELEMENT, AIR REFINER 1@49.95 49.95			I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
 200 S Gear Ave  
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
	1/16/26	6036166/2
Home Phone	R/O Close Date	Receipt No.
	1/21/26	Original
Body	Mileage In	Mileage Out
SEDAN	54478	54478
License Number	Service Advisor	
	JAKE BACHTELL	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2024	LEXUS	ES 300H
Vehicle Identification Number		Color
58ABA1C19RU038319		WHITE

INVENTORY: 1289831

Replaced the cabin air filter.

#6 \* AF: REPLACED ENGINE AIR FILTER \*ENGINE AIR FILTER REPLACEMENT

Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00

Work performed by Tech 329/9 \* 0.10hrs 10.00

17801-F0020 : ELEMENT SUB-ASSY, AI 1@29.95 29.95

Replaced the engine air filter.

I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	483.55				
PARTS	138.03				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	651.57				



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
149 Verified Reviews

♥ **102**  
Customer Favorites



### Vehicle History Report™

US \$44.99

#### 2024 LEXUS ES 300H F SPORT HANDLING

VIN: 58ABA1C19RU038319  
SEDAN 4 DR  
2.5L I4 F DOHC 16V  
HYBRID  
FRONT WHEEL DRIVE

This CARFAX Report Provided by:

**Deery Brothers**

★ **4.6 / 5.0**  
149 Verified Reviews  
♥ **102** Customer Favorites



No accidents or damage reported to CARFAX



Regular oil changes



At least 1 open recall



CARFAX 1-Owner vehicle



Personal vehicle



**54,478** Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 1/22/26 at 5:49:25 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



#### Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
Oil	✓ Oil and filter changed	01/21/2026
	This car has been recently serviced. That's a good thing!	



#### Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

<b>Total Loss</b> No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Structural Damage</b> No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Manufacturer Recall</b> At least 1 manufacturer recall requires service. Locate an authorized Lexus dealer near you to schedule an appointment. View Toyota disclosure	Recall Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	Warranty Expired

 <b>Title History</b> CARFAX guarantees the information in this section	<b>Owner 1</b>
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
 <b>GUARANTEED</b> - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. <a href="#">View Terms</a>   <a href="#">View Certificate</a>	

 <b>Ownership History</b> The number of owners is estimated	<b>Owner 1</b>
Year purchased	2023
Type of owner	Personal
Estimated length of ownership	2 yrs. 4 mo.
Owned in the following states/provinces	Illinois
Estimated miles driven per year	22,643/yr
Last reported odometer reading	54,478





## Detailed History



**Owner 1**

Purchased: 2023

Personal Vehicle  
22,643 mi/yr

Date	Mileage	Source	Comments
08/14/2023		NICB	<b>Vehicle manufactured and shipped to original dealer</b>
08/23/2023		Lexus of Quad Cities Davenport, IA 563-445-4306 smartlexusofquadcities.com/ 4.7 / 5.0 528 Verified Reviews 5,629 Customer Favorites	<b>Vehicle offered for sale</b>
08/24/2023	4	Lexus of Quad Cities Davenport, IA 563-445-4306 https://smartlexusofquadcities.com/ 4.7 / 5.0 528 Verified Reviews 5,629 Customer Favorites	<b>Vehicle serviced</b> - Pre-delivery inspection completed - Vehicle washed/detailed
08/26/2023	12	Lexus of Quad Cities Davenport, IA 563-445-4306 https://smartlexusofquadcities.com/ 4.7 / 5.0 528 Verified Reviews 5,629 Customer Favorites	<b>Vehicle sold</b>
08/26/2023		Illinois Motor Vehicle Dept.	<b>Vehicle purchase reported</b> - Titled or registered as personal vehicle
10/09/2023		Illinois Motor Vehicle Dept. East Galesburg, IL	<b>Title issued or updated</b> - Registration issued or renewed - First owner reported - Correction to record - Vehicle color noted as White
02/09/2024	6,712	Lexus of Quad Cities Davenport, IA 563-445-4306 https://smartlexusofquadcities.com/ 	<b>Vehicle serviced</b> - Maintenance inspection completed - 5,000 mile service performed - Floor mat(s) checked - Floor mats installed