

Mul i-Point Inspection Checklist

RO# 6036620

Customer Name INVENTORY: 968840

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 2/2/2026 8:04 AM

Printed on 2/2/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service


-   Cold Engine start-up
-   Engine operation warm-up
-   Engine at normal operating temperature
-   Brake and parking operation fb 9mm rb 8mm
-   Active seat belt test
-   Clutch and transmission operations
-   Overdrive operation
-   Transfer case operation (4-wheel drive only)
-   Steering operation and off center
-   Front end alignment
-   Tilt steering wheel operation
-   Windshield wiper and washer operation at all speeds, wiper blade condition
-   Speedometer and odometer operation
-   Cruise Control operation, including resume
-   Heater and air condition operation
-   Abnormal noises and vibrations
-   Squeaks and rattles
-   Frame Check
-   Body surface, lower body, and upper body damage requiring body shop repair
-   Tire defects and damage, 5/32 ft 7/32 rt 8/32
-   Drive shaft, joints, CV's and boots
-   Struts/shock absorbers, leaks and wear
-   Exhaust system leaks and damage, including catalytic converter
-   Fuel, oil, coolant, or other fluid leaks
-   Perform emmissions test and/or state inspection if required
-   Under hood labels and decals
-   Air filter and In-Cabin Air Filter equipped Found the engine air filter to be dirty
-   Battery cables and mount
-   Coolant level and test
-   Under hood fluid levels, including transmission and transfer case fluids
-   Drive belts and hoses
-   Air conditioning levels, check at sight glass
-   Warning lights (including air bag) gauges & horn
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-   Inside and outside rearview mirror operation, adjustment, and condition
-   Glass free of cracks, starts and large chips
-   Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager  _____ Date **2.2.26**

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone			R/O Open Date	R/O Number	
			01/28/26	9010751/1	
Home Phone			R/O Close Date	Receipt No	
			01/28/26	Original	
Body			Mileage In	Mileage Out	
4DR SPORT TOU			18957	18957	
License Number			Service Advisor		
			Ashley Lawler	1372	
Vehicle Identification Number		Color	Account No	Delivery Date	In-Service Date
5GAEVBR50SJ225234		GRAY			

INVENTORY: 968840

#1 - AD WV: WASH AND VAC
Work by Tech 773/5833*

1.00hrs


50.00

I

24.00

Account	Description	Control	Re	ference	Amount
49500	SLS-APPEARANCE-INTERNAL LABOR	9010751		9010751	-50.00
24701	INV-WORK IN PROCESS DETAIL/AP	965833		9010751	-24.00
69500	CST-APPEARANCE-INTERNAL LABOR	9010751		9010751	24.00
24100	INVENTORY - USED TRUCKS	968840		9010751	50.00

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER	COST
LABOR	50.00				24.00
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	50.00				24.00



This report provided free of charge by:

Deery Brothers
 200 S Gear Ave
 West Burlington, IA 52655
 319-271-8758

★ **4.6 / 5.0**
 151 Verified Reviews

♥ **101**
 Customer Favorites



Vehicle History Report™

US \$44.99

2025 BUICK ENCLAVE SPORT TOURING

VIN: 5GAEVBRS0SJ225234
 4 DOOR WAGON/SPORT UTILITY
 2.5L I4 F DOHC 16V GASOLINE
 ALL WHEEL DRIVE
 Original Window Sticker
 This CARFAX Report Provided by:

Deery Brothers

★ 4.6 / 5.0

151 Verified Reviews

♥ 101 Customer Favorites



No accidents or damage reported to CARFAX



2 Service history records



CARFAX 1-Owner vehicle



Rental vehicle



Last owned in Texas



18,957 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/4/26 at 5:24:43 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss

No total loss reported to CARFAX.



No Issues Reported

Structural Damage

No structural damage reported to CARFAX.



No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.



No Issues Reported

Odometer Check

No indication of an odometer rollback.



No Issues Indicated

Accident / Damage

No accidents or damage reported to CARFAX.



No Issues Reported

<p>Manufacturer Recall No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.</p>	<p><input checked="" type="checkbox"/> No Recalls Reported</p>
<p>Basic Warranty Original warranty estimated to have 27 months or 17,043 miles remaining. Confirm with dealer or vehicle manufacturer.</p>	<p><input checked="" type="checkbox"/> Warranty Active</p>

<p> Title History CARFAX guarantees the information in this section</p>	<p>Owner 1</p>
<p>Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon</p>	<p><input checked="" type="checkbox"/> Guaranteed No Problem</p>
<p>Odometer Brands Not Actual Mileage Exceeds Mechanical Limits</p>	<p><input checked="" type="checkbox"/> Guaranteed No Problem</p>
<p> GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate</p>	

<p> Ownership History The number of owners is estimated</p>	<p>Owner 1</p>
<p>Year purchased</p>	<p>2025</p>
<p>Type of owner</p>	<p>Rental</p>
<p>Estimated length of ownership</p>	<p>7 months</p>
<p>Owned in the following states/provinces</p>	<p>Texas</p>
<p>Estimated miles driven per year</p>	<p>---</p>
<p>Last reported odometer reading</p>	<p>18,957</p>

<p> Detailed History</p>									
<p> Owner 1 Purchased: 2025</p>	<p>Rental Vehicle</p>								
<table border="1"> <thead> <tr> <th data-bbox="126 1738 198 1768">Date</th> <th data-bbox="328 1738 451 1768">Mileage</th> <th data-bbox="474 1738 581 1768">Source</th> <th data-bbox="938 1738 1091 1768">Comments</th> </tr> </thead> <tbody> <tr> <td colspan="4" data-bbox="126 1789 1091 2032"> <!-- Empty table body for detailed history --> </td> </tr> </tbody> </table>		Date	Mileage	Source	Comments	Empty table body for detailed history			
Date	Mileage	Source	Comments						
Empty table body for detailed history									

Not Reported

General Motors

Original Window Sticker



04/15/2025 15

Texas
Motor Vehicle Dept.
Dallas, TX

Title issued or updated

- First owner reported
- Loan or lien reported
- Titled or registered as rental vehicle
- Vehicle color noted as Black

09/30/2025 17,030

Caliber Auto Glass
Lewisville, TX
888-461-0010
caliber.com/services/aut
o-glass



Vehicle serviced

- Glass repaired

★ 4.7 / 5.0
3,024 Verified Reviews

12/05/2025

Online Listing

Vehicle offered for sale

01/28/2026 18,957

Deery Brothers
West Burlington, IA
319-752-6000
deerybrothers.com/



Vehicle serviced

- Vehicle washed/detailed

★ 4.6 / 5.0
151 Verified Reviews
❤️ 101 Customer Favorites



Looks like this dealer serviced the car in order to prepare it for sale. That's a good thing!

01/31/2026

Deery Brothers
West Burlington, IA
319-752-6000
deerybrothers.com/

Vehicle offered for sale

★ 4.6 / 5.0
151 Verified Reviews
❤️ 101 Customer Favorites

02/04/2026

CARFAX Car Care

Manufacturer Recommended
Maintenance Schedules



Get this vehicle's maintenance schedule, service history and recall alerts at carfax.com/service.

Have Questions? Please visit our Help Center at www.carfax.com.