

MULTI-POINT INSPECTION REPORT

Prevention saves time and money

Keep Vehicles Trouble-Free and Fun to Drive!



Customer:		
VIN: 5GAKVCED5BJ130717	License:	
Model: ENCL	Color:	Odometer: 126,265

MAINTENANCE SERVICE	Future Attention	Immediate Attention	SERVICE RECOMMENDED
	Checked & OK		

1 - Cold engine start-up	✓	
2 - Engine operation warm-up	✓	
3 - Engine at normal operating temperature	✓	
4 - Brake and parking brake operation	✓	
5 - Active seat belt test	✓	
6 - Clutch and transmission operation	✓	
7 - Overdrive operation	✓	
8 - Transfer case operation (4-wheel drive only)	✓	NA
9 - Steering operation and off center	✓	
10 - Front end alignment	✓	
11 - Tilt steering wheel operation	✓	
12 - Windshield wiper and washer operation at all speeds, wiper blade condition	✓	
13 - Speedometer and odometer operation	✓	
14 - Cruise control operation, including resume	✓	
15 - Heater and air conditioning operation	✓	
16 - Abnormal noises and vibrations	✓	
17 - Squeaks and rattles	✓	
18 - Frame Check	✓	
19 - Body surface, lower body, and under body damage requiring body shop repair	✓	
20 - Tire defects and damage, 5/32	✓	7/32 ALL
21 - Drive shaft, joints, CV's and boots	✓	
22 - Struts/shock absorbers, leaks and wear	✓	
23 - Exhaust system leaks and damage, including catalytic convertor	✓	
24 - Fuel, oil, coolant, or other fluid leaks	✓	
25 - Perform emmissions test and/or state inspection if required	✓	NA
26 - Under hood lables and decals	✓	
27 - Air filter and In - Cabin Air Filter if equipped	✓	
28 - Battery cables and mount	✓	
29 - Coolant level and test	✓	-50
30 - Under hood fluid levels, including transmission and transfer case fluids	✓	
31 - Drive belts and hoses	✓	
32 - Air conditioning levels, check at sight glass	✓	
33 - Warning lights (including air bag) gauges & horn	✓	
34 - Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, backup lights, and license plate light	✓	
35 - Inside and outside rearview mirror ooperation, adjustment, and condition	✓	

Tech Name : 18425 KEVIN RANDALL

Date: 05/26/2021

Your Advisor Info:

Name : LEVI CAHILL

Phone :

e-Mail : lcahill@deerybrothers.com

Customer Signature

Next Service Due

131,265 - 09/24/2021

MULTI-POINT INSPECTION REPORT

Prevention saves time and money

Keep Vehicles Trouble-Free and Fun to Drive!



Customer:		
VIN: 5GAKVCED5BJ130717	License:	
Model: ENCL	Color:	Odometer: 126,265

MAINTENANCE SERVICE

Future Attention

Checked & OK

Immediate Attention

SERVICE RECOMMENDED

- 36 - Glass free of cracks, stars, and large chips
- 37 - Dome, courtesy, map and sun visor lights and lighters and power ports
- 38 - Window operation
- 39 - Sunroof or convertible top operation
- 40 - Audio system and clock (set if required)
- 41 - Factory-installed alarm system functional
- 42 - Cigarette lighter operation, replace element if used
- 43 - Headliner, sun visors, dash pad, upholstery, console, cup holders, trim panels, carpets
- 44 - Truck bed, bed liner, tailgate, rear bumper
- 45 - Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position
- 46 - Seats and seat belt operation for every position
- 47 - Rear defogger, check with test lights
- 48 - Headlight aim
- 49 - Trunk light and trunk trim appearance
- 50 - Hood, trunk, and fuel filler door latches
- 51 - Spare tire pressure, jack and tire wrench match vehicle and work properly
- 52 - Wheel covers and caps
- 53 - Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes, inspect rotors/drums for minimum thickness
- 54 - Differential oil level
- 55 - Engine oil and filter changed using genuine replacement parts
- 56 - CHECK AND COMPLETE ALL OPEN RECALLS
- 57 - OTHER
- 58 - Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- 59 - With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- 60 - Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- 61 - Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- 62 - Customer Acknowledgement:

X

MISSING SECOND ROW DOM LIGHT COVER

NA

SECOND ROW RADIO KNOB MISSING

NA

MISSING RIGHT FRONT CENTER CAP
4MM FRONT 2MM REAR

Tech Name : 18425 KEVIN RANDALL

Date: 05/26/2021

Your Advisor Info:

Name : LEVI CAHILL

Phone :

e-Mail : lcahill@deerybrothers.com

Customer Signature

Next Service Due

131,265 - 09/24/2021

CUSTOMER #: **722375**

722375

ACCOUNTING

PAGE 1

HOME: CONT:N/A
BUS: CELL: 18435 JAKE BACHTELL

11 BUICK ENCLAVE 5GAKVCE5BJ130717 126262/126262 T4155A

28JUL10 IS
DD10JUL10 18:00 24MAY21 110.88 CASH 26MAY21
STK:518642 ENG:3.6_Liter_SIDI

13:40 24MAY21 08:15 26MAY21
LINE OPCODE TECH TYPE A/HRS S/HRS COST SALE COMP LIST NET TOTAL
A C/S TO REPLACE ALTERNATOR
0999 REPLACE ALTERNATOR
471 IUT 3.00 7800 38664 386.64 386.64
1 19343531
(S)REMANUFACTURED
GENERATOR 21852 44797 0 447.97 447.97 447.97
126262 FOUND ALTERNATOR IS SHORTED OUT. REPLACED ALTERNATOR.

EST: 853.00 24MAY21 13:40 SA: 18435

CONTACT:

EPA COMPLIANCE AND SHOP SUPPLIES 0 3642 36.42
FOR QUICK, CONVENIENT SERVICE, RESERVATIONS
FOR YOUR NEXT SCHEDULED MAINTENANCE IS NOT
NEEDED BUT RECOMMENDED. CALL 319-752-6600 FOR
YOUR NEXT SERVICE RESERVATION. WE WELCOME ALL
WALK-IN CUSTOMERS.

WE WANT OUR CUSTOMERS 100% SATISFIED!

ACCOUNT	SALE	COST	CONTROL	ACCOUNT	SALE	COST	CONTROL
46301	38664	7800		48100	44797	21852	
66900	3642	0		24100	83461	*****	
24100	3642	*****	518642				

COST, SALE, & COMP TOTALS 29652 87103 0

0.00
0.00
0.00
0.00
0.00
0.00
0.00
0.00
0.00

CUSTOMER #:

722456

722456

ACCOUNTING

PAGE 1

HOME: CONT:N/A

BUS: CELL: 18187 LEVI CAHILL

11 BUICK ENCLAVE 5GAKVCED5BJ130717 126265/126265 518642

28JUL10 IS

DD10JUL10 17:00 27MAY21 110.88 CASH 27MAY21
STK:518642 ENG:3.6_Liter_SIDI

15:55 25MAY21 15:40 27MAY21

LINE OPCODE TECH TYPE A/HRS S/HRS COST SALE COMP LIST NET TOTAL

A 56 POINT INSPECTION

4 56 POINT INSPECTION

18425 IUT 1.00 2000 11243 112.43 112.43

126265 SERVICE COMPLETED

B CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS

1 CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS

FILL ALL FLUID LEVELS

18425 IUT 0.40 800 4120 41.20 41.20

6 19420080 OIL 1644 2652 0 4.42 4.42 26.52

1 19419227 (S)FILTER 356 587 0 5.87 5.87 5.87

126265 SERVICE COMPLETED

C USED CAR INSPECTION #1

UCI1 USED CAR INSPECTION #1

18425 IUT 0.00 0 0 0.00 0.00

126265 SERVICE COMPLETED

D** REPLACE FRONT BRAKE LINING AND MACHINE ROTORS

GM24N REPLACE FRONT BRAKE LINING AND MACHINE
ROTORS

18425 IUT 1.80 3600 8200 82.00 82.00

1 19387593 (S)PAD KIT 2604 6800 0 68.00 68.00 68.00

1 K860G STOP SQUEAL 925 1295 0 12.95 12.95 12.95

126265 REPLACED FRONT BRAKES

E** REPLACE REAR BRAKE LINING AND RESURFACE DRUMS OR ROTORS .

GM24P REPLACE REAR BRAKE LINING AND RESURFACE
DRUMS OR ROTORS .

18425 IUT 1.80 3600 8200 82.00 82.00

1 19286141 (S)PAD KIT 2758 6800 0 68.00 68.00 68.00

1 K860G STOP SQUEAL 925 1295 0 12.95 12.95 12.95

126265 REPLACED REAR BRAKES AND TURNED ROTORS

F** REPLACE KNOB AND DOME LIGHT COVER

0999 MISCELLANEOUS REPAIR - MAINTENANCE ITEMS

18425 IUT 0.50 1000 5622 56.22 56.22

1 15853941 LENS 308 653 0 6.53 6.53 6.53

1 22912547 KNOB KIT 653 1384 0 13.84 13.84 13.84



Julie Daniels

May 29, 2021

[Update My Profile](#)[Logout](#)

Global Warranty Management: Main > Interface With Customer > View Vehicle Summary

INTERFACE WITH
CUSTOMER

View Vehicle Summary



This screen allows IVH users to view the Summary of Vehicle Information, Field Actions, Service Information, Applicable Warranties, Transaction History, Service Contract(s) if applicable, Warranty Block, Branded Title information and OnStar and XM Radio information (if applicable).

Vehicle Information

VIN: 5GAKVCED5BJ130717

Model: 4V14526-2011 BUICK ENCLAVE CX AWD

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: Yes

Order Type: 81 - DEALER USED CAR (CVMS USE)

Field Actions: [0 Open](#)

For this vehicle:

[View Vehicle Summary](#)[Service Contract](#)[Branded Title](#)[Warranty Block](#)[View Vehicle Build](#)[View Vehicle Component Summary](#)[View Vehicle Transaction History Detail](#)[View Vehicle Delivery Information](#)[Investigate Major Assembly History](#)

Required Field Actions

Open Field Action Details are highlighted

Type	Number	Original Nbr	Description	Release Date	Status
Product Safety Recall	N150240	15240	POWER LIFTGATE PROP ROD RECOVERY	11/10/2015	Closed
Product Safety Recall	N140187	14187	FRONT SAFETY BELT ANCHOR	05/29/2014	Closed
Product Safety Recall	N140030	14030	SIDE IMPACT AIRBAG CONNECTOR	03/18/2014	Closed
Customer Satisfaction Program	N130079	13079	WATER PUMP SHAFT SEAL LEAKS	04/04/2013	Closed

Branded Title

*The VIN information contained herein and information derived therefrom is the proprietary property of The Polk Company and is to be used only for the purpose of warranty verification and shall not be used for any other purpose whatsoever.

Vehicle has no current record of branded titles.

Warranty Block

Vehicle has no current record of warranty block.

Service Information

Vehicle has no current record of outstanding service information.

OnStar and XM Satellite Radio Information

Refer to Help page for details. For OnStar contact 888.ON.STAR1 (888.667.8271) and for XM Radio contact 877.GET.XMST (877.438.9677 Canada) and in the USA:800-556-3600.

OnStar Equipped: Y

OnStar Status: Inactive

XM Equipped: Y

XM Radio ID: RVMM72RY

XM Status: Inactive

OnStar Vehicle Diagnostics: N

DMN Enabled: N

Applicable Warranties

Valid warranties are highlighted

Valid	Description	Start Date	Effective Odometer	End Date	End Odometer
	Bumper to Bumper Limited Warranty	07/28/2010	0 MI	07/28/2014	50,000 MI
	Emission Select Component Ltd Wty	07/28/2010	0 MI	07/28/2018	80,000 MI
	Special Coverage 14582	07/28/2010	0 MI	07/28/2020	120,000 MI
	Special Coverage N192219480	07/28/2010	0 MI	07/28/2022	180,000 MI
	Special Coverage 14329	07/28/2010	0 MI	07/28/2020	150,000 MI
	Corrosion Limited Warranty	07/28/2010	0 MI	07/28/2016	Unlimited
	Powertrain Limited Warranty	07/28/2010	0 MI	07/28/2015	100,000 MI

Service Contract

Vehicle has no current record of service contracts.

Transaction History[View Details](#)

Job Card Date	Job Card Number	Transaction Type	Transaction Adjustment	Labour Operation	Odometer Reading
04/13/2020	702395	ZPTI----Part Transaction - Service Agent Installed		4032750 - Water Pump Replacement	119,450 MI
03/12/2020	701135	ZPTI----Part Transaction - Service Agent Installed		4063750 - Secondary Camshaft Intermediate Drive Chain Tensioner Replacement - Right Side	119,443 MI
01/24/2019	678965	ZREG----Regular Vehicle Transaction		9900244 - N140582 - Throttle Body Assembly Replacement (Includes Throttle/Idle learn and Diagnostic Time)	112,106 MI
04/13/2018	663803	ZREG----Regular Vehicle Transaction		9900053 - N140329 - Power Steering Pump Replacement (inc. system bleed)	105,917 MI
08/25/2016	619387	ZFAT----Field Action Recall		9101483 - N150240 - Reprogram Accessory and Lift Gate Control Module with SPS	96,622 MI
03/27/2015	96087	ZFAT----Field Action Recall		9100600 - N140187 - Rework Driver and Passenger Front Seat Belt Tensioner Cable Covers (Inspection Included)	72,266 MI
12/30/2014	94765	ZREG----Regular Vehicle Transaction		9900053 - N140329 - Power Steering Pump Replacement (inc. system bleed)	68,910 MI
06/24/2014	91301	ZFAT----Field Action Recall		9100413 - N140030 - Vehicle Harness Repair	59,208 MI
04/22/2013	84886	ZFAT----Field Action Recall		V2806 - 13079 - Check Engine Coolant Level (Includes Add Coolant)	36,325 MI
02/08/2011	239634	ZSSP----Special Sales Programs		Z2283 - Dexos Promotion	9,711 MI
09/08/2010	960329	ZPDI----Pre-Delivery Inspection		Z7000 - Pre-Delivery Inspection - Base Time	11 MI

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.



Julie Daniels

[Update My Profile](#)[Logout](#)

May 29, 2021

Global Warranty Management: Main > Interface With Customer > View Vehicle Build

INTERFACE WITH
CUSTOMER

View Vehicle Build



This screen allows IVH users to view the initial build information on the selected VIN including option codes with descriptions (where available).

Vehicle Information

VIN: 5GAKVCED5BJ130717

Model: 4V14526-2011 BUICK ENCLAVE CX AWD

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: Yes

Order Type: 81 - DEALER USED CAR (CVMS USE)

Field Actions: [0 Open](#)

Vehicle Build

Model: 4V14526 - 2011 BUICK ENCLAVE CX AWD

Order Number: PBDMG2

Gross Vehicle Weight: 2,932

Build Date: 07/10/2010

Build Plant: J

For this vehicle:

[View Vehicle Summary](#)

- Service Contract

- Branded Title

- Warranty Block

[View Vehicle Build](#)[View Vehicle](#)[Component Summary](#)[View Vehicle](#)[Transaction History](#)[Detail](#)[View Vehicle Delivery](#)[Information](#)[Investigate Major](#)[Assembly History](#)

Option Codes

*IVH is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

1SZ - OPTION PACKAGE DISCOUNTS

2XL - CXL-2 PACKAGE

392 - CASHMERE W/COCOA ACCENTS

39I - INTERIOR TRIM

6AB - COMPONENT FRT LH COMPUTER SEL SUSP

7AB - COMPONENT FRT RH COMPUTER SEL SUSP

8UM - COMPONENT FRT LH COMPUTER SEL SUSP

98U - WHITE DIAMOND TRICOAT

9UM - COMPONENT RR RH COMPUTER SEL SUSP

A45 - MEMORY SETTINGS

AAQ - PWR SEAT ADJUST-PASS, 4 WAY

ABB - 7 PASS SEATING W/2ND ROW CAPTAIN'S CHAIRS & 3RD ROW SPLIT BENCH SEAT

AG3 - PWR SEAT ADJ-DRV, 8-WAY W/MEM

AL0 - SENSOR INDICATOR INFLATABLE RESTRAINT, FRT PASS/CHILD PRESENCE DETECTOR

AQ4 - SEAT RR

AQQ - LOCK CONTROL, ENTRY REMOTE ENTRY, EXTENDED RANGE

AR9 - SEAT FRT BKT, DELUXE

ARN - SEAT REAR 3RD ROW 60/40 BENCH, MAN FOLD

AT8 - RESTRAINT PROVISIONS CHILD, RR SEAT, RR FACING

AXE - WINDOW PWR OPERATED-EXPRESS UP/DOWN DRVR, EXP DOWN PASS REAR DISABLE

AXP - VIN IDENT POSITION, MULTI- PURPOSE VEHICLE

AY0 - AIRBAGS, DUAL FRONTAL, HEAD CURTAIN SIDE AIRBAGS, FRONT SIDE IMPACT AIRBAGS

B0J - VEHICLE GM PROD WEEK 27

B37 - FLOORMATS

BS1 - QUIET TUNING

BTV - REMOTE VEHICLE START

C98 - MODULE INFL RST SUPPRESSION

CJ2 - TRI-ZONE CLIMATE CONTROL

D7E - TRAY LOAD FLOOR, STORAGE

DCP - ONSTAR DIRECTIONS AND CONNECTIONS 1 YR FACTORY PACKAGE

DD8 - MIRROR-INSIDE RVIEW AUTO DIM

DLT - PLANT CODE LANSING DELTA TOWNSHIP, MI

DNP - OUTSIDE MIRRORS, HEATED, POWER FOLDING, TURN SIGNAL

EF7 - COUNTRY UNITED STATES OF AMERICA

FE2 - PREMIUM RIDE SUSPENSION

FE9 - 50-STATE EMISSIONS

GW5 - AXLE 3.16 RATIO

GZW - GVW RATING 6,459.5 LBS

IP2 - TRIM INTERIOR DESIGN	JJD - I/P SUBASSEMBLY INSTALLED
JJJ - SUSPENSION FRONT INSTALLED	JJK - SUSPENSION REAR INSTALLED
JJS - CONSOLE FRT FLR NOT INSTALLED	JL9 - ANTI-LOCK BRAKE SYSTEM
K34 - CRUISE CONTROL	KB6 - HEATED & COOLED SEATS, DRIVER & FRONT PASSENGER
	KW7 - GENERATOR 170 AMP
KV1 - 110 VOLT POWER OUTLET	MH6 - TRANSMISSION 6 SPEED AUTO AWD
LLT - ENGINE 3.6L SIDI V6	N38 - STEERING, TILT, & TELESCOPING
N30 - LEATHER WRAPPED STEERING WHEEL W/AUDIO CONTROLS AND WOOD ACCENTS	
NEA - DUAL EXHAUST W/CHROME TIPS	NT7 - EMISSION SYSTEM FEDERAL TIER 2
NV7 - PWR STEERING W/VAR ASSIST	NW9 - TRACTION CONTROL SYSTEM
P34 - TIRE & WHEEL SPARE	PCI - DRIVER CONFIDENCE PACKAGE
	*REARVIEW CAMERA SYSTEM *ULTRASONIC REAR PARKING ASSIST *REMOTE VEHICLE START
PCK - LUXURY PACKAGE *HEATED & COOLED DRIVER AND FRONT PASSENGER SEATS *OUTSIDE MIRRORS, HEATED POWER FOLDING, TURN SIGNAL *ARTICULATING HEADLIGHTS *STEERING, POWER TILT & TELESCOPING	PPE - 20" CHROME-CLAD ALUMINUM WHEELS
QD6 - SPARE TIRE & WHEEL (REPLACES TIRE SEALANT & INFLATOR KIT)	QQD - TIRES, P255/55R20-107H ALL
R6F - IDENTIFY B CODE USERS	R9N - PROCESS CODE
SLM - STOCK ORDERS	T43 - SPOILER RR
T61 - DAYTIME RUNNING LAMPS	T83 - HEADLAMPS CONTROL AUTOMATIC ON-OFF
	TB5 - LIFTGATE
T96 - FOG LAMPS	U05 - HORN DUAL
TSH - STEERABLE HEADLIGHTS	U4H - AUDIO SYSTEM W/NAVIGATION & DVD *TOUCHSCREEN NAVIGATION *DVD REAR SEAT ENTERTAINMENT *XM NAVIGATION & TRAFFIC *SERVICE FEE EXTRA *1ST 3 MONTHS INCLUDED
U42 - ENTERTAINMENT PKG REAR SEAT	UBS - XM NAVTRAFFIC
	UD7 - ULTRASONIC REAR PARKING ASSIST
UA1 - BATTERY HIGH CAPACITY	UG1 - UNIVERSAL GARAGE DOOR OPENER
UC1 - SPEEDOMETER IBNST, MILES	
UE1 - 6 MTHS ONSTAR DIRECTIONS & CONNECTIONS WITH AUTOMATIC CRASH RESPONSE AND TURN-BY-TURN NAVIGATION (ASK DEALER ABOUT GEOGRAPHIC COVERAGE)	
UH9 - INSTRUMENTATION	UJ2 - INSTRUMENTATION
UJM - TIRE PRESS INDICATOR MANUAL LEARN	UK3 - STEERING WHEEL CONTROLS
ULD - AUDIO CONTROL RR SEAT & EARPHONE JACKS, DISPLAY	UPF - BLUETOOTH FOR PHONE
UQS - SPEAKER SYSTEM PREMIUM AUDIO BRANDED WITH SURROUND AMPLIFIER	USR - RECEPTACLE USB
UUD - ANTENNA HEX FIXED	UVC - CAMERA REAR VIEW
V2P - LUGGAGE CARRIER RF RAIL	V8D - VEHICLE STATEMENT US
VFF - VIDEO FORMAT REGION 1, NTSC	VH9 - ENVELOPE OWNER INFO MAN
VRK - VAA/COMPONENT REL ROOF TRIM	VT7 - OWNERS MANUAL ENGLISH
W49 - MARKET BRAND BUICK	XL7 - FREQUENCIES RATING 315 MHZ, LONG DISTANCE
	YD5 - SPRING FRONT BASE EQUIPMENT
Y92 - MERCHANDISED PKG SPECIAL EDITION	
YD6 - SPRING RR BASE EQUIPMENT	

Added Option Codes

~CZ -

~EX -



Your AutoCheck Vehicle History Report

Report run: 05/29/2021 11:40:59 EDT



2011 Buick Enclave CXL

SUV 4D (3.6L V6 DI)

VIN: 5GAKVCED5BJ130717
Class: CUV - Mid Range
Country of Assembly: United States
Vehicle Age: 10 year(s)

This vehicle is eligible for Buyback Protection



Due to the vehicle's history showing no reported major state title brands. View terms and conditions and to register your vehicle.

YOUR VEHICLE AT A GLANCE



This vehicle's AutoCheck Score: 66

Other comparable 2011 vehicles in the CUV - Mid Range typically score between 73-84.

The patented AutoCheck score predicts the likelihood a car will be on the road in 5 years. It compares vehicles of similar age and class based on a scale of 1-100. The AutoCheck score is based on a proprietary model to help you understand a vehicle's predicted reliability as it pertains to age, number of owners, accidents and other vehicle history factors.

- No State Title Brand Reported
- No Accident Reported
No Air Bag Deployed
- No Other Damage Reported
- Other Title Brand or Specific Event Reported
- No Odometer Problem(s) Reported
Last Odometer Reading: 96,647
- No Open Recall(s) Reported



MULTIPLE OWNERS

Calculated Owners: 4

Owner History

Previous Owner(s)	Last Owner	Current Owner
 Purchased: 2010, 2012 Where: MI, IL Owned from: 07/27/2010 - 10/12/2016 6 year(s) 2 month(s)	 Purchased: 2016 Where: IA Owned from: 10/12/2016 - 07/22/2019 2 year(s) 9 month(s)	 Purchased: 2019 Where: IA Owned from: 07/22/2019 - Present 1 year(s) 10 month(s)

Vehicle Usage



Vehicle Use: There is indication of the below usage(s) for this vehicle

Personal | Fleet | Rental | Lease | Taxi | Livery | Police | Government | Drivers Ed | Commercial



Major State Title Brand Check



Your Vehicle Checks Out: No major state title brand has been reported by the state Division of Motor Vehicles (DMV). Your vehicle is qualified for the AutoCheck Buyback Protection Program. Terms and conditions. Register here.



0 Problem(s) Reported

Major State Title Areas Checked



No fire brand



No hail brand



No flood brand



No junk or scrapped brand



No manufacturer buyback



No lemon brand



No salvage brand



No rebuilt or rebuildable brand



No odometer brand (EML or NAM)



Accident Check



Your Vehicle Checks Out: AutoCheck has not received any accident records from government sources and independent agencies on this vehicle. Not all accidents are reported to AutoCheck.



**NO ACCIDENT
FOUND ON RECORD**



Damage Check



Your Vehicle Checks Out: AutoCheck has not received a damage-related event from an auction or an independent source. Not all damage events are reported to AutoCheck. It is recommended to have pre-owned vehicles inspected by a third party prior to purchase.



**NO DAMAGE
FOUND ON RECORD**

0 Problem(s) Reported

Other Problem Areas Checked



No non-title fire damaged record



No non-title hail damaged record



No non-title flood damaged record



No auction junk or scrapped record



No auction rebuilt or rebuildable record



No salvage auction record



No damaged or major damage incident record



No structural damage or structural alteration record



No recycling facility record



No crash test record



Other Title Brand And Specific Event Check



Information Reported: One or more non-major state title brand(s) and/or additional significant event(s) has been reported to AutoCheck. It is recommended to have pre-owned vehicles inspected by a third party prior to purchase.

1 Event(s) Reported

Vehicle Events Checked



No Insurance Loss record

1 Event(s) Reported**Vehicle Events Checked**

No Titled to an insurance company record



No Auction Lemon/Manufacturer Buyback record



No abandoned title record



No grey market title record



Loan/Lien record(s)



No repossessed record



No corrected title record



No duplicate title record



No theft record(s)

**Odometer Check**

Your Vehicle Checks Out: No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

**State title odometer check****Auction odometer check****Odometer calculation check****0 Problem(s) Reported****Mileage****Date Reported****Other**

10

07/27/2010



15,376

04/21/2011



15,880

02/15/2012



96,647

10/12/2016

**Open Recall Check**

Your Vehicle Checks Out: AutoCheck found no open recalls reported by the vehicle manufacturer. Not all open recalls are reported to AutoCheck.

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order. Any discrepancies will be in bold text.

Report Run Date: 05/29/2021 11:40:59 EDT

Vehicle: 2011 Buick Enclave CXL (5GAKVCE5BJ130717)

Event Date	Location	Odometer Reading	Data Source	Details
07/27/2010	LANSING, MI	10	Motor Vehicle Dept.	TITLE(Title #:809Y2080007)
07/27/2010	LANSING, MI		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
04/21/2011	MI	15,376	Auto Auction	REPORTED AT AUTO AUCTION
02/10/2012	WASHINGTON, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
02/15/2012	WASHINGTON, IL	15,880	Motor Vehicle Dept.	TITLE(Title #:X2046694168) (Lien Reported)
08/02/2012	WASHINGTON, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
08/09/2013	WASHINGTON, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
08/05/2014	WASHINGTON, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
09/15/2015	WASHINGTON, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
07/25/2016	WASHINGTON, IL		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
10/12/2016	BURLINGTON, IA	96,647	Motor Vehicle Dept.	TITLE(Title #:29AB66951) (Lien Reported) REGISTRATION EVENT/RENEWAL
07/18/2017	BURLINGTON, IA		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
07/16/2018	BURLINGTON, IA		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
07/22/2019	BURLINGTON, IA		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
07/23/2020	BURLINGTON, IA		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL

This Vehicle's Glossary

Below are the specific definitions for events that appear in this vehicle's report. More information is available in the full AutoCheck glossary.

Term	Section Location	Definition
Loan/Lien	Other Title Brand and Specific Event Check	A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.
Personal Use	Vehicle Use	This vehicle was driven for personal use.

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to AutoCheck Terms and Conditions. If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 955 American Lane Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (5GAKVCED5BJ130717) qualifies for AutoCheck Buyback Protection. If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbp/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 955 American Lane Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.