

Multi-Point Inspection Checklist

RO# 6036142

Customer Name INVENTORY: 1289591

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 1/16/2026 10:09 AM

Printed on 1/16/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?


 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-   Cold Engine start-up Pass
-   Engine operation warm-up Pass
-   Engine at normal operating temperature Pass
-   Brake and parking operation Pass
-   Active seat belt test Pass
-   Clutch and transmission operations Pass
-   Overdrive operation Pass
-   Transfer case operation (4-wheel drive only) Pass
-   Steering operation and off center Pass
-   Front end alignment Pass
-   Tilt steering wheel operation Pass
-   Windshield wiper and washer operation at all speeds, wiper blade condition Pass
-   Speedometer and odometer operation Pass
-   Cruise Control operation, including resume Pass
-   Heater and air condition operation Pass
-   Abnormal noises and vibrations Pass
-   Squeaks and rattles Pass
-   Frame Check Pass
-   Body surface, lower body, and upper body damage requiring body shop repair Pass
-   Tire defects and damage, 5/32 7/32 all
-   Drive shaft, joints, CV's and boots Pass
-   Struts/shock absorbers, leaks and wear Pass
-   Exhaust system leaks and damage, including catalytic converter Pass
-   Fuel, oil, coolant, or other fluid leaks Pass
-   Perform emissions test and/or state inspection if required Pass
-   Under hood labels and decals Pass
-   Air filter and In-Cabin Air Filter equipped Pass
-   Battery cables and mount Pass
-   Coolant level and test Pass
-   Under hood fluid levels, including transmission and transfer case fluids Pass
-   Drive belts and hoses Pass
-   Air conditioning levels, check at sight glass Pass
-   Warning lights (including air bag) gauges & horn Pass
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-   Inside and outside rearview mirror operation, adjustment, and condition Pass
-   Glass free of cracks, starts and large chips Pass
-   Dome, courtesy, map and sun visor lights and lighters and power ports Pass

- Window operation Pass
- Sunroof or convertible top operation Pass
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance Pass
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 6mm all
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL Pass
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager  _____ Date 1-16-25

Used Car Manager _____ Date _____



Customer _____ Date _____



5J6RW2H58ML015569

Odometer:50277

Honda : CR-V : 2021 : All Wheel Drive ExpressAlign Total Alignment



• One or more values are not within specification. Tire wear, handling and safety problems may result.

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
SUV	50277	50277
License Number	Service Advisor	
	AMANDA KEPHART	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2021	HONDA	CR-V
Vehicle Identification Number		Color
5J6RW2H58ML015569		

INVENTORY: 1289591

<p>#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 256/ 0.40hrs @ 184.25 73.70 R85358MP : FILTER 1@9.65 9.65 19432337 : N-OIL (08800-BOPCK) 4@8.92 35.68 new oil and filter installed</p>		I
<p>#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 256/ 1.00hrs @ 169.95 169.95 inspection complete</p>		I
<p>#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 256/ * 1.50hrs 159.95 alignment complete</p>		I
<p>#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 256/ * 0.90hrs 59.95 tires rotated and balanced psi 36</p>		I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	463.55				
PARTS	45.33				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	538.87				



This report provided free of charge by:

Deery Brothers
 200 S Gear Ave
 West Burlington, IA 52655
 319-271-8758

★ **4.6 / 5.0**
 148 Verified Reviews

♥ **102**
 Customer Favorites



Vehicle History Report™

US \$44.99

2021 HONDA CR-V EX
 VIN: 5J6RW2H58ML015569
 4 DOOR WAGON/SPORT UTILITY
 1.5L I4 F DOHC 16V GASOLINE
 ALL WHEEL DRIVE

This CARFAX Report Provided by:
Deery Brothers
 ★ 4.6 / 5.0
 148 Verified Reviews
 ♥ 102 Customer Favorites

- ✔ No accidents or damage reported to CARFAX
- ✂ 2 Service history records
- 👍 Great Reliability
- 1 CARFAX 1-Owner vehicle
- 🏠 Personal vehicle
- 00mi 50,277 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 1/17/26 at 10:08:20 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
Oil	✔ Oil and filter changed	01/16/2026

This car has been recently serviced. That's a good thing!



Reliability Forecast

Based on 2021 Honda CR-V EX with similar mileage

3-Year Reliability Forecast



Good news! This vehicle is expected to have low risk of repair and average repair costs.



What makes this vehicle have **great** reliability?

- Top 25%** compared to similar vehicles
- Average Repair Cost**
\$310 avg per year
- Low Likelihood of Repair**



Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss

No total loss reported to CARFAX.

No Issues Reported

Structural Damage

No structural damage reported to CARFAX.

No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.

No Issues Reported

Odometer Check

No indication of an odometer rollback.

No Issues Indicated

Accident / Damage

No accidents or damage reported to CARFAX.

No Issues Reported

Manufacturer Recall

No open recalls reported to CARFAX.

No Recalls Reported

Basic Warranty

Original warranty estimated to have expired.

Warranty Expired



Title History

CARFAX guarantees the information in this section

Owner 1

Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

Guaranteed
No Problem

Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits

Guaranteed
No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

 Ownership History The number of owners is estimated		Owner 1
Year purchased		2021
Type of owner		Personal
Estimated length of ownership		4 yrs. 8 mo.
Owned in the following states/provinces		Iowa
Estimated miles driven per year		10,663/yr
Last reported odometer reading		50,277

 Detailed History			
 Owner 1 Purchased: 2021		<div style="border: 1px solid blue; padding: 5px;"> Low mileage! This owner drove less than the industry average of 15,000 miles per year. </div>	Personal Vehicle 10,663 mi/yr
Date	Mileage	Source	Comments
03/11/2021	5	Brad Deery Honda West Burlington, IA 319-754-6000 braddeeryhonda.com/  4.4 / 5.0 62 Verified Reviews  21 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed
05/01/2021		Iowa Motor Vehicle Dept. Burlington, IA	Titled or registered as personal vehicle
05/19/2021		Brad Deery Honda West Burlington, IA 319-754-6000 braddeeryhonda.com/  4.4 / 5.0 62 Verified Reviews  21 Customer Favorites	Vehicle sold
06/03/2021		Iowa Motor Vehicle Dept. Burlington, IA	Title or registration issued - First owner reported - Vehicle color noted as Gray
04/11/2022		Iowa Motor Vehicle Dept.	Registration issued or renewed - Vehicle color noted as Gray