

# Multi-Point Inspection Checklist

RO# 6036838

Customer Name INVENTORY: 1139161

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 2/9/2026 7:32 AM

Printed on 2/9/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time

 May Require Future Attention

 Requires immediate attention

## Maintenance Service

-   Cold Engine start-up Pass
-   Engine operation warm-up Pass
-   Engine at normal operating temperature Pass
-   Brake and parking operation Pass
-   Active seat belt test Pass
-   Clutch and transmission operations Pass
-   Overdrive operation Pass
-   Transfer case operation (4-wheel drive only) Pass
-   Steering operation and off center Pass
-   Front end alignment Pass
-   Tilt steering wheel operation Pass
-   Windshield wiper and washer operation at all speeds, wiper blade condition Pass
-   Speedometer and odometer operation Pass
-   Cruise Control operation, including resume Pass
-   Heater and air condition operation Pass
-   Abnormal noises and vibrations Pass
-   Squeaks and rattles Pass
-   Frame Check Pass
-   Body surface, lower body, and upper body damage requiring body shop repair Pass
-   Tire defects and damage, 5/32 6/32 ALL
-   Drive shaft, joints, CV's and boots Pass

---

-   Struts/shock absorbers, leaks and wear Pass
-   Exhaust system leaks and damage, including catalytic converter Pass
-   Fuel, oil, coolant, or other fluid leaks Pass
-   Perform emissions test and/or state inspection if required Pass
-   Under hood labels and decals Pass
-   Air filter and In-Cabin Air Filter equipped Fail AIR FILTER
-   Battery cables and mount Pass

---

-   Coolant level and test Pass
-   Under hood fluid levels, including transmission and transfer case fluids Pass
-   Drive belts and hoses Pass
-   Air conditioning levels, check at sight glass Pass
-   Warning lights (including air bag) gauges & horn Pass
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-   Inside and outside rearview mirror operation, adjustment, and condition Pass
-   Glass free of cracks, starts and large chips Pass
-   Dome, courtesy, map and sun visor lights and lighters and power ports Pass

- Window operation Pass
- Sunroof or convertible top operation Pass
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights
- Headlight aim Pass
- Trunk light and trunk trim appearance Pass
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness Pass
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL Pass
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:



Technician	Date
Service Manager	Date 2-9-26
Used Car Manager	Date 2-9-26
Customer	Date



5N1AT2MV3LC769068

Odometer:99722

### Nissan : Rogue : 2020 : All Wheel Drive (USA Production) : 5 Seat with 19" Wheel ExpressAlign Total Alignment



• One or more values are not within specification. Tire wear, handling and safety problems may result.

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
SUV	99722	99722

2/09/26	6036838/1
2/12/26	Original
AMANDA KEPHART	

Year	Make	Model	License Number	Service Advisor
2020	NISSAN	ROGUE		AMANDA KEPHART
Vehicle Identification Number		Color	Account No.	Delivery Date
5N1AT2MV3LC769068		WHITE		8/31/20
				In-Service Date
				8/31/20

INVENTORY: 1139161

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 256/ 0.40hrs @ 184.25 73.70 19432337 : N-OIL (08800-BOPCK) 5@8.92 44.60 1520865F0E : OIL FILTER 1@6.90 6.90 NEW OIL AND FILTER INSTALLED	I	
#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 256/ 1.00hrs @ 169.95 169.95 INSPECTION COMPLETE	I	
#3 - RECALL: CHECK FOR OPEN RECALLS Corrected by NRF: NO RECALLS FOUND FOR VEHICLE AT THIS TIME. LRATE:180.14 Work performed by Tech 256/ 0.00hrs @	I	
#4 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00 Work performed by Tech 256/ * 0.10hrs 12.00 165464BA1J : ELEMENT ASSY 1@29.95 29.95	I	
#5 * GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 428/8 * 0.90hrs 99.00	I	
#6 * ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
 200 S Gear Ave  
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
	2/09/26	6036838/2
Home Phone	R/O Close Date	Receipt No.
	2/12/26	Original
Body	Mileage In	Mileage Out
SUV	99722	99722

Year	Make	Model	License Number	Service Advisor
2020	NISSAN	ROGUE		AMANDA KEPHART
Vehicle Identification Number		Color	Account No.	Delivery Date
5N1AT2MV3LC769068		WHITE		8/31/20
				In-Service Date
				8/31/20

INVENTORY: 1139161

DAMAGED OR RUSTED COMPONENTS AND OR PART  
 DAMAGED OR RUSTED COMPONENTS AND OR PART  
 REPLACEMENT . LRATE:.00  
 Work performed by Tech 428/8 \* 1.50hrs 159.95

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	514.60				
PARTS	81.45				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	626.04				



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
151 Verified Reviews

♥ **101**  
Customer Favorites



## Vehicle History Report™

US \$44.99

### 2020 NISSAN ROGUE SL

VIN: 5N1AT2MV3LC769068  
4 DOOR WAGON/SPORT UTILITY  
2.5L I4 F DOHC 16V GASOLINE  
ALL WHEEL DRIVE  
Original Window Sticker  
This CARFAX Report Provided by:

**Deery Brothers**

★ 4.6 / 5.0

151 Verified Reviews

♥ 101 Customer Favorites



No accidents or damage reported to CARFAX



Regular oil changes



Great Reliability



CARFAX 1-Owner vehicle



Personal vehicle



**99,531** Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 2/11/26 at 5:19:05 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



### Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
Oil	✓ Oil and filter changed	12/30/2025
Tires	✓ Tires rotated	12/30/2025



This car has been recently serviced. That's a good thing!

**CARFAX** Reliability Forecast

Based on 2020 Nissan Rogue SL with similar mileage

**3-Year Reliability Forecast**



Fair Reliability    Good Reliability    **Great Reliability**

Good news! This vehicle is expected to have low risk of repair and average repair costs.



**What makes this vehicle have great reliability?**

- Top 25%** compared to similar vehicles
- Average Repair Cost**  
\$380 avg per year
- Oil Changes** performed regularly
- Low Likelihood of Repair**

**CARFAX** Additional History

Not all accidents / issues are reported to CARFAX

**Owner 1**

**Total Loss**

No total loss reported to CARFAX.

No Issues Reported

**Structural Damage**

No structural damage reported to CARFAX.

No Issues Reported

**Airbag Deployment**

No airbag deployment reported to CARFAX.

No Issues Reported

**Odometer Check**

No indication of an odometer rollback.

No Issues Indicated

**Accident / Damage**

No accidents or damage reported to CARFAX.

No Issues Reported

**Manufacturer Recall**

No open recalls reported to CARFAX.

No Recalls Reported

**Basic Warranty**

Original warranty estimated to have expired.

**Warranty Expired**

**CARFAX** Title History

CARFAX guarantees the information in this section

**Owner 1**

**Damage Brands**

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

**Guaranteed**  
No Problem

**Odometer Brands**

Not Actual Mileage | Exceeds Mechanical Limits

**Guaranteed**  
No Problem