

Multi-Point Inspection Checklist

RO# 6029972

Customer Name INVENTORY: 1288221

Advisor Name Jim Smith

Technician Name Moore Alicia

Created on 7/8/2025 7:53 AM

Printed on 7/8/2025

Did your Service Advisor review the results of this multi-point inspection checklist with you?

-  Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-   Cold Engine start-up
-   Engine operation warm-up
-   Engine at normal operating temperature
-   Brake and parking operation
-   Active seat belt test
-   Clutch and transmission operations
-   Overdrive operation
-   Transfer case operation (4-wheel drive only)
-   Steering operation and off center
-   Front end alignment
-   Tilt steering wheel operation
-   Windshield wiper and washer operation at all speeds, wiper blade condition
-   Speedometer and odometer operation
-   Cruise Control operation, including resume
-   Heater and air condition operation
-   Abnormal noises and vibrations
-   Squeaks and rattles
-   Frame Check
-   Body surface, lower body, and upper body damage requiring body shop repair
-   Tire defects and damage, 5/32 7/32 front 7/32 rear, Pass
-   Drive shaft, joints, CV's and boots
-   Struts/shock absorbers, leaks and wear
-   Exhaust system leaks and damage, including catalytic converter
-   Fuel, oil, coolant, or other fluid leaks
-   Perform emissions test and/or state inspection if required
-   Under hood labels and decals
-    Air filter and In-Cabin Air Filter equipped BOTH FILTERS DIRTY 
-   Battery cables and mount
-   Coolant level and test
-   Under hood fluid levels, including transmission and transfer case fluids
-   Drive belts and hoses
-   Air conditioning levels, check at sight glass
-   Warning lights (including air bag) gauges & horn
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-   Inside and outside rearview mirror operation, adjustment, and condition

- Glass free of cracks, starts and large chips
- Dome , courtesy, map and sun visor lights and lighters and power ports
- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness **front 8mm rear 5mm, Caution**
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician

Date

Service Manager



Date

7-8.25

Used Car Manager

Date

Customer

Date

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone		R/O Open Date	R/O Number
Home Phone		7/08/25	6029972/1
Body		R/O Close Date	Receipt No.
SUV		7/15/25	Original
License Number		Mileage In	Mileage Out
		24550	24550
Year	Make	Service Advisor	
2023	NISSAN	Jim Smith	
Vehicle Identification Number		Account No.	In-Service Date
5N1DR3CC8PC202698			11/05/24
Color		Delivery Date	
WHITE			

INVENTORY: 1288221

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Work performed by Tech 853/ 0.40hrs @ 184.25 73.70 19432337 : N-OIL (08800-BOPCK) 6@8.10 48.60 1520865F0E : OIL FILTER 1@6.90 6.90 drain and refill with filter. 5.13 ow20	I	
#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION Work performed by Tech 853/ 1.00hrs @ 169.95 169.95 56 POINT INSPECTION COMPLETE	I	
#3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Work performed by Tech 853/ * 0.90hrs 59.95 4 WHEEL BANLANCE AND TIRE ROTATION COMPLETE	I	
#4 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Work performed by Tech 853/ * 1.50hrs 159.95 HUNTER ALIGNMENT COMPLETE	I	
#5 - RECALL: CHECK FOR OPEN RECALLS no open recalls on this vehicle at this time.	I	
#6 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	7/08/25	6029972/2
Body	R/O Close Date	Receipt No.
SUV	7/15/25	Original
License Number	Mileage In	Mileage Out
	24550	24550
Account No.	Service Advisor	
	Jim Smith	
Vehicle Identification Number	Delivery Date	In-Service Date
5N1DR3CC8PC202698		11/05/24
Color		
WHITE		

Year	Make	Model
2023	NISSAN	PATHFINDER
Vehicle Identification Number	Color	
5N1DR3CC8PC202698	WHITE	

INVENTORY: 1288221

Work performed by Tech 853/ * 0.10hrs	10.00	
272776CT0B : FILTER KIT - AIR, AIR CONDITI 1@49.95	49.95	
CABIN AIR FILTER REPLACED		

#7 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT		I
Corrected by AF: REPLACED ENGINE AIR FILTER		
Work performed by Tech 853/ * 0.10hrs	10.00	
165466TA0A : AIR CLEANER ELEMENT 1@29.95	29.95	
REPLACED FILTER		

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	483.55				
PARTS	135.40				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	648.94				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
136 Verified Reviews

♥ **102**
Customer Favorites

#1288221



Vehicle History Report™

US \$44.99

2023 NISSAN PATHFINDER SL

VIN: 5N1DR3CC8PC202698
4 DOOR WAGON/SPORT
UTILITY
3.5L V6
GASOLINE
FRONT WHEEL DRIVE W/ 4X4
Original Window Sticker
This CARFAX Report Provided
by:

Deery Brothers

★ 4.6 / 5.0

136 Verified Reviews

♥ 102 Customer Favorites

✓ No accidents or damage reported to CARFAX

🔧 5 Service history records

👤 2 Previous owners

🏠 Types of owners: Personal lease, Personal

🌍 Last owned in Missouri

📊 24,550 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 7/16/25 at 4:44:28 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	07/15/2025
 <div style="border: 1px solid blue; padding: 5px; display: inline-block;"> <p>This car has been recently serviced. That's a good thing!</p> </div>		

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Owner 2

Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have 5 months or 11,450 miles remaining. Confirm with dealer or vehicle manufacturer.	<input checked="" type="checkbox"/> Warranty Active	<input checked="" type="checkbox"/> Warranty Active

 Title History CARFAX guarantees the information in this section	Owner 1	Owner 2
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem


GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
[View Terms](#) | [View Certificate](#)

 Ownership History The number of owners is estimated	Owner 1	Owner 2
Year purchased	2022	2024
Type of owner	Personal lease	Personal
Estimated length of ownership	1 yr. 6 mo.	1 year
Owned in the following states/provinces	Tennessee	Missouri
Estimated miles driven per year	9,009/yr	10,504/yr
Last reported odometer reading	13,689	24,550



Detailed History



Owner 1
Purchased: 2022



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Lease
Vehicle
9,009 mi/yr

Date	Mileage	Source	Comments
Not Reported		Nissan North America, Inc.	Original Window Sticker 
10/12/2022		Dealer Inventory	Vehicle offered for sale
12/14/2022	14	Tennessee Motor Vehicle Dept.	Vehicle purchase reported - Titled or registered as personal lease vehicle
12/21/2022		Tennessee Motor Vehicle Dept. Greenville, TN	Title or registration issued - First owner reported
07/27/2023	6,540	Gateway Ford Lincoln Mazda Nissan Greenville, TN 423-639-5151 gatewayfordmazda.com/ ★ 4.9 / 5.0 35 Verified Reviews ❤️ 19 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Air filter checked - Battery/charging system checked - Brakes checked - Cabin air filter checked - Fluids checked - Oil and filter changed - Tires rotated
10/24/2023	10,949	Gateway Ford Lincoln Mazda Nissan Greenville, TN 423-639-5151 gatewayfordmazda.com/ ★ 4.9 / 5.0 35 Verified Reviews ❤️ 19 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Air filter checked - Battery/charging system checked - Brakes checked - Cabin air filter checked - Fluids checked - Oil and filter changed - Tires rotated
01/02/2024		Tennessee Motor Vehicle Dept. Greenville, TN	Registration issued or renewed
06/15/2024		Online Listing	Vehicle offered for sale
06/20/2024	13,689	Vehicle Manufacturer	Lease vehicle returned to dealer