

Multi-Point Inspection Checklist

RO# 6036506

Customer Name INVENTORY: 1288961B

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 1/28/2026 1:57 PM

Printed on 2/4/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

-  Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-    Cold Engine start-up
-    Engine operation warm-up
-    Engine at normal operating temperature
-    Brake and parking operation **fb 8mm rb 7mm**
-    Active seat belt test
-    Clutch and transmission operations
-    Overdrive operation
-    Transfer case operation (4-wheel drive only)
-    Steering operation and off center
-    Front end alignment
-    Tilt steering wheel operation
-    Windshield wiper and washer operation at all speeds, wiper blade condition
-    Speedometer and odometer operation
-    Cruise Control operation, including resume
-    Heater and air condition operation
-    Abnormal noises and vibrations
-    Squeaks and rattles
-    Frame Check
-    Body surface, lower body, and upper body damage requiring body shop repair
-     Tire defects and damage, 5/32 **ft 3/32 rt 3/32**
-    Drive shaft, joints, CV's and boots
-    Struts/shock absorbers, leaks and wear
-    Exhaust system leaks and damage, including catalytic converter
-    Fuel, oil, coolant, or other fluid leaks
-    Perform emissions test and/or state inspection if required
-    Under hood labels and decals
-     Air filter and In-Cabin Air Filter equipped **Found the cabin and engine air filter to be dirty**
-    Battery cables and mount

-    Coolant level and test
-    Under hood fluid levels, including transmission and transfer case fluids
-    Drive belts and hoses
-    Air conditioning levels, check at sight glass
-    Warning lights (including air bag) gauges & horn
-    Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-    Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips
- Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Year	Make	Model	License Number	Service Advisor
2020	TOYOTA	TACOMA		JAKE BACHTELL
Vehicle Identification Number		Color	Account No.	Delivery Date
5TFRX5GN0LX168282		GRAY		

Work Phone	R/O Open Date	R/O Number
	1/28/26	6036506/1
Home Phone	R/O Close Date	Receipt No.
	1/31/26	Original
Body	Mileage In	Mileage Out
TRUCK	53304	53304

INVENTORY: 1288961B

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95 169.95 19432337 : N-OIL (08800-BOPCK) 7@8.92 62.44 90915-YZZD1 : FILTER, OIL 1@9.53 9.53	I	
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 73.70	I	
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs 159.95	I	
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs 59.95	I	
#5 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 10.00 87139-YZZ09 : ELEMENT, AIR REFINER 1@49.95 49.95	I	
#6 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2020	TOYOTA	TACOMA
Vehicle Identification Number		Color
5TFRX5GN0LX168282		GRAY

TRUCK	53304	53304
JAKE BACHTTELL		

INVENTORY: 1288961B

Work performed by Tech 329/9 * 0.10hrs 10.00
17801-0C040 : ELEMENT SUB-ASSY, AI 1@29.95 29.95

#7 * 4T: REPLACE 4 TIRES MOUNT & BALANCE . INCLUDES WITH PURCHASE OF THESE TIRES - ORIGINAL OWNER WILL RECEIVE TIRE ROTATIONS FOR LIFE OF TIRE AND ONE YEAR DEERY ROAD HAZARD
Corrected by 4T: REPLACE 4 TIRES MOUNT & BALANCE . INCLUDES WITH PURCHASE OF THESE TIRES - ORIGINAL OWNER WILL RECEIVE TIRE ROTATIONS FOR LIFE OF TIRE AND ONE YEAR DEERY ROAD HAZARD LRATE:.00
Work performed by Tech 329/9 * 1.20hrs 100.00
19472523 : N-U24575167 (05880-BOPCKT) 4@170.78 683.12

Total Fee Amounts 34.00

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	583.55				
PARTS	834.99				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	1482.53				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
151 Verified Reviews

♥ **101**
Customer Favorites



Vehicle History Report™

US \$44.99

2020 TOYOTA TACOMA SR

VIN: 5TFRX5GN0LX168282
CLUB CAB PICKUP
2.7L I4 F DOHC 16V
GASOLINE
REAR WHEEL DRIVE

This CARFAX Report Provided by:


Deery Brothers

★ **4.6 / 5.0**

151 Verified Reviews

♥ **101** Customer Favorites

Damage reported: very minor damage




🔧 **9** Service history records

👍 **Great Reliability**

👤 **2** Previous owners

📊 **53,031** Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 1/31/26 at 11:46:27 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



CARFAX Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1

10/11/2022

Damage reported: very minor damage



CARFAX Reliability Forecast

Based on 2020 Toyota Tacoma SR with similar mileage

3-Year Reliability Forecast



Fair Reliability Good Reliability **Great Reliability**

Good news! This vehicle is expected to have low risk of repair and average repair costs.



What makes this vehicle have **great reliability**?

- Top 25%** compared to similar vehicles
- Average Repair Cost**
\$300 avg per year
- Low Likelihood of Repair**

Additional History Not all accidents / issues are reported to CARFAX	Owner 1	Owner 2
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage Damage reported: 10/11/2022.	Very Minor Damage	No New Issues Reported
Manufacturer Recall No open recalls reported to CARFAX. View Toyota disclosure	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired

Title History CARFAX guarantees the information in this section	Owner 1	Owner 2
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem