

Iti-Point Inspection Checklist

RO# 6038914

Customer Name INVENTORY: 1140001

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 4/17/2026 2:15 PM

Printed on 4/17/2026



Did your Service Advisor review the results of this multi-point inspection checklist with you?

Checked and OK at this time
 May Require Future Attention
 Requires immediate attention

Maintenance Service

- Cold Engine start-up Pass
- Engine operation warm-up Pass
- Engine at normal operating temperature Pass
- Brake and parking operation Pass
- Active seat belt test Pass
- Clutch and transmission operations Pass
- Overdrive operation Pass
- Transfer case operation (4-wheel drive only) Pass
- Steering operation and off center Pass
- Front end alignment Pass
- Tilt steering wheel operation Pass
- Windshield wiper and washer operation at all speeds, wiper blade condition Pass
- Speedometer and odometer operation Pass
- Cruise Control operation, including resume Pass
- Heater and air condition operation Pass
- Abnormal noises and vibrations Pass
- Squeaks and rattles Pass
- Frame Check Pass
- Body surface, lower body, and upper body damage requiring body shop repair Pass
- Tire defects and damage, 5/32 3/32 all
- Drive shaft, joints, CV's and boots Pass
- Struts/shock absorbers, leaks and wear Pass
- Exhaust system leaks and damage, including catalytic converter Pass
- Fuel, oil, coolant, or other fluid leaks Pass
- Perform emissions test and/or state inspection if required Pass
- Under hood labels and decals Pass
- Air filter and In-Cabin Air Filter equipped Fail air
- Battery cables and mount Pass
- Coolant level and test Pass
- Under hood fluid levels, including transmission and transfer case fluids Pass
- Drive belts and hoses Pass
- Air conditioning levels, check at sight glass Pass
- Warning lights (including air bag) gauges & horn check engine light on
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
- Inside and outside rearview mirror operation, adjustment, and condition Pass
- Glass free of cracks, starts and large chips Pass
- Dome, courtesy, map and sun visor lights and lighters and power ports Pass

- Window operation Pass
- Sunroof or convertible top operation N/A
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance Pass
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 6mm front 8mm rear
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL Pass
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician	Date
Service Manager 	Date 4.17
Used Car Manager 	Date 4-20-1
Customer	Date

6038914

4/21/26 9:02 AM

5XYPG4A36JG349704

DEERY DEERY



256 N/A



5XYPG4A36JG349704

Odometer:96037

Kia : Sorento : 2018 : Front Wheel Drive ExpressAlign Total Alignment



• One or more values are not within specification. Tire wear, handling and safety problems may result.

REPAIR ORDER - AUDIT			Work Phone	R/O Open Date	R/O Number
DEERY BROTHERS 200 S Gear Ave West Burlington, IA 52655				04/17/26	6038914/1
			Home Phone	R/O Close Date	Receipt No
				04/21/26	Original
			Body	Mileage In	Mileage Out
	SUV	96031	96031		
YEAR	MAKE	Model	License Number	Service Advisor	
2018	KIA	SORENTO		AMANDA KEPHART 1403	
Vehicle Identification Number		Color	Account No	Delivery Date	In-Service Date
5XYPG4A36JG349704		BLUE			

INVENTORY: 1140001

#1 - QL 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FI ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Work by Tech 256/756 0.40hrs @ 195.58 19419537 : N-OIL (08800-BOPCKT) 6@9.60 25161877 : SL-N-FILTER (01836-BOPCKT) 1@14.40 inspection complete	LL	I	78.23 57.60 14.40	11.20 25.86 5.94
#2 - QL 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION Work by Tech 256/756 1.00hrs @ 178.95 inspection complete		I	178.95	28.00
#3 - QL GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTAT Work by Tech 256/756 * 0.90hrs	E	I	99.00	25.20
#4 - QL ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTE COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Work by Tech 256/756 * 1.50hrs	D	I	159.95	42.00
#5 - QL RECALL: CHECK FOR OPEN RECALLS Corrected by NRE: NO RECALLS FOUND FOR VEHICLE AT THIS TIME. Work by Tech 256/756 0.00hrs @		I		
#6 * QL DIAG: DIAGNOSED AND PRICED REPAIR TO CUSTOMER CHECK ENGINE LIGHT ON - CHECK AND ADVISE Corrected by DIAG: DIAGNOSED AND PRICED REPAIR TO		I		

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT			Work Phone	R/O Open Date	R/O Number
DEERY BROTHERS 200 S Gear Ave West Burlington, IA 52655				04/17/26	6038914/2
			Home Phone	R/O Close Date	Receipt No
				04/21/26	Original
			Body	Mileage In	Mileage Out
	SUV	96031	96031		
YEAR	MAKE	Model	License Number	Service Advisor	
2018	KIA	SORENTO		AMANDA KEPHART 1403	
Vehicle Identification Number		Color	Account No	Delivery Date	In-Service Date
5XYPG4A36JG349704		BLUE			

INVENTORY: 1140001

<p>CUSTOMER Work by Tech 256/756 * 1.00hrs Corrected by 0999: MISCELLANEOUS REPAIR - MAINTENANCE ITEMS Work by Tech 256/756 0.60hrs @ 186.82 25224 : 02 SENSOR 1@225.45 check engine light caused by 02 sensor code</p>			160.00		28.00
<p>----- #7 * QL AF: REPLACED ENGINE AIR FILTER Corrected by AF: REPLACED ENGINE AIR FILTER Work by Tech 256/756 * 0.10hrs PA99071 : AIR FILTER 1@29.95 air filter replaced</p>			12.00 29.95	I	2.80 11.70
<p>----- #8 * QL 4T: REPLACE 4 TIRES MOUNT & BALANCE . INCLUDES WITH PURCHASE OF THESE TIRES - ORIGINAL OWNER WILL RECEIVE TIRE ROTATIONS FOR LIFE OF TIRE AND ONE YEAR DEERY ROAD HAZARD 19531329 - KELLY EDGE TOUR PLUS 235.65R17 Corrected by 4T: REPLACE 4 TIRES MOUNT & BALANCE . INCLUDES WITH PURCHASE OF THESE TIRES - ORIGINAL OWNER WILL RECEIVE TIRE ROTATIONS FOR LIFE OF TI AND ONE YEAR DEERY ROAD HAZARD Work by Tech 256/756 * 1.20hrs TIRE DISPOSAL FEE 4 TIRES 19531329 : N-TIRE (05880-BOPCKT) 4@152.88</p>			100.00 34.00 611.52	I	33.60 507.56
Account	Description	Control	Re	ference	Amount
46150	SLS-SRV-QUICKLANE LABOR-OTHER	6038914		6038914	-900.22
24700	INV-WORK IN PROCESS SERVICE	217756		6038914	-187.60
66150	CST-SRV-QUICKLANE-LABOR-OTHER	6038914		6038914	187.60
49010	SLS-PTS- TIRES & TUBES INTERN	6038914		6038914	-611.52
69010	CST-PTS- TIRES & TUBES INTERN	6038914		6038914	507.56
24300	INVENTORY - TIRES - GM,MAZ,OT	6038914		6038914	-507.56
46750	SLS-PTS-CUSTOMER MECH RO-OTHE	6038914		6038914	-255.40
66750	CST-PTS-CUSTOMER MECH RO-OTHE	6038914		6038914	123.31
24230	INVENTORY-PTS/ACCESS-OTHER	6038914		6038914	-123.31

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
160 Verified Reviews

♥ **101**
Customer Favorites



Report

US \$44.99

2018 Kia Sorento LX

95,985 mi | VIN: 5XYPG4A36JG349704 |

4 Door Wagon/Sport Utility | 2.4L I4 F DOHC 16V | Gasoline | Front wheel drive



NO ACCIDENTS REPORTED

✓ No Accidents or Damage Reported to CARFAX

GOOD VALUE \$12,518

\$202 below \$12,720 CARFAX Value



GOOD RELIABILITY



🛢️ Regular Oil Changes

👤 2 Previous Owners

🏠 Personal Vehicle

🌍 Last Owned in Illinois

📄 49 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/21/26 at 6:39:06 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	02/11/2026
💧 Flashes ⓘ	✓ Antifreeze/coolant flushed/changed	01/02/2026

This car has been recently serviced. That's a good thing!

CARFAX History-Based Value Report

\$12,518

Listing Price*

What makes this vehicle a good value?

↑ ✓ No Accidents Reported

GOOD VALUE \$202 below
\$12,720 CARFAX Value ⓘ

Fair Value **Good Value** Great Value

*As reported to CARFAX as of 4/20/26 10:16:35 PM (CDT)

- ↑ Regular Oil Changes
- ↑ Personal Vehicle

CARFAX Reliability Forecast
Based on 2018 Kia Sorento LX with similar mileage

3-Year Reliability Forecast

Fair Reliability **Good Reliability** Great Reliability

Good news! This vehicle is expected to have average risk of repair and average repair costs.

What makes this vehicle have good reliability?

- Top 50%** compared to similar vehicles
- Average Repair Cost**
\$310 avg per year
- Oil Changes** performed regularly
- Average Likelihood of Repair**

CARFAX Additional History Not all accidents / issues are reported to CARFAX	Owner 1	Owner 2
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired

CARFAX Title History CARFAX guarantees the information in this section	Owner 1	Owner 2
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem

GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
[View Terms](#) | [View Certificate](#)

CARFAX Ownership History The number of owners is estimated	Owner 1	Owner 2
Year purchased	2017	2026