

Multi-Point Inspection Checklist

RO# 6012164

Customer Name INVENTORY: 963290

Advisor Name Anton Umek

Technician Name Kolton Bell

Created on 2/1/2024 9:47 AM

Printed on 2/1/2024

Did your Service Advisor review the results of this multi-point inspection checklist with you?

Checked and OK at this time May Require Future Attention Requires immediate attention

Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 7/32 all four tires
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emissions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In-Cabin Air Filter equipped
- Battery cables and mount
- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition

- Glass free of cracks, starts and large chips
- Dome , courtesy, map and sun visor lights and lighters and power ports
- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position


- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 9mm in front and 8mm in rear
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL has an open recall
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician

Date

Service Manager



Date

2-1-21

Used Car Manager

Date

Customer

Date

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2022	TOYOTA	COROLLA CROSS
Vehicle Identification Number	Color	
7MUDAABG1NV036837	RED	

INVENTORY: 963290

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION Work performed by Tech 496/ 56 point inspection	1.00hrs @ 169.95	169.95	I
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Work performed by Tech 496/ 90915-YZZN1 : FILTER S/A, OIL chnaged oil and filter	0.40hrs @ 184.25 1@5.97	73.70 5.97	I
#3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Work performed by Tech 496/ rotated tires	* 0.90hrs	45.95	I
#4 - ALIGN: DEERY BROTHERS COMPUTERIZED ALIGNMENT SERVICE . IN CLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUST ABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR R USTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: DEERY BROTHERS COMPUTERIZED ALIGNMENT SERVICE . IN CLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUST ABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR R USTED COMPONENTS AND OR PART REPLACEMENT . Work performed by Tech 496/	* 1.60hrs	149.95	I
#5 - RECALL: CHECK FOR OPEN RECALLS Corrected by SOP: PARTS TO REPAIR YOUR VEHICLE HAD TO BE SPECIAL ORD ERED. WE WILL CONTACT YOU AS SOON AS WE RECEIVE TH E REQUIRED PARTS TO REPAIR YOUR VEHICLE. IF YOU HA VE ANY FURTHER QUESTIONS PLEASE CONTACT THE SERVIC Work performed by Tech 496/	0.00hrs @		I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
 200 S Gear Ave
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2022	TOYOTA	COROLLA CROSS
Vehicle Identification Number		Color
7MUDAABG1NV036837		RED

2/01/24	6012164/2
2/05/24	Original
15437	15437
Anton Umek	
11/15/22	11/15/22

INVENTORY: 963290

1 open recall				

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	439.55				
PARTS	5.97				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	22.77				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	468.29				

963290



Experian AutoCheck Report

Report run: 01/30/2024 17:19:49 EST

ISD = 11-15-22

Steve

2022 Toyota Corolla Cross XLE

Wagon 4D (2.0L I4 DI)

VIN: 7MJDAABG1NV036837

Class: SUV - Compact

Country of Assembly: United States

Vehicle Age: 2 year(s)

Last Reported Odometer: 11 (10/04/2022)

One Owner
AutoCheck

Vehicle Usage
Lease



AutoCheck Score

Similar vehicles usually range between 89 and 94

Vehicle History at a Glance



State Title Brand



CLEAN



Auction Brand / Issues



NO ISSUE



Accident / Damage

No Accidents or Damage Reported



NO ISSUE



Open Recall Check



1 OPEN RECALL(S)



Insurance Loss / Transfer



NO ISSUE



Odometer Check

Last reported odometer:
11 (10/04/2022)



NO ISSUE



Certified Pre-Owned



NO CPO INFO AVAILABLE



Service / Repair



NO ISSUE



Additional History

Lien Reported



EVENTS REPORTED




This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. Terms & Conditions

[Learn More](#)

Your Vehicle Checks Out AutoCheck has not received any accident or damage-related events from government sources, independent agencies, or auction sources. Not all damage-related events are reported to AutoCheck. It is recommended to have pre-owned vehicles inspected by a third-party prior to purchase.



No Accidents or Damage Reported

Airbag Deployed

Structural Damage

Overtuned

No Damage

Open Recall Check



Information Reported: AutoCheck found 1 open recall(s).

It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date - 12/20/2023

Recall Type - Safety

NHTSA / OEM Recall No. - 23V864 / 23TA16-24942

Campaign Description - Safety Recall: SAFETY (NONCOMPLIANCE) RECALL 23TA16 (REMEDY NOTICE) - CERTAIN 2022-2023 MODEL YEAR COROLLA CROSS - PASSENGER AIRBAG MAY NOT DEPLOY AS DESIGNED

Status: Remedy Unknown

More information including remedy or risk factors. Locate your nearest authorized Toyota Dealer to schedule repair.

Odometer Check



Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check

No issues reported



Auction Odometer Check

No issues reported



Odometer Calculation Check

No issues reported

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2022 Toyota Corolla Cross XLE (7MUDAABG1NV036837) Report Run Date: 01/30/2024 17:19:49 EST

2022

Vehicle Prep and Other Pre-Titling Events

Preparation Date: 09/2022

Event Date	Location	Odometer	Data Source	Details
09/26/2022			Independent Source	Vehicle Manufactured and Shipped to Dealer
10/04/2022	ONLINE DEALER	11	Dealer Listing	Vehicle Listed for Sale

2023

Owner 1

Location: IL	Owned From: 01/2023	Usage: Lease
--------------	---------------------	--------------

Event Date	Location	Odometer	Data Source	Details
01/05/2023	LOMAX, IL		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
01/13/2023	LOMAX, IL		Motor Vehicle Dept.	Title(Leased Vehicle)(Lien Reported)

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to **AutoCheck Terms and Conditions**. If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (7MUDAABG1NV036837) qualifies for **AutoCheck Buyback Protection**. If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbptterms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.

7MUDAABG1NV036837 - 2022 Corolla Cross XLE (6306) L4 - M20A-FKS, CVT-F/4WD, 03R3-BARCELONA RED METALLIC



Campaign

Campaign Description: SAFETY (NONCOMPLIANCE) RECALL 23TA04 (Remedy Notice) - Certain 2022-2023 Model Year Corolla Cross - Passenger Airbag May Not Deploy as Designed
Campaign Status: Remedy Available
Completion Status: Completed
Date Serviced: 08/22/2023
Dealer Name: DEERY BROTHERS TOYOTA
Dealer Code: 14036

Safety (Noncompliance) Recall 23TA04; 2022-2023 Corolla Cross: Passenger Airbag May Not Deploy as Designed (Dealer Letter)
Safety (Noncompliance) Recall 23TA04; 2022-2023 Corolla Cross: Passenger Airbag May Not Deploy as Designed (Technical Instructions)

Tech Cert Requirements:

Required Courses:
 *TIC206A-TIC206A - Electrical Repair 1

Campaign Description: SAFETY (NONCOMPLIANCE) RECALL 23TA16 (Remedy Notice) - Certain 2022-2023 Model Year Corolla Cross - Passenger Airbag May Not Deploy as Designed
Campaign Status: Remedy Available
Completion Status: Not Completed
Estimated Repair Time: 4.2
Parts Required: Yes

Safety (Noncompliance) Recall 23TA16; 2022-2023 Corolla Cross: Passenger Airbag May Not Deploy as Designed (Dealer Letter)
Safety (Noncompliance) Recall 23TA16; 2022-2023 Corolla Cross: Passenger Airbag May Not Deploy as Designed (Technical Instructions)

Tech Cert Requirements:

Required Courses:
 *TIC206A-TIC206A - Electrical Repair 1

Service History

Warranty NSH

Customer Pay	Warranty Paid	Internal (DEALER) Pay	Goodwill	Total Amount
\$33.11	\$202.63	\$115	\$0	\$350.74

RO Close	Source	Mileage	Dealer	RO Number	RO Total	RO Open	Service Advisor
03/17/2023	NSH	4729	DEERY BROT (14036)	6000721	\$33.11	03/14/2023	CAHILL, LEVI
Condition: 1- Op Code Desc NO CHARGE TOYOTA EXPRESS LUBE MULTI POINT VEHICLE ...					Pay Type: CUSTOMER PAY		
Condition: 2- Op Code Desc CHECK FOR OPEN RECALLS ~ ~CHECK FOR OPEN RECALLS O...					Pay Type: CUSTOMER PAY		
Condition: 3- Op Code Desc 1ST TOYOTACARE NO COST SERVICE TIRE ROTATE, MULTI...					Pay Type: CUSTOMER PAY		
RO Close	Source	Mileage	Dealer	RO Number	RO Total	RO Open	Service Advisor

11/18/2022	NSH	11	DEERY BROT (14036)	0748541	\$40	11/15/2022	
Condition: 1- Op Code Desc CLEAN FOR DELIVERY ~ ~CLEAN FOR DELIVERY ~ ~ Pay Type: INTERNAL (DEALER) PAY							
RO Close	Source	Mileage	Dealer	RO Number	RO Total	RO Open	Service Advisor
10/31/2022	NSH	10	DEERY BROT (14036)	0747611	\$75	10/27/2022	
Condition: 1- Op Code Desc NEW VEHICLE SETUP ~ ~NEW VEHICLE SETUP ~ ~ Pay Type: INTERNAL (DEALER) PAY							
RO Close	Source	Mileage	Dealer	RO Number	RO Total	RO Open	Service Advisor
10/26/2022	NSH	2	DEERY BROT (14036)	0747322	\$103.64	10/24/2022	
Condition: 1- Op Code Desc PRE-DELIVERY SERVICE FOR USA ALL ALTITUDES ~ ~PERF... Pay Type: WARRANTY PAY							
Condition: 2- Op Code Desc CHECK FOR OPEN RECALLS ~ ~CHECK FOR OPEN RECALLS. ... Pay Type: INTERNAL (DEALER) PAY							
Condition: 3- Op Code Desc INSTALL 1ST OIL CHANGE REMINDER STICKER ON LEFT UP... Pay Type: INTERNAL (DEALER) PAY							

Warranty

Vehicle Warranty Information

WARRANTY APPLICABILITY QUICK REFERENCE CHART

2022 Corolla Cross VIN: 7MUDAABG1NV036837 Retailed State: IA

Current Months In service: 15

Last Known Mileage: 15437

State: IA

Category	Months	Mileage	Eligible
Basic	36	36,000	YES
OEM 12V Auxillary Battery	36	36,000	YES
Wheel Alignment and Balancing	12	12,000	NO
Federal Emission Warranty			
Short Term	36	36,000	YES
Long Term	36	36,000	YES
Specific Components	96	80,000	YES
Performance Emission Control Warranty			
All Parts to pass I/M programs	24	24,000	YES
Specific Components	96	80,000	YES
Powertrain & Restraint Systems	60	60,000	YES
Corrosion Perforation	60	Unlimited	YES
Accessories installed at Vehicle Purchase	36	36,000	YES

Warranty Applicability Quick Reference Chart not available for Mexico or Canada market vehicles.

Refer to appropriate Warranty Policy and Procedures guide instead.

Warranty Policy and Procedures

- Warranty is dependent on both the number of months and mileage covered, and the terms, conditions, limitations and exclusions set forth in the New Vehicle Limited Warranty/TCUV and CPO Warranties. If either "Current Months In Service" or "Last Known Mileage" is beyond the applicable warranty coverage, then the vehicle is no longer covered under that warranty category. Last known mileage may have changed - confirm current mileage.
- Please note the information shown above may be subject to change without notice. Refer to applicable warranty for specific terms and conditions.
- Please note the emissions warranty logic in the graph above is based only on the selected state (which defaults to your dealership state) and may not accurately reflect the vehicle's actual warranty coverage. Vehicle must be retailed, registered and normally operated in California or any other state that adopts California emission warranty provisions. Refer to Policy 4.7, California Emission Warranty, to determine a vehicle's applicable warranty coverage.

Customer Support Program

No INFORMATION found for VIN: 7MUDAABG1NV036837

