

Multi-Point Inspection Checklist

RO# 6037874

Customer Name INVENTORY: 968051

Advisor Name JAKE BACHTELL

Technician Name Dylan Miller

Created on 3/13/2026 7:41 AM

Printed on 3/31/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?



Checked and OK at this time



May Require Future Attention



Requires immediate attention

Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 all four tires are at 11/32nds
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emissions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In-Cabin Air Filter equipped cabin air filter and engine air filter are dirty
- Battery cables and mount
- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips
- Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
missing passenger front floor mat
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness **front pads are at 10mm, rear pads are at 6mm**
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2023	NISSAN	ROGUE
Vehicle Identification Number	Color	
JN8BT3BB9PW467221	OTHER	

INVENTORY: 968051

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 461/4 1.00hrs @ 169.95 performed 56 point inspection	I	169.95
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 461/4 0.40hrs @ 184.25 73.70 19432337 : N-OIL (08800-BOPCK) 5@9.60 48.00 1520865F1E : OIL FILTER 1@6.95 6.95 changed engine oil and filter. reset maintenance and installed sticker	I	73.70 48.00 6.95
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 461/4 * 1.50hrs 159.95 performed alignment. front toe was out of specs. set front toe and test drove. wheel was straight and vehicle drove straight	I	159.95
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 461/4 * 0.90hrs 99.00 balanced and rotated all four wheels	I	99.00
#5 * RECALL: CHECK FOR OPEN RECALLS perform recall - P4A47 ROGUE TURBO HOSE	W	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
	3/13/26	6037874/2
Home Phone	R/O Close Date	Receipt No.
	3/20/26	Original
Body	Mileage In	Mileage Out
	72128	72128

Year	Make	Model	License Number	Service Advisor
2023	NISSAN	ROGUE		JAKE BACHTTELL
Vehicle Identification Number		Color	Account No.	Delivery Date
JN8BT3BB9PW467221		OTHER		In-Service Date
				2/27/24

INVENTORY: 968051

<p>Caused by performed recall Corrected by P4A470: CHECK FOR OPEN RECALLS performed recall LRATE:149.75 Work performed by Tech 461/4 0.20hrs @ 149.75 29.95 A18236RC4A : HOSE ASSY-BLOW BY,A 1@15.60 15.60 performed recall as per bulletin# P4A47 Replace Turbo Hose labor code# P4A470 lt 0.2hrs</p>			
<p>#6 * RECALL: CHECK FOR OPEN RECALLS perform R25D1 - R25D1 ROGUE MY2123 KR ENG NTB25055 Caused by performed recall Corrected by R25D10: CHECK FOR OPEN RECALLS performed recall LRATE:149.75 Work performed by Tech 461/4 0.90hrs @ 149.75 134.78 performed recall as per bulletin# R25D1 Reprogram ECM and Complete Test Drive with NO DTC P0524 present GOOD CONDITION labor code# R25D10 lt 0.9hrs old part# 23761 6rx4a new part# 23761jh94b</p>		W	
<p>#7 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00 Work performed by Tech 461/4 * 0.10hrs 12.00 CAF15027C : CABIN FILTER 1@49.95 49.95 replaced in cabin filter</p>		I	
<p>#8 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00 Work performed by Tech 461/4 * 0.10hrs 12.00 SA50183 : ENGINE AIR FILTER 1@29.95 29.95</p>		I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
 200 S Gear Ave
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2023	NISSAN	ROGUE
Vehicle Identification Number	Color	
JN8BT3BB9PW467221	OTHER	

3/13/26	6037874/3
3/20/26	Original
72128	72128
JAKE BACHTELL	
	2/27/24

INVENTORY: 968051

replaced engine air filter

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	526.60		164.73		
PARTS	134.85		15.60		
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	691.44		180.33		



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
159 Verified Reviews

♥ **101**
Customer Favorites



Report

US \$44.99

2023 Nissan Rogue SV

72,128 mi | VIN: JN8BT3BB9PW467221 |
4 Door Wagon/Sport Utility | 1.5L I3 F DOHC 12V | Gasoline | All wheel drive



NO ACCIDENTS REPORTED

✓ No Accidents or Damage Reported to CARFAX

🔧 14 Service history records

1 CARFAX 1-Owner vehicle

🏠 Personal lease vehicle

🌍 Last owned in Iowa

📄 21 Detailed records available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/31/26 at 5:34:13 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢️ Oil	✓ Oil and filter changed	03/20/2026
🛞 Tires	✓ Tires rotated	03/20/2026

This car has been recently serviced. That's a good thing!

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

👤 Owner 1

Total Loss

No total loss reported to CARFAX.


✓ No Issues Reported

Structural Damage


No structural damage reported to CARFAX.



✓ No Issues Reported

Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

CARFAX Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

CARFAX Ownership History The number of owners is estimated	Owner 1
Year purchased	2023
Type of owner	Personal lease
Estimated length of ownership	3 years
Owned in the following states/provinces	Iowa
Estimated miles driven per year	23,611/yr
Last reported odometer reading	72,128



CARFAX Detailed History			
Owner 1 Purchased: 2023	Personal Lease Vehicle 23,611 mi/yr		
Date	Mileage	Source	Comments
Not Reported		Nissan North America, Inc.	Original Window Sticker 
01/16/2023	4	Hawk Chevrolet Mercedes Nissan Peru, IL 815-223-7000 hawkautoperu.com/ ★ 4.7 / 5.0 104 Verified Reviews ❤️ 1,488 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed - Nitrogen fill tires - Wheel locks installed
01/18/2023	8	Hawk Chevrolet Mercedes Nissan Peru, IL 815-223-7000	Vehicle sold