

Multi-Point Inspection Checklist

RO# 6035474

Customer Name INVENTORY: 968421

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 12/22/2025 3:09 PM

Printed on 12/23/2025

Did your Service Advisor review the results of this multi-point inspection checklist with you?


 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-  Cold Engine start-up Pass
-  Engine operation warm-up Pass
-  Engine at normal operating temperature Pass
-  Brake and parking operation Pass
-  Active seat belt test Pass
-  Clutch and transmission operations Pass
-  Overdrive operation Pass
-  Transfer case operation (4-wheel drive only) Pass
-  Steering operation and off center Pass
-  Front end alignment Pass
-  Tilt steering wheel operation Pass
-  Windshield wiper and washer operation at all speeds, wiper blade condition Pass
-  Speedometer and odometer operation Pass
-  Cruise Control operation, including resume Pass
-  Heater and air condition operation Pass
-  Abnormal noises and vibrations Pass
-  Squeaks and rattles Pass
-  Frame Check Pass
-  Body surface, lower body, and upper body damage requiring body shop repair Pass
-  Tire defects and damage, 5/32 6/32 all
-  Drive shaft, joints, CV's and boots Pass
-  Struts/shock absorbers, leaks and wear Pass
-  Exhaust system leaks and damage, including catalytic converter Pass
-  Fuel, oil, coolant, or other fluid leaks Pass
-  Perform emissions test and/or state inspection if required Pass
-  Under hood labels and decals Pass
-  Air filter and In-Cabin Air Filter equipped Pass
-  Battery cables and mount Pass
-  Coolant level and test -50
-  Under hood fluid levels, including transmission and transfer case fluids Pass
-  Drive belts and hoses Pass
-  Air conditioning levels, check at sight glass Pass
-  Warning lights (including air bag) gauges & horn Pass
-  Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-  Inside and outside rearview mirror operation, adjustment, and condition Pass
-  Glass free of cracks, starts and large chips Pass
-  Dome, courtesy, map and sun visor lights and lighters and power ports Pass

- Window operation Pass
- Sunroof or convertible top operation Pass
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance Pass
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 8mm all
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL Pass
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____



Service Manager  _____ Date 12-22-25

Used Car Manager _____ Date _____

Customer _____ Date _____



Chevrolet : Trax : 2024 ExpressAlign Total Alignment



• One or more values are not within specification. Tire wear, handling and safety problems may result.

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2024	CHEVROLET	TRAX
Vehicle Identification Number	Color	
KL77LFE25RC225087		

INVENTORY: 968421

<p>#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 256/ 0.40hrs @ 184.25 73.70 19419537 : N-OIL (08800-BOPCKT) 5@7.25 36.25 25206966 : SL-N-FILTER (01836-BCKT) 1@10.49 10.49 new oil and filter</p>		I
<p>#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 256/ 1.00hrs @ 169.95 169.95</p>		I
<p>#3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 256/ * 0.90hrs 59.95 wheels have been rotated and balanced</p>		I
<p>#4 - RECALL: CHECK FOR OPEN RECALLS Corrected by NRF: NO RECALLS FOUND FOR VEHICLE AT THIS TIME. LRATE:180.14 Work performed by Tech 256/ 0.00hrs @</p>		I
<p>#5 * ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 256/ * 1.50hrs 159.95</p>		I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	463.55				
PARTS	46.74				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	540.28				



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
147 Verified Reviews

♥ **102**
Customer Favorites



Vehicle History Report™

US \$44.99

2024 CHEVROLET TRAX LS

VIN: KL77LFE25RC225087
4 DOOR WAGON/SPORT UTILITY
1.2L I3 F DOHC 12V GASOLINE
FRONT WHEEL DRIVE
Original Window Sticker
This CARFAX Report Provided by:

Deery Brothers

★ **4.6 / 5.0**
147 Verified Reviews
♥ **102** Customer Favorites

✓ No accidents or damage reported to CARFAX

✂ 4 Service history records

1 CARFAX 1-Owner vehicle

🏠 Personal vehicle

🌍 Last owned in Illinois

📊 21,501 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 12/27/25 at 10:13:46 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	12/23/2025
🛞 Tires	✓ Tires rotated	12/23/2025

This car has been recently serviced. That's a good thing!

 Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have 17 months or 14,499 miles remaining. Confirm with dealer or vehicle manufacturer.	<input checked="" type="checkbox"/> Warranty Active

 Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
[View Terms](#) | [View Certificate](#)

 Ownership History The number of owners is estimated	Owner 1
Year purchased	2024
Type of owner	Personal
Estimated length of ownership	1 yr. 7 mo.
Owned in the following states/provinces	Illinois
Estimated miles driven per year	13,241/yr



Last reported odometer reading

21,501

CARFAX Detailed History



Owner 1
Purchased: 2024



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
13,241 mi/yr

Date	Mileage	Source	Comments
Not Reported		General Motors	Original Window Sticker
05/03/2024	2	Essig Motors Aledo, IL 309-582-5336 essigs.com ★ 4.9 / 5.0 18 Verified Reviews ❤️ 43 Customer Favorites	Vehicle serviced - Pre-delivery inspection completed - Fluids checked - Nitrogen fill tires
05/07/2024		Illinois Motor Vehicle Dept.	Vehicle purchase reported - Titled or registered as personal vehicle
05/28/2024	14	Illinois Motor Vehicle Dept. Aledo, IL	Title issued or updated - Registration issued or renewed - First owner reported - Loan or lien reported - Vehicle color noted as Blue
11/22/2024	6,571	Essig Motors Aledo, IL 309-582-5336 essigs.com ★ 4.9 / 5.0 18 Verified Reviews ❤️ 43 Customer Favorites	Vehicle serviced - Body lubricated - Oil and filter changed
04/02/2025	10,207	Essig Motors Aledo, IL 309-582-5336 essigs.com ★ 4.9 / 5.0 18 Verified Reviews	Vehicle serviced - Body lubricated - Brakes checked - Oil and filter changed