

Multi-Point Inspection Checklist

RO# 6037301

Customer Name INVENTORY: 968221

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 2/24/2026 10:11 AM

Printed on 3/3/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

 Checked and OK at this time  May Require Future Attention  Requires immediate attention

Maintenance Service

-   Cold Engine start-up
-   Engine operation warm-up
-   Engine at normal operating temperature fb 8mm rb 7mm
-   Brake and parking operation
-   Active seat belt test
-   Clutch and transmission operations
-   Overdrive operation
-   Transfer case operation (4-wheel drive only)
-   Steering operation and off center
-   Front end alignment
-   Tilt steering wheel operation
-    Windshield wiper and washer operation at all speeds, wiper blade condition Found both front wiper blades to streak
-   Speedometer and odometer operation
-   Cruise Control operation, including resume
-   Heater and air condition operation
-   Abnormal noises and vibrations
-   Squeaks and rattles
-   Frame Check
-   Body surface, lower body, and upper body damage requiring body shop repair
-    Tire defects and damage, 5/32
ft 5/32 rt 7/32 found both rear tires to be extremely unworn on the inside and causing a vibration
-   Drive shaft, joints, CV's and boots
-   Struts/shock absorbers, leaks and wear
-   Exhaust system leaks and damage, including catalytic converter
-   Fuel, oil, coolant, or other fluid leaks
-   Perform emissions test and/or state inspection if required
-   Under hood labels and decals
-   Air filter and In-Cabin Air Filter equipped
-   Battery cables and mount
-   Coolant level and test
-   Under hood fluid levels, including transmission and transfer case fluids
-   Drive belts and hoses
-   Air conditioning levels, check at sight glass
-    Warning lights (including air bag) gauges & horn Found the check engine light to be on
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
-   Inside and outside rearview mirror operation, adjustment, and condition
-   Glass free of cracks, starts and large chips

- Dome , courtesy, map and sun visor lights and lighters and power ports
- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

R/O Open Date	R/O Number
02/24/26	6037301/1
Time Received	Time Promised
	2/24 17:00
Current Mileage	Mileage Out
50218	

Estimate of Repairs	Service Advisor / Tag #
	JAKE BACHTTELL/4828

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	Vehicle Identification Number	
	KMHL64JA9PA323392	
Home Phone	Delivery Date	In-Service Date

YEAR	MAKE	Model	Body	Color	License Number
2023	HYUNDAI SONATA		SEDAN	BLACK	

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
----------------------------------	--------

INVENTORY: 968221

#1 - 4: 56 POINT INSPECTION	I	
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS	I I	
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT .	I I I I	
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE	I	
#5 - SES: CHECK ENGINE LIGHT IS ON	I	
Total Estimate:		502.60

TERMS: STRICTLY CASE UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs hereof."

DISCLAIMER OF WARRANTIES: Any warranties on the product sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and he seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.



This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

★ **4.6 / 5.0**
159 Verified Reviews

♥ **101**
Customer Favorites



Report

US \$44.99

2023 Hyundai Sonata Sel

50,034 mi | VIN: KMHL64JA9PA323392 |
Sedan 4 DR | 2.5L I4 | Gasoline | Front wheel drive



NO ACCIDENTS REPORTED

✓ No Accidents or Damage Reported to CARFAX

GREAT RELIABILITY



🔧 2 Service history records

1 CARFAX 1-Owner vehicle

🏠 Personal vehicle

🌍 Last owned in Iowa

📄 9 Detailed records available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/30/26 at 5:56:37 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights

Key services performed in the last 12 months


Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	12/27/2025

This car has been recently serviced. That's a good thing!

CARFAX Reliability Forecast

Based on 2023 Hyundai Sonata Sel with similar mileage

3-Year Reliability Forecast



What makes this vehicle have great reliability?

- 🏆 Top 50% compared to similar vehicles
- \$\$\$ Low Repair Cost
\$240 avg per year
- 🔧 Low Likelihood of Repair

Good news! This vehicle is expected to have low risk of repair and low repair costs.



CARFAX Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Total Loss

No total loss reported to CARFAX.

✓ No Issues Reported

Structural Damage

No structural damage reported to CARFAX.

✓ No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.

✓ No Issues Reported

Odometer Check

No indication of an odometer rollback.

✓ No Issues Indicated

Accident / Damage

No accidents or damage reported to CARFAX.

✓ No Issues Reported

Manufacturer Recall

No open recalls reported to CARFAX.

✓ No Recalls Reported

Basic Warranty

Original warranty estimated to have 30 months or 9,966 miles remaining. Confirm with dealer or vehicle manufacturer.

✓ Warranty Active

CARFAX Title History

CARFAX guarantees the information in this section

Owner 1

Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

✓ Guaranteed No Problem

Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits

✓ Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

CARFAX Ownership History

The number of owners is estimated

Owner 1

Year purchased

2023

Type of owner

Personal

Estimated length of ownership

2 yrs. 5 mo.

Owned in the following states/provinces

Iowa

Estimated miles driven per year

20,246/yr

Last reported odometer reading




50,034



CARFAX Detailed History

Owner 1
Purchased: 2023
Personal Vehicle
20,246 mi/yr

Date	Mileage	Source	Comments
------	---------	--------	----------

05/18/2023		Hyundai Motor America		Vehicle manufactured and shipped to Iowa - Original Manufacturer's Suggested - Retail Price: \$29,375 Original Window Sticker 
09/01/2023		Iowa Motor Vehicle Dept. Bloomfield, IA		Titled or registered as personal vehicle
09/04/2023	43	Service Plan Co. Bloomfield, IA		Service contract issued
09/08/2023		Iowa Motor Vehicle Dept. Bloomfield, IA Title #26AA58654		Title or registration issued - First owner reported - Vehicle color noted as Blue
07/19/2024		Iowa Motor Vehicle Dept. Bloomfield, IA Title #26AA58654		Registration issued or renewed - Vehicle color noted as Blue
05/27/2025		Iowa Motor Vehicle Dept. Bloomfield, IA Title #26AA58654		Registration issued or renewed - Vehicle color noted as Blue
07/01/2025	35,420	Fesler Auto Mall Fairfield, IA 641-472-3121 feslerautomall.com ★ 4.9 / 5.0 55 Verified Reviews ❤️ 1 Customer Favorite		Vehicle serviced - Maintenance inspection completed - Cabin air filter replaced/cleaned - Oil and filter changed
12/27/2025	46,055	Fesler Auto Mall Fairfield, IA 641-472-3121 feslerautomall.com ★ 4.9 / 5.0 55 Verified Reviews ❤️ 1 Customer Favorite		Vehicle serviced - Maintenance inspection completed - Air filter replaced - Oil and filter changed
02/19/2026	50,034	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ 4.6 / 5.0 159 Verified Reviews ❤️ 101 Customer Favorites		Vehicle offered for sale

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.

CARFAX Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Reliability Forecast

The CARFAX 3-Year Reliability Forecast predicts the likelihood of repairs for a vehicle over the next three years. This forecast is based on vehicles of the same year, make, and model with similar mileage, damage, service history, and other factors, and assumes an average of 15,000 miles driven per year. Repairs are

3/30/26, 5:56 PM

CARFAX Vehicle History Report for this 2023 HYUNDAI SONATA SEL: KMHL64JA9PA323392

separate from regular maintenance, such as oil changes. Some of the repairs predicted may be covered under warranty. The 3-Year Reliability Forecast is based on data reported to Carfax and is only a prediction, not a guarantee.

Follow Us:  facebook.com/CARFAX  [@CARFAXinc](https://twitter.com/CARFAXinc)  [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.
3/30/26 5:56:37 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2023 HYUNDAI SONATA vehicle (VIN: KMHL64JA9PA323392), which is based on information supplied to CARFAX and available as of 3/30/26 at 6:56 PM (EDT).

Customer Signature

Date

Dealer Signature

Date