

# Multi-Point Inspection Checklist

RO# 6034583

Customer Name INVENTORY: 968130

Advisor Name JAKE BACHTELL

Technician Name JACOB BLAKEMAN

Created on 11/24/2025 8:15 AM

Printed on 11/24/2025

Did your Service Advisor review the results of this multi-point inspection checklist with you?



Checked and OK at this time



May Require Future Attention



Requires immediate attention

## Maintenance Service

- Cold Engine start-up
- Engine operation warm-up
- Engine at normal operating temperature
- Brake and parking operation fb 9mm rb 8mm
- Active seat belt test
- Clutch and transmission operations
- Overdrive operation
- Transfer case operation (4-wheel drive only)
- Steering operation and off center
- Front end alignment
- Tilt steering wheel operation
- Windshield wiper and washer operation at all speeds, wiper blade condition
- Speedometer and odometer operation
- Cruise Control operation, including resume
- Heater and air condition operation
- Abnormal noises and vibrations
- Squeaks and rattles
- Frame Check
- Body surface, lower body, and upper body damage requiring body shop repair
- Tire defects and damage, 5/32 ft 6/32 rt 6/32
- Drive shaft, joints, CV's and boots
- Struts/shock absorbers, leaks and wear
- Exhaust system leaks and damage, including catalytic converter
- Fuel, oil, coolant, or other fluid leaks
- Perform emissions test and/or state inspection if required
- Under hood labels and decals
- Air filter and In-Cabin Air Filter equipped Found the engine air filter 
- Battery cables and mount
- Coolant level and test
- Under hood fluid levels, including transmission and transfer case fluids
- Drive belts and hoses
- Air conditioning levels, check at sight glass
- Warning lights (including air bag) gauges & horn
- Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light
- Inside and outside rearview mirror operation, adjustment, and condition
- Glass free of cracks, starts and large chips
- Dome, courtesy, map and sun visor lights and lighters and power ports

- Window operation
- Sunroof or convertible top operation
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position
- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician 	Date
Service Manager	Date 11-24-25
Used Car Manager	Date
Customer	Date

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2025	BUICK	ENVISION
Vehicle Identification Number	Color	
LRBFZKE40SD040001	SILVER	

AWD 4DR PREFE	18876	18876
JAKE BACHTTELL		

INVENTORY: 968130

#1 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 329/9 1.00hrs @ 169.95	169.95	I
#2 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 329/9 0.40hrs @ 184.25 19432337 : N-OIL (08800-BOPCK) 6@8.92 12735608 : SL-N-FILTER (01836-BCKT) 1@8.00	73.70 53.52 8.00	I
#3 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 329/9 * 1.50hrs	159.95	I
#4 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 329/9 * 0.90hrs	59.95	I
#6 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00 Work performed by Tech 329/9 * 0.10hrs 84215222 : SL-N-ELEMENT (03410-BCK) 1@29.95	10.00 29.95	I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	473.55				
PARTS	91.47				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS	595.01				



This report provided free of charge by:

**Deery Brothers**  
 200 S Gear Ave  
 West Burlington, IA 52655  
 319-271-8758

★ **4.6 / 5.0**  
 144 Verified Reviews

♥ **102**  
 Customer Favorites



## Vehicle History Report™

US \$44.99

**2025 BUICK ENVISION PREFERRED**

VIN: LRBZKE40SD040001  
 4 DOOR WAGON/SPORT UTILITY  
 2.0L I4 GASOLINE  
 ALL WHEEL DRIVE  
 Original Window Sticker  
 This CARFAX Report Provided by:  
**Deery Brothers**  
 ★ 4.6 / 5.0  
 144 Verified Reviews  
 ♥ 102 Customer Favorites

-  No accidents or damage reported to CARFAX
-  2 Service history records
-  CARFAX 1-Owner vehicle
-  Rental vehicle
-  Last owned in New York
-  **18,876** Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 11/26/25 at 5:53:15 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



### Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
 Oil	✓ Oil and filter changed	11/25/2025
 Tires	✓ Tires rotated	07/02/2025



This car has been recently serviced. That's a good thing!

 <b>Additional History</b> Not all accidents / issues are reported to CARFAX	<b>Owner 1</b>
<b>Total Loss</b> No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Structural Damage</b> No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Manufacturer Recall</b> No open recalls reported to CARFAX. Check for open recalls on GM vehicles at recalls.gm.com.	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have 28 months or 17,124 miles remaining. Confirm with dealer or vehicle manufacturer.	<input checked="" type="checkbox"/> Warranty Active

 <b>Title History</b> CARFAX guarantees the information in this section	<b>Owner 1</b>
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
 <b>GUARANTEED</b> - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. <a href="#">View Terms</a>   <a href="#">View Certificate</a>	

 <b>Ownership History</b> The number of owners is estimated	<b>Owner 1</b>
Year purchased	2025
Type of owner	Rental
Estimated length of ownership	6 months
Owned in the following states/provinces	New York, New Jersey
<div style="text-align: center;">  </div>	

Estimated miles driven per year	
Last reported odometer reading	18,876

**CARFAX** Detailed History



**Owner 1**

Purchased: 2025

Rental Vehicle

Date	Mileage	Source	Comments
Not Reported		General Motors	<b>Original Window Sticker</b> 
03/04/2025		New York Motor Vehicle Dept.	<b>Registration issued or renewed</b> - Passed safety inspection
03/04/2025		New Jersey Motor Vehicle Dept. Newark, NJ	<b>Titled or registered as rental vehicle</b>
03/05/2025	6	New York Inspection Station	<b>Passed safety inspection</b>
03/17/2025		New York Motor Vehicle Dept. Newark, NJ	<b>Title issued or updated</b> - First owner reported - Loan or lien reported
07/02/2025	10,749	Classic Buick GMC Inc Painesville, OH 440-942-6400 driveclassic.com ★ <b>4.8 / 5.0</b> 363 Verified Reviews ❤️ <b>4,263</b> Customer Favorites	 <b>Vehicle serviced</b> - Maintenance inspection completed - Engine serviced - Maintenance reminder reset - Oil and filter changed - Oil consumption test performed - Tires rotated
09/26/2025		Online Listing	<b>Vehicle offered for sale</b>
11/23/2025	18,651	Deery Brothers West Burlington, IA 319-752-6000 deerybrothers.com/ ★ <b>4.6 / 5.0</b> 144 Verified Reviews ❤️ <b>102</b> Customer Favorites	<b>Vehicle offered for sale</b>

11/25/2025 18,876

Deery Brothers  
West Burlington, IA  
319-752-6000  
deerybrothers.com/

★ 4.6 / 5.0

144 Verified Reviews

♥ 102 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed
- Air filter replaced
- Oil and filter changed



Looks like this dealer serviced the car in order to prepare it for sale. That's a good thing!

11/26/2025

CARFAX Car Care

**Manufacturer Recommended Maintenance Schedules**



Get this vehicle's maintenance schedule, service history and recall alerts at [carfax.com/service](https://www.carfax.com/service).

Have Questions? Please visit our Help Center at [www.carfax.com](https://www.carfax.com).



**Glossary**

**First Owner**

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

**Ownership History**

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

**Rental**

Vehicle was registered by a rental agency.

**Title Issued**

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



[facebook.com/CARFAX](https://www.facebook.com/CARFAX)



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

SYSTEMATIC RETRIEVAL OF THE CONTENT OR OTHER DATA FROM THIS SITE TO CREATE OR COMPILE, DIRECTLY OR INDIRECTLY, IN WHOLE OR IN PART, A COLLECTION, COMPILATION, DATABASE OR DIRECTORY WITHOUT THE EXPRESS WRITTEN PERMISSION OF CARFAX IS STRICTLY PROHIBITED. BY USING THE CARFAX VEHICLE HISTORY REPORT YOU AGREE TO THE CARFAX TERMS OF USE AND PRIVACY STATEMENT.

© 2025 CARFAX, Inc., part of S&P Global. All rights reserved.  
11/26/25 5:53:15 PM (CST)