

# Multi-Point Inspection Checklist

RO# 6037499

Did your Service Advisor review the results of this multi-point inspection checklist with you?

Customer Name INVENTORY: 966802

Advisor Name AMANDA KEPHART

Technician Name Dalton Berry

Created on 3/2/2026 3:19 PM

Printed on 3/2/2026

 Checked and OK at this time

 May Require Future Attention

 Requires immediate attention

## Maintenance Service

-   Cold Engine start-up Pass
-   Engine operation warm-up Pass
-   Engine at normal operating temperature Pass
-   Brake and parking operation Pass
-   Active seat belt test Pass
-   Clutch and transmission operations Pass
-   Overdrive operation Pass
-   Transfer case operation (4-wheel drive only) Pass
-   Steering operation and off center Pass
-   Front end alignment Pass
-   Tilt steering wheel operation Pass
-   Windshield wiper and washer operation at all speeds, wiper blade condition Pass
-   Speedometer and odometer operation Pass
-   Cruise Control operation, including resume Pass
-   Heater and air condition operation Pass
-   Abnormal noises and vibrations Pass
-   Squeaks and rattles Pass
-   Frame Check Pass
-   Body surface, lower body, and upper body damage requiring body shop repair Pass
-   Tire defects and damage, 5/32 7/32 all
-   Drive shaft, joints, CV's and boots Pass
-   Struts/shock absorbers, leaks and wear Pass
-   Exhaust system leaks and damage, including catalytic converter Pass
-   Fuel, oil, coolant, or other fluid leaks Pass
-   Perform emissions test and/or state inspection if required Pass
-   Under hood labels and decals Pass
-   Air filter and In-Cabin Air Filter equipped Pass
-   Battery cables and mount Pass
-   Coolant level and test Pass
-   Under hood fluid levels, including transmission and transfer case fluids Pass
-   Drive belts and hoses Pass
-   Air conditioning levels, check at sight glass Pass
-   Warning lights (including air bag) gauges & horn Pass
-   Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light Pass
-   Inside and outside rearview mirror operation, adjustment, and condition Pass
-   Glass free of cracks, starts and large chips Caution small crack in windshield
-   Dome, courtesy, map and sun visor lights and lighters and power ports Pass

- Window operation Pass
- Sunroof or convertible top operation N/A
- Audio system and clock (set if required) Pass
- Factory -installed alarm system functional Pass
- Cigarette lighter operation, replace element if used Pass
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets Pass
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position Pass
- Seats and seat belt operation for every position Pass
- Rear defogger, check with test lights Pass
- Headlight aim Pass
- Trunk light and trunk trim appearance Pass
- Hood, trunk, and fuel filler door latch Pass
- Spare tire pressure, jack and tire wrench match vehicle and work properly Pass
- Wheel covers and caps Pass
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 6mm all
- Differential oil level Pass
- Engine oil and filter changed using genuine replacement parts Pass
- CHECK AND COMPLETE ALL OPEN RECALL Pass
- OTHER
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.
- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician \_\_\_\_\_ Date \_\_\_\_\_



Service Manager \_\_\_\_\_ Date \_\_\_\_\_

Used Car Manager \_\_\_\_\_ Date \_\_\_\_\_

Customer \_\_\_\_\_ Date \_\_\_\_\_



### Ford : EcoSport : 2021 : Front Wheel Drive ExpressAlign Total Alignment



• One or more values are not within specification. Tire wear, handling and safety problems may result.

# REPAIR ORDER - AUDIT COPY

DEERY BROTHERS  
200 S Gear Ave  
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
2021	FORD	ECOSPORT
Vehicle Identification Number		Color
MAJ3S2GE4MC407883		GRAY

SUV	50379	50379
AMANDA KEPHART		

INVENTORY: 966802

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:184.25 Work performed by Tech 256/ 0.40hrs @ 184.25 73.70 19419537 : N-OIL (08800-BOPCKT) 5@9.60 48.00 R85348MP : FILTER 1@9.65 9.65 new oil and filter	I	
#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:169.95 Work performed by Tech 256/ 1.00hrs @ 169.95 169.95 inspection complete	I	
#3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 256/ * 0.90hrs 99.00 balanced 4 wheels and rotated all psi 35	I	
#4 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 256/ * 1.50hrs 159.95 alignment complete	I	
#5 - RECALL: CHECK FOR OPEN RECALLS Corrected by NRF: NO RECALLS FOUND FOR VEHICLE AT THIS TIME. LRATE:172.39 Work performed by Tech 256/ 0.00hrs @	C	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	502.60				
PARTS	57.65				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	590.24				



This report provided free of charge by:

**Deery Brothers**  
200 S Gear Ave  
West Burlington, IA 52655  
319-271-8758

★ **4.6 / 5.0**  
154 Verified Reviews

♥ **101**  
Customer Favorites



### Vehicle History Report™

US \$44.99

#### 2021 FORD ECOSPORT SE

VIN: MAJ3S2GE4MC407883  
4 DOOR WAGON/SPORT UTILITY  
1.0L I3 F DOHC 12V GASOLINE  
FRONT WHEEL DRIVE  
Original Window Sticker  
This CARFAX Report Provided by:

**Deery Brothers**

★ **4.6 / 5.0**  
154 Verified Reviews  
♥ **101** Customer Favorites

✓ No accidents or damage reported to CARFAX

✂ 8 Service history records

📄 At least 1 open recall

1 CARFAX 1-Owner vehicle

🏠 Personal vehicle

📊 49,903 Last reported odometer reading



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/3/26 at 5:28:38 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.




#### Recent Service Highlights



Key services performed in the last 12 months


Service	Comments	Date
🛢 Oil	✓ Oil and filter changed	12/08/2025
🛞 Tires	✓ Tires rotated	12/08/2025



This car has been recently serviced. That's a good thing!

 <b>Additional History</b> Not all accidents / issues are reported to CARFAX	<b>Owner 1</b>
<b>Total Loss</b> No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Structural Damage</b> No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Manufacturer Recall</b> At least 1 manufacturer recall requires service. Locate an authorized Ford or Lincoln Mercury dealer or call 866-436-7332 to obtain more information about this recall.	Recall Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	<b>Warranty Expired</b>

 <b>Title History</b> CARFAX guarantees the information in this section	<b>Owner 1</b>
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
 <b>GUARANTEED</b> - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. <a href="#">View Terms</a>   <a href="#">View Certificate</a>	

 <b>Ownership History</b> The number of owners is estimated	<b>Owner 1</b>
Year purchased	2022
Type of owner	Personal
Estimated length of ownership	3 yrs. 10 mo.
Owned in the following states/provinces	Louisiana, Iowa
Estimated miles driven per year	13,778/yr

