

Multi-Point Inspection Checklist

RO# 6040037

Customer Name INVENTORY: 1290442

Advisor Name Jim Smith

Technician Name KADEN SCHMITZ

Created on 5/20/2026 10:09 AM

Printed on 5/20/2026

Did your Service Advisor review the results of this multi-point inspection checklist with you?

Checked and OK at this time
 May Require Future Attention
 Requires immediate attention

Maintenance Service

- | | | |
|-------------------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Cold Engine start-up |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Engine operation warm-up |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Engine at normal operating temperature |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Brake and parking operation |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Active seat belt test |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Clutch and transmission operations |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Overdrive operation |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Transfer case operation (4-wheel drive only) |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Steering operation and off center |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Front end alignment |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Tilt steering wheel operation |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Windshield wiper and washer operation at all speeds, wiper blade condition |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Speedometer and odometer operation |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Cruise Control operation, including resume |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Heater and air condition operation |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Abnormal noises and vibrations |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Squeaks and rattles |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Frame Check |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Body surface, lower body, and upper body damage requiring body shop repair |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Tire defects and damage, 5/32 <u>8 ALL</u> |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Drive shaft, joints, CV's and boots |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Struts/shock absorbers, leaks and wear |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Exhaust system leaks and damage, including catalytic converter |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Fuel, oil, coolant, or other fluid leaks |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Perform emissions test and/or state inspection if required |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Under hood labels and decals |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> Air filter and In-Cabin Air Filter equipped <u>Fail</u> |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Battery cables and mount |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Coolant level and test |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Under hood fluid levels, including transmission and transfer case fluids |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Drive belts and hoses |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Air conditioning levels, check at sight glass |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Warning lights (including air bag) gauges & horn |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Headlights, instrument lights, turn signals, flashers, brake lights, side marker lights, taillights, back up lights, and license plate light |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Inside and outside rearview mirror operation, adjustment, and condition |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Glass free of cracks, starts and large chips |
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | Dome , courtesy, map and sun visor lights and lighters and power ports |

- Window operation
- Sunroof or convertible top operation N/A
- Audio system and clock (set if required)
- Factory -installed alarm system functional
- Cigarette lighter operation, replace element if used
- Headliner, sun visors, dash pad, upholstery, console, cup holder, trim panels, carpets
- Truck bed, bed liner, tailgate, rear bumper N/A
- Door and door key/lock operation, including rear deck on wagons, child safety door locks are in normal (off) position

- Seats and seat belt operation for every position
- Rear defogger, check with test lights
- Headlight aim
- Trunk light and trunk trim appearance
- Hood, trunk, and fuel filler door latch
- Spare tire pressure, jack and tire wrench match vehicle and work properly
- Wheel covers and caps
- Pull four wheels and check brakes for minimum 50% remaining wear on pads/shoes. inspect rotors/drums for minimum thickness 9MM
- Differential oil level
- Engine oil and filter changed using genuine replacement parts
- CHECK AND COMPLETE ALL OPEN RECALL
- OTHER Airbox Assembly
- Deery Brothers has made every effort to inspect this vehicle and inform the customer of the condition of this vehicle.

- With the complexity of the modern automobile, no one can foresee what may happen to it at any time.
- Deery Brothers makes no warranty, promise or guarantee that this inspection has caught every flaw that exists.
- Deery Brothers welcomes a customers' request to have their own mechanic inspect this vehicle prior to purchase.
- Customer Acknowledgement:

Technician	Date
Service Manager	Date 5-20-26
Used Car Manager	Date 5/20/26
Customer	Date

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
200 S Gear Ave
West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	5/20/26	6040037/1
	R/O Close Date	Receipt No.
	5/21/26	Original
Body	Mileage In	Mileage Out
SUV	78416	78418
License Number	Service Advisor	
	Jim Smith	
Vehicle Identification Number	Account No.	Delivery Date
ZACCJBDB7JPG76040		
Color		In-Service Date
PURPLE		

INVENTORY: 1290442

#1 - 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS Corrected by 1: CHANGE ENGINE OIL AND OIL FILTER LUBE CHASSIS FILL ALL FLUID LEVELS LRATE:195.58 Work performed by Tech 847/8 0.40hrs @ 195.57 78.23 19432337 : N-OIL (08800-BOPCK) 6@9.60 57.60 12737085 : SL-N-FILTER (01836-BOPCKT) 1@6.95 6.95 PERFORMED SERVICE	I	
#2 - 4: 56 POINT INSPECTION Corrected by 4: 56 POINT INSPECTION LRATE:178.95 Work performed by Tech 847/8 1.00hrs @ 178.95 178.95 PERFORMED SERVICE	I	
#3 - GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE Corrected by GM24D: ELECTRONIC WHEEL BALANCE AND ROTATE LRATE:.00 Work performed by Tech 847/8 * 0.90hrs 99.00 PERFORMED SERVICE	I	
#4 - ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . Corrected by ALIGN: COMPUTERIZED ALIGNMENT SERVICE . INCLUDES SETTING CASTER AND CAMBER AND TOE IF ADJUSTABLE. DOES NOT INCLUDE REPLACEMENT OF DAMAGED OR RUSTED COMPONENTS AND OR PART REPLACEMENT . LRATE:.00 Work performed by Tech 847/8 * 1.50hrs 159.95 PERFORMED ALIGNMENT	I	
#5 - RECALL: CHECK FOR OPEN RECALLS	I	
#6 * AF: REPLACED ENGINE AIR FILTER *ENGINE AIR FILTER REPLACEMENT Corrected by AF: REPLACED ENGINE AIR FILTER LRATE:.00	I	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

DEERY BROTHERS
 200 S Gear Ave
 West Burlington, IA 52655

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
SUV	78416	78418
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date
	Jim Smith	

Year	Make	Model
2018	JEEP	RENEGADE
Vehicle Identification Number		Color
ZACCJBDB7JPG76040		PURPLE

INVENTORY: 1290442

Work performed by Tech 847/8 * 0.10hrs	12.00	
SA12066 : AIR FILTER 1@29.95	29.95	
REPLACED FILTER		

#7 * ICF: REPLACED IN CABIN AIR FILTER *CABIN AIR FILTER REPLACEMENT		I
Corrected by ICF: REPLACED IN CABIN AIR FILTER LRATE:.00		
Work performed by Tech 847/8 * 0.10hrs	12.00	
CAF90168P : CABIN FILTER 1@49.95	49.95	
CHANGED FILTER		

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	540.13				
PARTS	144.45				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	29.99				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	714.57				

This report provided free of charge by:

Deery Brothers
200 S Gear Ave
West Burlington, IA 52655
319-271-8758

2025 TOP-RATED DEALER

★ **4.6 / 5.0**
170 Verified Reviews

♥ **1,214**

Customer Favorites



Report

US \$44.99

2018 Jeep Renegade Limited

78,416 mi | VIN: ZACCJBDB7JPG76040 |

4 Door Wagon/Sport Utility | 2.4L I4 F SOHC 16V | Gasoline | Front wheel drive w/ 4X4

CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION



ACCIDENT Vehicle Not Damaged

FAIR VALUE
\$14,560 CARFAX Value



🔧 13 Service History Records

👤 3 Previous Owners

🚗 Types of Owners: Rental, Personal

🌍 Last Owned in Iowa

📄 32 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/20/26 at 4:51:18 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1

04/08/2021

Accident reported

- Involving right rear impact with another motor vehicle
- Vehicle was not damaged
- Airbags did not deploy

CARFAX History-Based Value Report

\$14,560

CARFAX Value

FAIR VALUE



What makes this vehicle a fair value?

↑ 🛠️ Service History

↓ 🚗 Non-Personal Vehicle

CARFAX Additional History Not all accidents / issues are reported to CARFAX	Owner 1	Owner 2	Owner 3
Total Loss No total loss reported to CARFAX.	✔ No Issues Reported	✔ No Issues Reported	✔ No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	✔ No Issues Reported	✔ No Issues Reported	✔ No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	✔ No Issues Reported	✔ No Issues Reported	✔ No Issues Reported
Odometer Check No indication of an odometer rollback.	✔ No Issues Indicated	✔ No Issues Indicated	✔ No Issues Indicated
Accident / Damage Accident reported: 04/08/2021.	✔ No Issues Reported	Vehicle Not Damaged	No New Issues Reported
Manufacturer Recall No open recalls reported to CARFAX.	✔ No Recalls Reported	✔ No Recalls Reported	✔ No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired	Warranty Expired

CARFAX Title History CARFAX guarantees the information in this section	Owner 1	Owner 2	Owner 3
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	✔ Guaranteed No Problem	✔ Guaranteed No Problem	✔ Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	✔ Guaranteed No Problem	✔ Guaranteed No Problem	✔ Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

CARFAX Ownership History The number of owners is estimated	Owner 1	Owner 2	Owner 3
Year purchased	2018	2019	2023
Type of owner	Rental	Personal	Personal
Estimated length of ownership	9 months	4 yrs. 6 mo.	2 yrs. 8 mo.
Owned in the following states/provinces	Oklahoma, Illinois	Illinois, Iowa	Iowa
Estimated miles driven per year	--	10,680/yr	2,024/yr
Last reported odometer reading	26,408	72,877	78,416

CARFAX Detailed History			
Owner 1 Purchased: 2018			Rental Vehicle
Date	Mileage	Source	Comments
Not Reported		FCA US LLC	Original Window Sticker 
02/28/2018		Oklahoma	Vehicle purchase reported